

NANCY KING

BOOKKEEPING SERVICE BOX 385 @ 300 BOOKER BLDG. ARTESIA, NEW MEXICO 88210

December 21, 1979


TAX SERVICE PHONE 746-6107





Mr. Ramey Energy and Minerals Department P. O. Box 2088 Santa Fe, New Mexico 87501

> Re: R. Q. Silverthorne Kenwood No. 6



Dear Mr. Ramey:

The Order of Division granting Mr. Silverthorne approval to drill the above referenced well at a location <u>1310' from South line</u>, 1310' from West line, Section 30, T 18S, R <u>31E</u>, this location fell directly under an electric power line and it is necessary to move the well to a point <u>1100'</u> from the South and West lines of this section.

With this letter, we are requesting administrative approval for this unorthodox location.

Yours very truly,

R. Q. Silverthorne

aner Nancy King

Agent

NK/bj

cc R.Q. Silverthorne

e w KENWOOD LEASE RQ. SILVERTHORNE RJOE 420 VELT-SECONDARY SS л^ь О PJIE 11001 1310 275 ' * 0-1220 (ES) 480 VOLT. SECONDARY 544 б . TO CORIA PHOTO COPY 411 1 1980 CONSCRIMINON DIVISION Οį 12 30 -1 NOV 1 5 1973 R. Q. MENIALWRIE LINE ARE FROM MAR MAD PRIMPRY AND Second. Acturel mensures Nore: Distince to SCALE 1"= 500' JCACED . ==/



STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION

December 28, 1979

BRUCE KING GOVERNOA LARRY KEHOE BECRETARY

> Nancy King P. O. Box 385 Artesia, New Mexico 88210

OIL CONSTRUATION DIVISION

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE, NEW MEXICO 87501 (505) 827-2434

Re: Application for Non-Standard Location: R. Q. Silverthorne Kenwood No. 6, 1100' FSL and 1100'

> FWL of Sec. 30, T-18-S, R-31-E, Eddy County

We may not process the subject application for non-standard location until the required information or plats checked below (is) (are) submitted.

X A plat must be submitted clearly showing the ownership of the offsetting leases.

 $-\frac{X}{X}$ A statement must be submitted that offset owners have been notified of the application by certified mail.

x A plat must be submitted fully identifying the topography necessitating the non-standard location.

 \square

2

Other:

R. L. STAMETS Technical Support Chief

RLS/dr

Please refer to Case No. 6696, The offsetting leases are owned by R. Q. Silverthorne. Plat item No. 3 enclosed.

Maney