

TEXAS ROSE PETROLEUM, INC.

16970 DALLAS PARKWAY SUITE 702 DALLAS, TEXAS 75248 (214) 931-3722

May 29, 1985

New Mexico Oil Conservation 1000 Rio Brazos Rd. Aztec, New Mexico 87410

Gentlemen:

This letter is being written as an application for exemption of Rule 104 for an unorthodox location. The well is Well #2 in the El Poso Ranch. This well has been accepted as an unorthodox location but was stipulated as being drilled to the Dakota formation. The well, however, was only drilled to the Gallup.

Therefore, an additional request is being made for exemption of Rule 104 for an unorthodox location on Well #2, in the Gallup formation. The reason for this unorthodox location is that the topography of the area makes it impossible to drill a standard well.

Thank you and please forward any paperwork to my attention.

, er Trans

Best Regards, Matthew J. Butgess

Texas Rose Petroleum, Inc.

MB/kw

÷.

1985 OIL CONSERVATION DIVISION SANTA FE

STATE OF NEW MEXICO

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 37501

Form C-102 Revised 10-1-78

•

		All distances	must be from the outer be	undaries of the Secti	on.	
perator			Lease			Well No.
TEXAS ROSE PETROLEUM			Range	EL POSO RANCH		2
init Letter	Section	Township 28N	1 -	County	ARRIBA	2 11
ctual Footage Loca		JON	IE	I IEIC	MRRIBA	
/ 10		Se Al	2/10		illes L	
618 (eet from the South III Ground Level Elev. Producing Formation			line and 0410	feet from the	West	line Dedicated Acreage:
1 -		Mancas	12001		'	da
			I		1	40 Acres
1. Outline the	e acreage dedic	cated to the su	bject well by colore	l pencil or hachur	e marks on the	plat below.
interest an	d royalty).				-	reof (both as to workin
	mmunitization,	unitization, for	snip is dedicated to ce-pooling. etc? ?' type of consolidati		interests of a	all owne rs been cònsoli
			-		een consolidat	ed. (Use reverse side o
						unitization, unitization pproved by the Division
	1			······································		CERTIFICATION
			1			
	1		-		I hereby cer	tify that the information con-
	I				 tained herei 	n is true and complete to the
	1				best of my k	nowledge and belief.
	1					
	1		· · · ·			
		P	Prepared by Davia For reference on	<u> </u>	Name	
	1		for reference on	14.		
	1		1		Position	
	1		1			
		[Company	
	1		1			
	1				'Date	
			B' East of Star 40 oil.		l hereby ce	rtify that the well location
	1		last will		shown on thi	s plat was plotted from field
			a Fundlo cil. 1		notes of act	ual surveys made by me a
	1	10	Sta 40		under my sup	pervision, and that the same
	l	'	jor		is true and	correct to the best of my
	1		<i>i</i> 1		knowledge ar	nd belief.
	- ±.m.m.m		_ _			
	Ŧ		•		1	
	Ŧ	. e	•		Date Surveyed	
<i></i>	, Ē	4 4	1 1			
24/8					Registered Pm	lessional Engineer
	4	T \$	l i		and/or Land Su	•
	Ŧ.	618'	I		1	
	Ī	e e	1			
	<u> </u>				Certificate No.	

NSL - 1996



STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD 2000 RIO BRAZOS ROAD 2000 RIO BRAZOS ROAD 2000 ROAD 200 OIL CONSERVATION DIVISION BOX 2088 SANTA FE, NEW MEXICO 87501. DATE 4-8 Proposed MC RE: 1.1S10M Proposed DHC Proposed NSL Proposed SWD Proposed WFX Proposed PMX Gentlemen: I have examined the application dated N-28N-1E for the 195 la wa #2 0 Unit. S-T-R Operat and Well ease and my recommendations are as follows: Norv-C .

Yours truly,

e.l

Ph. 505-622-1299

By DRC

2709 Resolana Dr. Roswell, NM 88201



JERRY W. LONG CONSULTANT

February 26, 1985

UNderey naled Mancos Oil Pool 40 - Ares -Ded. Areage - SE14 SWY

NS6-1996

DIRECTOR NEW MEXICO OIL CONSERVATION DIVISION P. O. Box 2088

Santa Fe, New Mexico 87501

618 FSL Section 14, 2418 FWL - JAN, RIE.

Re: Non-Standard Location TEXAS ROSE PETROLEUM, INC. No.2 El Poso Ranch Unit N, Sec.14, T.28N., R.1E. (Projected Survey)

Gentlemen:

Texas Rose Petroleum, Inc. is an Out-of-State corporation, without prior experience in drilling in New Mexico. Referenced well was inadvertently drilled by Texas Rose Petroleum, Inc., with the understanding that the well had been permitted by the previous owner of the fee oil and gas lease. In order to correct this deficiency, the operator has engaged me to obtain record approval for drilling of the well.

Attached are copies of C-101 and C-102 which I have filed with your Aztec Office. As indicated by the C-102, the well is located 222' from a subdivision line, instead of the minimum 330'. The well was drilled at a non-standard location because of the rugged terrain.

It is respectfully requested that administration approval be granted for an exception to Rule 104(B) for topographic reason. Also attached is a contour map indicating the extreme topography where the standard location should be and a map indicting that all offset drilling units are under lease to Texas Rose Petroleum, Inc.

Reports advising of subsequent operations will be filed as soon as possible. Your assistance in correcting this deficiency is greatly appreciated.

Sincerely yours, JERRY'W. LONG


Agent for: TEXAS ROSE PETROLEUM, INC.

JWL/bl1

TEXAS ROSE PETROLEUM, INC.

No.2 El Poso Ranch. 618'FSL 2418'FWL Sec.14-28N-1E Rio Arriba County, N.M.

LEASE OWNERSHIP



Jicarilla

