



NOTES "MW-XX" - Monitoring Wells Locations
 "RW-XX" - Recovery Well Locations
 "P" - Piezometer
 --- Denotes Under Ground Pipe-Way.
 --- Denotes Above Ground Pipe-Way.
 --- Denotes Slurry Barrier Wall

"CW" - Collection Well Locations
 "OW" - Observation Well Locations
 "SW" - Sump Well Locations

NO.	REVISION
8	Revised To Indicate Tanks 24 & 25 Addition.
7	Observation, & Collection Wells Added As Per Enviro. Dept. Mark-Ups.
6	Updated To Indicate Changes As Per Enviro. Dept. Red-Line Mark-Ups.
5	Updated To Indicate Changes As Per Enviro. Dept. Red-Line Mark-Ups.
4	Updated To Indicate Changes As Per Enviro. Dept. Red-Line Mark-Ups.
10	Revised As Per Red-Line Mark-Ups From 'C. Hurtado' Enviro. Dept.
9	Revised To Indicate "SW" or Sump Well Locations.
1	Updated As Per Environmental Dept. Mark Up

DATE	BY	DATE	BY	DATE	BY
3/06	NHB	12/04	NHB	7/05	NHB
7/05	NHB	3/05	NHB	2/04	NHB
7/07	NHB	5/06	NHB		

SCALE As Noted
 DRAWN BY NHB
 INITIAL CHK.
 FINAL CHK.
 ENGR.
 APPR. BY
 DATE 8/29/02

GIANT
 REFINING CO.
 BLOOMFIELD REFINERY
 BLOOMFIELD NEW MEXICO
 DWG. NO. D-000-900-023
 REV. 10

Giant Bloomfield Refinery
 Area Plot Plan
 Recovery Well & Monitoring
 Well Locations