

District I 1625 N. French Dr., Hobbs, NM 88240
District II 1301 W. Grand Ave., Artesia, NM 88210
District III 1000 Rio Brazos Rd., Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

WELL API NO. 30-025-03428
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil & Gas Lease No. B-1399
7. Lease Name or Unit Agreement Name: SHELL STATE
7. Well No. 8
8. Pool name or Wildcat WILSON YATES 7 RVRS ASSOC.
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3689 DF

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [] Other WATER SUPPLY
2. Name of Operator HAL J. RASMUSSEN OPERATING, INC.
3. Address of Operator 550 W. TEXAS, SUITE 200, MIDLAND, TEXAS 79701
4. Well Location Unit Letter C : 660 feet from the NORTH line and 1907 feet from the WEST line Section 7 Township 21S Range 35E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [X] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] MULTIPLE COMPLETION [] OTHER []
SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [] PLUG AND ABANDONMENT [] CASING TEST AND CEMENT JOB [] OTHER []

THE COMMISSION MUST BE NOTICED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR SUCH TO BE APPROVED.

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Subject well has CIBP @ EST 3600'. Calc Top of Cement @ 1500' & has perms 1070'-1090' (Santa Rosa)

Propose to P&A as follows:

- 1. Tag CIBP @ 3600' + dump bail 35' cement plug (Bottom)
2. 25 sx cement plug 1560' - 1700' Tag (Top Salt @1842')
3. 45 sx cement 1090- 1020 Sqz perms 1070'-1090' - TAG
4. 100 sx cement 37'- 137' Perf @ 137' and Sqz & Tag (Surface Shoe)
5. 10 sx surface plug w/ regulation marker

BEFORE EXAMINER OIL CONSERVATION DIVISION
OCD EXHIBIT NO. 61
CASE NO. 12758-A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE [Signature] TITLE Agent DATE 10/31/01

Type or print name Michael P. Jobe Telephone No. 915-687-1664
(This space for State use)

APPROVED BY [Signature] TITLE ORIGINAL SIGNED BY GARY W. WINK DATE NOV 19 2001
Conditions of approval, if any: NATURAL SCIENCE MANAGER - 2

JC

h
dm