BEFORE EXAMINED CATANACH OIL CONSERVATION DIVISION

OCD EXHIBIT NO. 3

CASE NO: 1298/

## mit.3 Copupropriate

NOTIONS OF AFFROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-8

Name of Operator  CENTRAL RESOURCES, INC.  Address of Operator  Stoperator  Unit Lester F: 1980 Feet From The North  Line and 1650 Feet From The West Line  Socion  19 Township 25S Range 38E NMFM  Lea County  10 Elevation (Show whather DF, REB, RT, GR, atc.)  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PLUG AND ABANDON CHANGE PLANS  COMMENCE DRILLING OPNS.  CHANGE PLANS  COMMENCE DRILLING OPNS.  CHANGE TEST AND CEMENT JOB  OTHER: Change to T&A'd status  CHANGE PLANS  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast from bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary  Abandonment Expires  MATURE  MATURE  MATURE  CHANGE PLANS  1. Breathering Tech.  2. Breathering Tech.  Breathering Tech.  AND DATE  6/19/97  ADATE  CALIFER CASING  Breathering Tech.  Breathering Tech.  CHANGE PLANS  CASING TEST AND CEMENT JOB  AND ABANDONMENT  CASING TEST AND CEMENT JOB  ALTERING CASING  CHANGE PLANS  CASING TEST AND CEMENT JOB  ALTERING CASING  ALTERING CASING  CHANGE PLANS  CASING TEST AND CEMENT JOB  ALTERING CASING  C	Box 1900, Fobbs, NM 88240   2040 Pacheco St.   Santa Fe, NM 87505   Sa	Line
Simplicity   Sim	S. Indicate Type of Lease   TRICTITI   DRUB BREZOS Rd., ARISO, NM 57410   SAND BREZOS Rd., ARISO, NM 57410   SAND DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"   (FORM C-101) FOR SUCH PROPOSALS. TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"   (FORM C-101) FOR SUCH PROPOSALS.	Line
SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TOA DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM COID FOR SUCH PROPOSALS)  O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TOA DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM COID) FOR SUCH PROPOSALS  Type of Well:  WILL  OTHER SAIT WATER SOURCES, INC.  Address Objection CENTRAL RESOURCES, INC.  Address Objection CENTRAL RESOURCES, INC.  Address Objection Usia Later F: 1980 Fee From The NOTTH Line and 1650 Feet From The West Line Section 19 Township 25S Ramp 38E NAMPM Lea County Well Location  Usia Later F: 1980 Fee From The NOTTH Line and 1650 Feet From The West Line Section 19 Township 25S Ramp 38E NAMPM Lea County  TO Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS.  PULIC AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.  PULIC AND ABANDON POTABLE TO TAKE IT A STATE OF THE POPPOSAND COMMENCE DRILLING OPNS.  1. (ALTERING CASING COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  1. (ASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS.)  2. (ASING TEST AND CEMENT JOB COM	TRICTIII O RIO Brazos Rd, Aziec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVORI. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  ONL  ONL  ONL  ONL  ONL  ONL  ONL  ON	Line
Sauch is & Southern Residence No.  SUNDRY NOTICES AND REPORTS ON WELLS ONOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  OTHER SAIL WATER DAY  OTHER SAIL WATER DISPOSALS.  OTHER SAIL WATER DAY  OTHER SAIL WATER DISPOSALS.  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER SAIL WATER DISPOSALS.  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER SAIL WATER DISPOSALS.  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER SAIL WATER DISPOSALS.  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  CE PENNY FED. NCT-4  OTHER METERS  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  OTHER METERS  I. WAIL NO.  CE PENNY FED. NCT-4  II. WAIL NO.	SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  ONE OF PROPOSALS, TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  ONE OF PROPOSALS.)  OTHER Salt water disposal  Remain of Operator  CENTRAL RESOURCES, INC.  Address of Operator  CENTRAL RESOURCES, INC.  Address of Operator  Unit Letter F : 1980 Feet From The North Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMFM Lea  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  COMMENCE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMI CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PROPOSED OF THE TOTAL TOTAL TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PROPOSED OF THE TOTAL TEST AND CEMENT JOB COMME	_ Line
SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO ROLL OR TO DEFERE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  Type of Wall:  OND.  OND.  OND.  OTHER SAIT WATER disposal  North Common Copensor  CE PENNY FED. NOT-4  OND.  OTHER SAIT WATER disposal  A. Wall No.  2  Advantas of Opensor  CE PENNY FED. NOT-4  OND.  A. Wall No.  CE PENNY FED. NOT-4  OND.  CE PENNY FED. NOT-4  OND.  A. Wall No.  CE PENNY FED. NOT-4  OND.  CE PENNY FED. NOT-4  OND.  A. Wall No.  CE PENNY FED. NOT-4  OND.  CE PENNY FED. NOT-4  OND.  CE PENNY FED. NOT-4  OND.  A. Wall No.  CE PENNY FED. NOT-4  OND.  CE PENNY FE	SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'  (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  ONS  ONE  OFFIRE SAIT WATER disposal  Name of Operator  CE PENNY FED. NCT-4  OR PROPOSALS.)  Type of Well:  ONE  OR WELL  ONE  OFFIRE SAIT WATER disposal  R. Well No.  CE PENNY FED. NCT-4  OR PROPOSALS.)  1. Lease Name or Unit Agreement Name  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4  OR PROPOSALS.)  ONE PENNY FED. NCT-4  OR PROPOSALS.)  1. Lease Name or Unit Agreement Name  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4  OR PROPOSALS.)  1. Lease Name or Unit Agreement Name  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4  OR PROPOSALS.)  1. Lease Name or Unit Agreement Name  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4  OR PROPOSALS.)  1. Lease Name or Unit Agreement Name  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4  OR PROPOSALS.)  1. Lease Name or Unit Agreement Name  CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4   CE PENNY FED. NCT-4  OR PROPOSALS.)  CE PENNY FED. NCT-4   CE PENNY FED. NCT-4   CE PENNY FED. NCT-4   OR PROPOSALS.)  CE PENNY FED. NCT-4   CE PENNY FED. NCT-4	_ Line
O NOT DEFENENT ROR PODPOSALS TO DRILL ON TO DEEPEN OR PLUIS BACK TO A    The property of Wall	O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  OTHER Salt water disposal  CE PENNY FED. NCT-4  OTHER Salt water disposal  Resources, Inc.  Address of Operator  550 West Texas, Suite 430, Midland, TX 79701  Unit Letter F: 1980 Feet From The North  Unit Letter F: 1980 Feet From The North  Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMPM Lea  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  COMMENCE DISILING OPNS.  PLUG AND ABANDON  CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMEN	_ Line
DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM -101) FOR SUCH PROPOSALS.)  Type of Wall:    Wall	DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well: OIL WELL OTHER Salt water disposal  Name of Operator CENTRAL RESOURCES, INC.  Address of Operator 550 West Texas, Suite 430, Midland, TX 79701  Well Leation Unit Letter F: 1980 Feet From The North Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMFM Lea  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PORARILY ABANDON CHANGE PLANS CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMMENCE OF TEAM' d status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	_ Line
Type of Well:  Will   ONS   ONE   ONE    Will   ONE   OTHER   Salt water disposal    Well   OTHER   Salt water disposal    Well   Well No.    CEPENNY FED. NCT-4  Well No.    Address of Operator    CEPENNY FED. NCT-4  Well No.    Address of Operator    SUBSCIENT   Speech Same or Widest    SUBSCIENT   Speech Right    Well Losit Letter   F   1980   Feet From The   North    Unit Letter   F   1980   Feet From The   North    Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data    NOTICE OF INTENTION TO:    SUBSEQUENT REPORT OF:    FORM REMEDIAL WORK   PLUG AND ABANDON    CASING TEST AND CEMENT JOB    FOR ALTER CASING    CASING TEST AND CEMENT JOB    THER: Change to TGA'd status    OTHER: Change to TGA'd stat	Type of Well:  Office of Operator  CEPENNY FED. NCT-4  Office of Operator  CENTRAL RESOURCES, INC.  Address of Operator  550 West Texas, Suite 430, Midland, TX 79701  Unit Letter F: 1980 Feet From The North  Unit Letter F: 1980 Feet From The North  Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMPM Lea Completed Operation (Show whether DF, RKB, RT, GR, etc.)  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FORM REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONM CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AN	_ Line
Name of Operator  SERVELLE 103.  CENTRAL RESOURCES, INC.  Address of Operator  SERVELLE MESCURCES, INC.  Check Expropriate Morth North Line and 1650 Feet From The West Line  Socion 19 Township 25S Range 38E NMGM Lea County  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK ALTERING CASING COMMENCE DIFFLLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB MESCURCES CHARTHY ABANDON CHANGE PLANS OTHER. Change to T&A'd status  CHART CASING CHART AND CEMENT JOB MESCURCES CHARTHY ABANDON MENT COMMENCE DIFFLLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB MESCURCES CHARTHY ABANDON MENT COMMENCE DIFFLLING OPNS. THE CHARTHY ABANDON MENT COMMENCE DIFFLING OPNS. THE CHAR	OTHER Salt water disposal  Name of Operator  CENTRAL RESOURCES, INC.  Address of Operator  CENTRAL RESOURCES, INC.  2  Address of Operator  550 West Texas, Suite 430, Midland, TX 79701  Vell Location  Unit Letter F: 1980 Feet From The North  Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMPM Lea  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  PORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONM  CASING TEST AND CEMENT JOB C	_ Line
Name of Operator CENTRAL RESOURCES, INC.  2 Address of Operator S50 West Texas, Suite 430, Midland, TX 79701  3 Pool same or Wildcast Faringite Matrix South Power From The North Unit Lester F: 1980 Feet From The North Unit Lester F: 1980 Feet From The North Line and 1650 Feet From The West Line Society 19 Township 25S Range 38E NMTM Lea County  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: FORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: Change to T6A'd status  OTHER: Change to T6A'd status  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casting to 525 pst for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  ANDER  6/19/97  THIS Approval of Temporary Abandonment Expires  ANDER  6/19/97  ANDER  CASING TEST AND CEMENT JOB  Remedial Work Aller 1930  ANDER  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casting to 525 pst for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  ANDRE  6/19/97	Name of Operator  CENTRAL RESOURCES, INC.  Address of Operator  550 West Texas, Suite 430, Midland, TX 79701  Politication  Unit Letter F: 1980 Feet From The North Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMFM Lea C  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONM CASING TEST AND CEMENT JOB X  OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	_ Line
CENTRAL RESOURCES, INC.  Address of Operator  500 West Texas, Suite 430, Midland, TX 79701  9. Pool same or Wildest  550 West Texas, Suite 430, Midland, TX 79701  West Leaster  Unit Letter F : 1980 Feet From The North Line and 1650 Feet From The West Line  Section 19 Township 25S Range 38E NMFM Lea County  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOS CASING TEST AND CEMENT	Address of Operator  550 West Texas, Suite 430, Midland, TX 79701  Well Location  Unit Letter F: 1980 Feet From The North  Line and 1650 Feet From The West  Section 19 Township 258 Range 38E NMPM Lea  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  PORARILY ABANDON CHANGE PLANS CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONM  COR ALTER CASING CASING CHANGE PLANS CASING TEST AND CEMENT JOB  ER: Change to T&A'd status  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	_ Line
Section   19   Township   25S   Range   38E   NNTPM   Lea   County	Well Lossion  Unit Letter F: 1980 Feet From The North Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMPM Lea C  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  PORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB TOTHER:  Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datas, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	_ Line
Well Lester   F   1980   Feet From The   North   Line and   1650   Feet From The   West   Line	Well Location  Unit Letter F: 1980 Feet From The North Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMFM Lea C  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  PORARILY ABANDON CHANGE PLANS CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMED.  OR ALTER CASING CHANGE PLANS CHANGE TO TEA'd status  Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	_ Line
Unit Letter F: 1980 Feet From The North Line and 1650 Feet From The West Line  Section 19 Township 25S Rampe 38E NMPM Lea County  10. Elevation (Show whather DF, RKB, RT, GR, etc.)  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  FORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB THE CHANGE OF THE CHANGE	Unit Letter F: 1980 Feet From The North Line and 1650 Feet From The West  Section 19 Township 25S Range 38E NMPM Lea CO  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  PORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONM  LOR ALTER CASING CASING CASING TEST AND CEMENT JOB COMMENCE DRILLING OF TEAM of Status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  PORARILY ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE TO TAKE THE CHANGE TO THE CHANGE TO TAKE THE CHANGE TO THE CHANGE TO TAKE THE CHANGE TO THE CHANGE TO TAKE THE CHANGE THE	Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PLUG AND ABANDONM  CASING TEST AND CEMENT JOB  CASING TEST AND CEMENT JOB  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CHANGE TEST AND CEMENT JOB  CHANGE TO TEAT of States all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starring any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held 0K.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary / Williams w/ OCD.  This Approval of Temporary / Williams w/ OCD.	NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONM  LOR ALTER CASING CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONM  CASING TEST AND CEMENT JOB COMMENCE OF T&A'd status  OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	,,,,,
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starring any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held 0K.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary / Williams w/ OCD.  This Approval of Temporary / Williams w/ OCD.	NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  FORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONM  LOR ALTER CASING CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONM  CASING TEST AND CEMENT JOB COMMENCE OF T&A'd status  OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires O/W/Commendation above a true and complete to the best of my knowledge and belief.  THIS Engineering Tech.  DATE 6/19/97	FORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMIC CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMIC CASING TEST AND CEMENT JOB CASING TEST AND CEM	
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  THER: Change to T&A'd status  OTHER: Change to T&A'd status  OTHER: Change to T&A'd status  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary  Abandonment Expires  THE Engineering Tech.  DATE  OLE 570.0	COMMENCE DRILLING OPNS. PLUG AND ABANDONM  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  OTHER: Ch	
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  THER: Change to T&A'd status  OTHER: Change to T&A'd status  OTHER: Change to T&A'd status  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary  Abandonment Expires  THE Engineering Tech.  DATE  OLE 570.0	COMMENCE DRILLING OPNS. PLUG AND ABANDONM  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  OTHER: Change to T&A'd status  Commence Drilling OPNS. Plug and Abandonm  CASING TEST AND CEMENT JOB   OTHER: Change to T&A'd status  OTHER: Ch	
CASING TEST AND CEMENT JOB TO TEAT OF THE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Albandonment Expires  CASING TEST AND CEMENT JOB XX Approvacy of Temporary Albandonment Expires  This Approval of Temporary Albandonment Expires  OLIVIANTE  Engineering Tech.  DATE  OLIVIANTE  OLIVIAN	CASING TEST AND CEMENT JOB TO TEAT of Status  OTHER: Change to T&A'd status  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires // Ith/Lawner Complete to the best of my knowledge and belief.  Thus Engineering Tech.  DATE 6/19/97	Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	INT L
Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held 0K. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  This Approval of Temporary Abandonment Expires  The Engineering Tech.  DATE 6/19/97	Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
Describe Proposed or Completed Operations (Clearly state all personent details, and give personent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held 0K. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires	Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  This Approval of Temporary Abandonment Expires  The Engineering Tech.  DATE  6/19/97	1.) 6/11/97 moved on service rig. 2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
1.) 6/11/97 moved on service rig.  2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  This Approval of Temporary Abandonment Expires  The Engineering Tech.  DATE  6/19/97	<ol> <li>6/11/97 moved on service rig.</li> <li>Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"</li> </ol>	
2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires	2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8" internally plastic coated tubing. 3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  Olivination above at true and complete to the best of my knowledge and belief.  This Approval of Temporary Abandonment Expires  Olivination above at true and complete to the best of my knowledge and belief.  This Approval of Temporary Abandonment Expires  Olivination Date  Olivina	2.) Released and pulled out of hole w/ AD-1 5 1/2" packer laying down 102 jts 2 7/8"	
internally plastic coated tubing.  3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline.  4.) Dump bailed 35' cement (4 sacks) on top of plug.  5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires		
3.) 6/12/97 set cast iron bridge plug @ 3130' w/ wireline. 4.) Dump bailed 35' cement (4 sacks) on top of plug. 5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK. 6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  Olf 19/97	internally plastic coated tubing.	
5.) 6/14/97 tested casing to 525 psi for 30 mins. Held OK.  6.) Witnessed by Chris Williams w/ OCD.  This Approval of Temporary Abandonment Expires  This information above is true and complete to the best of my knowledge and belief.  HATURE  THE Engineering Tech.  DATE  6/19/97		
This Approval of Temporary Abandonment Expires  This information above at true and complete to the best of my knowledge and belief.  Engineering Tech.  DATE  O15 570 0		
This Approval of Temporary Abandonment Expires  This Engineering Tech.  DATE  1116 570.0		
Abandonment Expires 0/14/2002  The certify that the information above at true and complete to the best of my knowledge and belief.  Engineering Tech.  DATE 6/19/97	6.) Witnessed by Chris Williams w/ OCD.	
Abandonment Expires 0/14/2002  The certify that the information above at true and complete to the best of my knowledge and belief.  Engineering Tech.  DATE 6/19/97		a share a sa
reby certify that the information above at true and complete to the best of my knowledge and belief.  HATURE	This Approval of Temporary	
Engineering Tech.  DATE  6/19/97		A
Engineering Tech.  DATE  6/19/97		605
Engineering Tech.  DATE  6/19/97	Telly Certify that the information should be and appropriate to the heat of the legal of the legal of	10°C
DATE OLS 570 0		<b>め</b> て —
EORFRINTNAME Tricia Barnes TELEPHONE NO. 915-570-9	MATURE (Much)   MINIS   Brighteering lech.   DATE   6/19/9	
IBLESTICUE NU.	EOR PRINT NAME Tricia Barnes 915-	<u></u>
	IBLETTORE NO.	