



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968



In Reply Refer To:
3186
(3186.1)
Poker Lake Unit
NMNM71016X

APR 29 2021

Mr. Jim Pruitt
XTO Energy Inc.
Land Dept., Loc. 115
22777 Springwoods Village Pkwy.
Spring, TX 77389-1425

Re: Paying Well Determination
Poker Lake Unit 420H
SHL: SE $\frac{1}{4}$ SE $\frac{1}{4}$, Sec. 28, T.25S., R.31E. (Lease No. NMLC063136A)
BHL: NE $\frac{1}{4}$ NE $\frac{1}{4}$, Sec. 29, T.25S., R.31E. (Lease No. NMLC062140A)
Poker Lake Unit
Eddy County, New Mexico

Dear Mr. Pruitt:

We have determined that under existing conditions the Poker Lake Unit No. 420H well is **not** capable of producing unitized substances from the Delaware Formation in unit paying quantities. The well was completed in the Delaware Formation on October 17, 2012. Since the well was determined to be a nonpaying unit well, a communitization agreement should be submitted to the New Mexico State Office for approval.

If you have any questions, please call the undersigned at (307) 261-7685.

Sincerely,

/S/ J. David Chase

J. David Chase
Chief, Reservoir Management Group

cc: NMSO, Sheila Mallory
ONRR-RRM (email: leases.blm@onrr.gov)
New Mexico State Land Office, Scott Dawson
New Mexico Oil Conservation Division, Leonard Lowe



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968



In Reply Refer To:
3186
(3186.1)
Poker Lake Unit
NMNM71016X

APR 29 2021

Mr. Jim Pruitt
XTO Energy Inc.
Land Dept., Loc. 115
22777 Springwoods Village Pkwy.
Spring, TX 77389-1425

Re: Paying Well Determination
Poker Lake Unit 356H
SHL: NW $\frac{1}{4}$ SE $\frac{1}{4}$, Sec. 33, T.24S., R.31E. (Lease No. NMNM031382)
BHL: SE $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 3, T.25S., R.31E. (Lease No. NMNM030457)
Poker Lake Unit
Eddy County, New Mexico

Dear Mr. Pruitt:

We have determined that under existing conditions the Poker Lake Unit No. 356H well is **not** capable of producing unitized substances from the Delaware Formation in unit paying quantities. The well was completed in the Delaware Formation on November 2, 2012. Since the well was determined to be a nonpaying unit well, a communitization agreement should be submitted to the New Mexico State Office for approval.

If you have any questions, please call the undersigned at (307) 261-7685.

Sincerely,

/S/ J. David Chase

J. David Chase
Chief, Reservoir Management Group

cc: NMSO, Sheila Mallory
ONRR-RRM (email: leases.blm@onrr.gov)
New Mexico State Land Office, Scott Dawson
New Mexico Oil Conservation Division, Leonard Lowe

INTERIOR REGION 7 • UPPER COLORADO BASIN

COLORADO, NEW MEXICO, UTAH, WYOMING