



Case 417

Post Office Box 61229  
Houston, Texas 77208-1229

1111 Travis Street  
Houston, Texas 77002

Phone: (832) 839-4601  
ccreekmore@hilcorp.com

March 1, 2022

Bureau of Land Management  
Farmington Resource Area  
6251 College Blvd., Suite A  
Farmington, NM 87402

Commissioner of Public Lands  
State of New Mexico  
P. O. Box 1148  
Santa Fe, NM 87501-1148

Oil Conservation Division  
State of New Mexico  
1220 S. Saint Francis Drive  
Santa Fe, NM 87505

**2022 PLAN OF DEVELOPMENT  
FOR THE SAN JUAN 30-5 UNIT  
NO. 14-08-001-346  
RIO ARRIBA COUNTY, NEW MEXICO**

Pursuant to Section 10 of the San Juan 30-5 Unit Agreement, Hilcorp Energy Company ("Hilcorp"), as Unit Operator, hereby submits the proposed 2022 Plan of Development and Operations ("POD").

**I. PERIOD**

This plan will be effective from April 1, 2022 through March 31, 2023. The 2023 Plan will be submitted on or before March 1, 2023.

**II. 2021 PLAN REVIEW OF OPERATIONS**

**A. Production History:** During 2021, cumulative production from the San Juan 30-5 Unit was 8.61 BCF gas; 0.08 MBO oil; and 104.02 MBW produced water. Refer to Exhibit A attached for a listing of all wells in the San Juan 30-5 Unit.

**B. Participating Areas:** The Participating Areas currently established in the San Juan 30-5 Unit are as follows:

| FORMATION       | EXPANSION | EFFECTIVE DATE |
|-----------------|-----------|----------------|
| DAKOTA          | 018       | 01-AUG-00      |
| DAKOTA "A"      | 000       | 19-JUL-73      |
| FRUITLAND COAL  | 037       | 1-OCT-04       |
| MESAVERDE       | 037       | 01-NOV-12      |
| PICTURED CLIFFS | 004       | 01-DEC-05      |

**C. Drilling Program:** No drilling projects were undertaken by Hilcorp during the period of 2021.

**D. Workovers/Recompletion Program:** During 2021, Hilcorp undertook and completed the following projects:

| Well Name               | API        | Sec. | Twp  | Rng  | Formation | Work Description        |
|-------------------------|------------|------|------|------|-----------|-------------------------|
| San Juan 30-5 Unit 47   | 3003921070 | 17   | 030N | 005W | DK        | Tubing Repair           |
| San Juan 30-5 Unit 79   | 3003922705 | 5    | 030N | 005W | MV/DK     | Tubing Repair           |
| San Juan 30-5 Unit 104E | 3003926417 | 13   | 030N | 005W | MV/DK     | Tubing Repair           |
| San Juan 30-5 Unit 206  | 3003924691 | 18   | 030N | 005W | FC        | RPR                     |
| San Juan 30-5 Unit 220A | 3003929857 | 8    | 030N | 005W | FC        | Install Artificial Lift |
| San Juan 30-5 Unit 110  | 3003925284 | 16   | 030N | 005W | MV/DK     | Tubing Repair           |
| San Juan 30-5 Unit 217  | 3003924849 | 21   | 030N | 005W | FC        | RPR                     |
| San Juan 30-5 Unit 101  | 3003923147 | 35   | 030N | 005W | DK        | Tubing Repair           |
| San Juan 30-5 Unit 29A  | 3003923147 | 35   | 030N | 005W | DK        | Clean Out               |

**E. Facility Program:** The 2021 POD, as approved, provided for no additional facilities. No additional facility projects were undertaken by Hilcorp during this period.

**F. Plugging & Abandonment Program:** The 2021 POD, as approved, provided for no planned P&A activity. No additional projects were undertaken by Hilcorp during this period.

### III. 2022 PLAN OF DEVELOPMENT AND OPERATIONS

**A. Drilling Program:** Hilcorp does not anticipate drilling any new wells in the San Juan 30-5 Unit. New drill opportunities will be evaluated and executed as they arise.

**B. Workovers/Recompletion Program:** Hilcorp anticipates performing twenty-three (23) projects in the San Juan 30-5 Unit. Additional workovers, rate adds and optimization projects will be evaluated and executed as they arise.

| Well Name               | API        | Sec. | Twp  | Rng  | Formation                                            | Type                        |
|-------------------------|------------|------|------|------|------------------------------------------------------|-----------------------------|
| San Juan 30-5 Unit 104E | 3003926417 | 13   | 030N | 005W | Basin Dakota/Blanco<br>Mesaverde/Pictured Cliffs     | Recomplete PC and Trimingle |
| San Juan 30-5 Unit 88M  | 3003927087 | 18   | 030N | 005W | Basin Dakota/Blanco<br>Mesaverde/Pictured Cliffs     | Recomplete PC and Trimingle |
| San Juan 30-5 Unit 087  | 3003923157 | 05   | 030N | 005W | Basin Dakota/Blanco<br>Mesaverde                     | Recomplete MV and Commingle |
| San Juan 30-5 Unit 089  | 3003923178 | 19   | 030N | 005W | Basin Dakota/Blanco<br>Mesaverde                     | Recomplete MV and Commingle |
| San Juan 30-5 Unit 091  | 3003923168 | 25   | 030N | 005W | LJ Canyon Gallup/Basin<br>Dakota/Blanco<br>Mesaverde | Recomplete MV and Trimingle |
| San Juan 30-5 Unit 095  | 3003923128 | 28   | 030N | 005W | Basin Dakota/Blanco<br>Mesaverde                     | Recomplete MV and Commingle |
|                         |            |      |      |      |                                                      |                             |

San Juan 30-5 Unit  
2022 Plan of Development

|                         |            |    |      |      |                                                |                             |
|-------------------------|------------|----|------|------|------------------------------------------------|-----------------------------|
| San Juan 30-5 Unit 096  | 3003923179 | 28 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 097  | 3003923180 | 29 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 100  | 3003923175 | 34 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 101  | 3003923147 | 35 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 102  | 3003923176 | 34 | 030N | 005W | LJ Canyon Gallup/Basin Dakota/Blanco Mesaverde | Recomplete MV and Trimingle |
| San Juan 30-5 Unit 103  | 3003923223 | 03 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 220A | 3003929857 | 08 | 030N | 005W | Fruitland Coal                                 | Recomplete FC               |
| San Juan 30-5 Unit 239A | 3003929232 | 15 | 030N | 005W | Fruitland Coal                                 | Recomplete FC               |
| San Juan 30-5 Unit 240A | 3003929219 | 22 | 030N | 005W | Fruitland Coal                                 | Recomplete FC               |
| San Juan 30-5 Unit 268  | 3003926508 | 24 | 030N | 005W | Fruitland Coal                                 | Recomplete FC               |
| San Juan 30-5 Unit 29A  | 3003925707 | 14 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 51   | 3003922447 | 21 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 74   | 3003922754 | 34 | 030N | 005W | Blanco Mesaverde/Pictured Cliffs               | Recomplete PC and Commingle |
| San Juan 30-5 Unit 86   | 3003923148 | 35 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 92   | 3003923145 | 26 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Recomplete MV and Commingle |
| San Juan 30-5 Unit 73N  | 3003930374 | 10 | 030N | 005W | Basin Dakota/Blanco Mesaverde                  | Tubing Repair               |
| San Juan 30-5 Unit 264  | 3003926049 | 09 | 030N | 005W | Fruitland Coal                                 | Tubing Repair               |

**C. Facility Program:** Throughout 2022, Hilcorp will conduct routine repairs and replacement of facilities required to maintain and increase field production, including construction of additional gas lift lines and/or gas flow lines, expansion of production facilities (including electrical and piping upgrades), and construction of additional water disposal, injection or processing equipment.

**D. Plugging & Abandonment Program:** Hilcorp anticipates plugging and abandoning two (2) wells in the San Juan 30-5 Unit. Hilcorp will evaluate and implement additional P&A projects as they arise.

| Well Name               | API        | Sec | Twp  | Rng  | Formation | Type |
|-------------------------|------------|-----|------|------|-----------|------|
| San Juan 30-5 Unit 243A | 3003927805 | 15  | 030N | 005W | FRC       | P&A  |
| San Juan 30-5 Unit 49   | 3003921830 | 09  | 030N | 005W | MV/DK     | P&A  |

San Juan 30-5 Unit  
2022 Plan of Development

In accordance with Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (832) 839-4601 if there are any questions regarding this letter.

Sincerely,  
HILCORP ENERGY COMPANY



Chuck Creekmore,  
Division Landman

*cc: Working Interest Owners*

DUGAN PRODUCTION CORP  
ENDURING RESOURCES IV LLC  
HILCORP SAN JUAN, LP  
JABCO LLP  
JHPOOL RESOURCES LLC  
LANGDON D HARRISON TRUST  
LOGOS RESOURCES II LLC  
MAR OIL & GAS CORPORATION  
NAVATEX ENERGY LP  
PROVIDENCE MINERALS LLC  
RIO ARIBAGAS LTD  
RIO ARRIBA LIMITED PARTNERSHIP  
ROY G & OPAL BARTON SR REV TR  
RUTH ZIMMERMAN TRUST  
SAN JUAN BASIN PARTNERSHIP  
SCHALK DEVELOPMENT COMPANY  
SIMCOE, LCC  
THOMAS P TINNIN  
TINMIL A NM LLC

San Juan 30-5 Unit  
2022 Plan of Development

**SAN JUAN 30-5 UNIT  
2022 PLAN OF DEVELOPMENT APPROVALS**

\_\_\_\_\_  
**Bureau of Land Management**

\_\_\_\_\_  
**Date**

\_\_\_\_\_  
**New Mexico Oil Conservation Division**

\_\_\_\_\_  
**Date**

\_\_\_\_\_  
**New Mexico Commissioner of Public Lands**

\_\_\_\_\_  
**Date**



## San Juan 30-5 Unit Exhibit "A"

| API #      | WELL NAME             | POOL/FORMATION   | STATUS  | ST | COUNTY     | SEC | TWP  | RCE  | QTR  | OPERATOR               |
|------------|-----------------------|------------------|---------|----|------------|-----|------|------|------|------------------------|
| 3003930662 | San Juan 30-5 Un 001N | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 4   | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003930662 | San Juan 30-5 Un 001N | Basin Dakota     | Flowing | NM | Rio Arriba | 4   | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003930662 | San Juan 30-5 Un 001N | Basin Mancos     | Flowing | NM | Rio Arriba | 4   | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003921148 | San Juan 30-5 Un 002R | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 29  | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003907745 | San Juan 30-5 Un 004  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 35  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003907754 | San Juan 30-5 Un 007  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 29  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003907717 | San Juan 30-5 Un 009  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 32  | 030N | 032W | SWSW | Hilcorp Energy Company |
| 3003922710 | San Juan 30-5 Un 009A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 32  | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003930895 | San Juan 30-5 Un 009B | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 32  | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003930895 | San Juan 30-5 Un 009B | Basin Dakota     | Flowing | NM | Rio Arriba | 32  | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003907838 | San Juan 30-5 Un 010  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 18  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003918204 | San Juan 30-5 Un 011  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 23  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003907721 | San Juan 30-5 Un 012  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 31  | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003922729 | San Juan 30-5 Un 012A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 31  | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003907859 | San Juan 30-5 Un 013  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 16  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003907743 | San Juan 30-5 Un 014  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 31  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003922192 | San Juan 30-5 Un 014A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 31  | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003907812 | San Juan 30-5 Un 015  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 19  | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003907756 | San Juan 30-5 Un 016  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 26  | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003907918 | San Juan 30-5 Un 017  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 6   | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003907848 | San Juan 30-5 Un 019  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 18  | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003926040 | San Juan 30-5 Un 020A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 8   | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003926040 | San Juan 30-5 Un 020A | Basin Dakota     | Flowing | NM | Rio Arriba | 8   | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003930599 | San Juan 30-5 Un 020M | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 8   | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003930599 | San Juan 30-5 Un 020M | Basin Dakota     | Flowing | NM | Rio Arriba | 8   | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003930707 | San Juan 30-5 Un 020N | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 8   | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003930707 | San Juan 30-5 Un 020N | Basin Dakota     | Flowing | NM | Rio Arriba | 8   | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003926418 | San Juan 30-5 Un 021A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 24  | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003930717 | San Juan 30-5 Un 021M | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 24  | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003930717 | San Juan 30-5 Un 021M | Basin Dakota     | Flowing | NM | Rio Arriba | 24  | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003907849 | San Juan 30-5 Un 022A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 17  | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003925497 | San Juan 30-5 Un 022A | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 17  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003925497 | San Juan 30-5 Un 022A | Basin Dakota     | Flowing | NM | Rio Arriba | 17  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003930091 | San Juan 30-5 Un 022F | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 17  | 030N | 005W | NESE | Hilcorp Energy Company |
| 3003930091 | San Juan 30-5 Un 022F | Basin Dakota     | Flowing | NM | Rio Arriba | 17  | 030N | 005W | NESE | Hilcorp Energy Company |
| 3003930597 | San Juan 30-5 Un 022M | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 17  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003930597 | San Juan 30-5 Un 022M | Basin Dakota     | Flowing | NM | Rio Arriba | 17  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003907891 | San Juan 30-5 Un 023  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 7   | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003907836 | San Juan 30-5 Un 024  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 16  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003907835 | San Juan 30-5 Un 025  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 17  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003930128 | San Juan 30-5 Un 027F | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003930128 | San Juan 30-5 Un 027F | Basin Dakota     | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003925669 | San Juan 30-5 Un 027M | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003925669 | San Juan 30-5 Un 027M | Basin Dakota     | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003930875 | San Juan 30-5 Un 027N | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003930875 | San Juan 30-5 Un 027N | Basin Dakota     | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003907820 | San Juan 30-5 Un 028X | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 23  | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003907851 | San Juan 30-5 Un 029  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 14  | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003925707 | San Juan 30-5 Un 029A | Basin Dakota     | Flowing | NM | Rio Arriba | 14  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003926776 | San Juan 30-5 Un 029B | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 14  | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003926776 | San Juan 30-5 Un 029B | Basin Dakota     | Flowing | NM | Rio Arriba | 14  | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003926777 | San Juan 30-5 Un 029M | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 14  | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003926777 | San Juan 30-5 Un 029M | Basin Dakota     | Flowing | NM | Rio Arriba | 14  | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003907799 | San Juan 30-5 Un 030  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 21  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003907761 | San Juan 30-5 Un 031  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 27  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003907822 | San Juan 30-5 Un 033  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 20  | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003907778 | San Juan 30-5 Un 034  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 27  | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003907884 | San Juan 30-5 Un 035  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 7   | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003920524 | San Juan 30-5 Un 036  | Blanco-Mesaverde | Flowing | NM | Rio Arriba | 30  | 030N | 005W | SWSW | Hilcorp Energy Company |










|            |                       |                      |         |    |            |    |      |      |      |                        |
|------------|-----------------------|----------------------|---------|----|------------|----|------|------|------|------------------------|
| 3003930710 | San Juan 30-5 Un 100N | Basin Dakota         | Flowing | NM | Rio Arriba | 34 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003923147 | San Juan 30-5 Un 101  | Basin Dakota         | Flowing | NM | Rio Arriba | 35 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003923176 | San Juan 30-5 Un 102  | Lajara Canyon-Gallup | Flowing | NM | Rio Arriba | 34 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003923176 | San Juan 30-5 Un 102  | Basin Dakota         | Flowing | NM | Rio Arriba | 34 | 030N | 005W | NWSE | Hilcorp Energy Company |
| 3003923223 | San Juan 30-5 Un 103  | Basin Dakota         | Flowing | NM | Rio Arriba | 3  | 030N | 005W | NWSE | Hilcorp Energy Company |
| 3003923311 | San Juan 30-5 Un 104  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 13 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003923311 | San Juan 30-5 Un 104  | Basin Dakota         | Flowing | NM | Rio Arriba | 13 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003926417 | San Juan 30-5 Un 104E | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 13 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003926417 | San Juan 30-5 Un 104E | Basin Dakota         | Flowing | NM | Rio Arriba | 13 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003924266 | San Juan 30-5 Un 109  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 14 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003925706 | San Juan 30-5 Un 109A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 14 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003925706 | San Juan 30-5 Un 109A | Basin Dakota         | Flowing | NM | Rio Arriba | 14 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003925284 | San Juan 30-5 Un 110  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003925284 | San Juan 30-5 Un 110  | Basin Dakota         | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003930108 | San Juan 30-5 Un 110G | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003930108 | San Juan 30-5 Un 110G | Basin Dakota         | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003925658 | San Juan 30-5 Un 110M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003925658 | San Juan 30-5 Un 110M | Basin Dakota         | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003926158 | San Juan 30-5 Un 111  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 13 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003926158 | San Juan 30-5 Un 111  | Basin Dakota         | Flowing | NM | Rio Arriba | 13 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003930665 | San Juan 30-5 Un 111E | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 13 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003930665 | San Juan 30-5 Un 111E | Basin Dakota         | Flowing | NM | Rio Arriba | 13 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003926159 | San Juan 30-5 Un 112  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 12 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003926159 | San Juan 30-5 Un 112  | Basin Dakota         | Flowing | NM | Rio Arriba | 12 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003926366 | San Juan 30-5 Un 113  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 11 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003926366 | San Juan 30-5 Un 113  | Basin Dakota         | Flowing | NM | Rio Arriba | 11 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003924543 | San Juan 30-5 Un 201  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 19 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003927867 | San Juan 30-5 Un 201A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 19 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003924520 | San Juan 30-5 Un 202  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 6  | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003927765 | San Juan 30-5 Un 202A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 6  | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003927253 | San Juan 30-5 Un 203A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 7  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003924685 | San Juan 30-5 Un 204  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 7  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003924637 | San Juan 30-5 Un 205  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 7  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003924691 | San Juan 30-5 Un 206  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 18 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003924790 | San Juan 30-5 Un 207  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 18 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003924806 | San Juan 30-5 Un 208  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 19 | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003927854 | San Juan 30-5 Un 208A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 19 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003924692 | San Juan 30-5 Un 209  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 30 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003924971 | San Juan 30-5 Un 210  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 30 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003924720 | San Juan 30-5 Un 211  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 31 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003924721 | San Juan 30-5 Un 212  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 31 | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003927252 | San Juan 30-5 Un 213A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 5  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003926523 | San Juan 30-5 Un 213R | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 5  | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003926512 | San Juan 30-5 Un 214  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 5  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003927251 | San Juan 30-5 Un 214A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 5  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003924787 | San Juan 30-5 Un 215  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 8  | 030N | 005W | SESW | Hilcorp Energy Company |
| 3003927775 | San Juan 30-5 Un 215A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 8  | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003925318 | San Juan 30-5 Un 216R | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 20 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003924849 | San Juan 30-5 Un 217  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 21 | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003927809 | San Juan 30-5 Un 217A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 21 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003924788 | San Juan 30-5 Un 218  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 17 | 030N | 005W | SENW | Hilcorp Energy Company |
| 3003924901 | San Juan 30-5 Un 223  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 20 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003924902 | San Juan 30-5 Un 224  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 17 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003924965 | San Juan 30-5 Un 226  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 29 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003929210 | San Juan 30-5 Un 226A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 29 | 030N | 005W | NWSE | Hilcorp Energy Company |
| 3003924892 | San Juan 30-5 Un 227  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 28 | 030N | 032W | NENE | Hilcorp Energy Company |
| 3003925127 | San Juan 30-5 Un 228  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 28 | 030N | 032W | SWSW | Hilcorp Energy Company |
| 3003924979 | San Juan 30-5 Un 229  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 21 | 030N | 033W | NESW | Hilcorp Energy Company |
| 3003927773 | San Juan 30-5 Un 229A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 21 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003924903 | San Juan 30-5 Un 230  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 32 | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003925195 | San Juan 30-5 Un 231  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 32 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003925171 | San Juan 30-5 Un 233  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 33 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003925171 | San Juan 30-5 Un 234  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 22 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003925140 | San Juan 30-5 Un 235  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 27 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003925077 | San Juan 30-5 Un 236  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 27 | 030N | 005W | SWNW | Hilcorp Energy Company |

|            |                             |                      |         |    |            |    |      |      |      |                        |
|------------|-----------------------------|----------------------|---------|----|------------|----|------|------|------|------------------------|
| 3003927488 | San Juan 30-5 Un 237A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003925141 | San Juan 30-5 Un 238        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 34 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003925165 | San Juan 30-5 Un 239        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 15 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003925202 | San Juan 30-5 Un 240        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 22 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003925203 | San Juan 30-5 Un 241        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 23 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003929244 | San Juan 30-5 Un 241A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 23 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003925984 | San Juan 30-5 Un 243        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 15 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003925972 | San Juan 30-5 Un 249        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 23 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003929230 | San Juan 30-5 Un 249A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 23 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003925532 | San Juan 30-5 Un 255        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 14 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003929225 | San Juan 30-5 Un 255A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 14 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003925718 | San Juan 30-5 Un 257        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 11 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003929226 | San Juan 30-5 Un 257A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 11 | 030N | 005W | SENW | Hilcorp Energy Company |
| 3003925699 | San Juan 30-5 Un 258        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 14 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003929228 | San Juan 30-5 Un 258A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 14 | 030N | 005W | SENW | Hilcorp Energy Company |
| 3003925705 | San Juan 30-5 Un 259        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 13 | 030N | 005W | NWSE | Hilcorp Energy Company |
| 3003929227 | San Juan 30-5 Un 259A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 13 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003925981 | San Juan 30-5 Un 260        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 9  | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003927256 | San Juan 30-5 Un 260A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 9  | 030N | 005W | NWSE | Hilcorp Energy Company |
| 3003929224 | San Juan 30-5 Un 261A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 11 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003925959 | San Juan 30-5 Un 262        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 12 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003925982 | San Juan 30-5 Un 263        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 13 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003929223 | San Juan 30-5 Un 263A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 13 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003926049 | San Juan 30-5 Un 264        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 9  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003927772 | San Juan 30-5 Un 264A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 9  | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003926303 | San Juan 30-5 Un 265        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 10 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003927771 | San Juan 30-5 Un 265A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 10 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003926302 | San Juan 30-5 Un 266        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 10 | 030N | 005W | SENW | Hilcorp Energy Company |
| 3003927254 | San Juan 30-5 Un 266A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 10 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003926514 | San Juan 30-5 Un 267        | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 24 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003929250 | San Juan 30-5 Un 268A       | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 24 | 030N | 005W | SENW | Hilcorp Energy Company |
| 3003921148 | San Juan 30-5 Unit 002R     | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 29 | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003907717 | San Juan 30-5 Unit 009      | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 32 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003930128 | San Juan 30-5 Unit 027F     | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 20 | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003930128 | San Juan 30-5 Unit 027F     | Basin Dakota         | Flowing | NM | Rio Arriba | 20 | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003907822 | San Juan 30-5 Unit 033      | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 20 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003926803 | San Juan 30-5 Unit 049      | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 9  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003921654 | San Juan 30-5 Unit 068      | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 25 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003930720 | San Juan 30-5 Unit 085M     | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 36 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003930720 | San Juan 30-5 Unit 085M     | Basin Dakota         | Flowing | NM | Rio Arriba | 5  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003924806 | San Juan 30-5 Unit 207A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 19 | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003924971 | San Juan 30-5 Unit 209A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 20 | 030N | 005W | NWNW | Hilcorp Energy Company |
| 3003924720 | San Juan 30-5 Unit 210A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 16 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003929857 | San Juan 30-5 Unit 220A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 8  | 030N | 005W | NENW | Hilcorp Energy Company |
| 3003924901 | San Juan 30-5 Unit 220R     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 20 | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003924902 | San Juan 30-5 Unit 223A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 17 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003924893 | San Juan 30-5 Unit 230A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 32 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003925195 | San Juan 30-5 Unit 232R     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 33 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003925140 | San Juan 30-5 Unit 234A     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 27 | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003927488 | San Juan 30-5 Unit 237      | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 16 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003925141 | San Juan 30-5 Unit 237R     | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 34 | 030N | 005W | SENE | Hilcorp Energy Company |
| 3003925972 | San Juan 30-5 Unit 246      | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 23 | 030N | 005W | NENE | Hilcorp Energy Company |
| 3003929250 | San Juan 30-5 Unit 268      | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 24 | 030N | 005W | SENW | Hilcorp Energy Company |
| 3003930662 | San Juan 30-5 Unit Com 001N | Basin Dakota         | Flowing | NM | Rio Arriba | 4  | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003930662 | San Juan 30-5 Unit Com 001N | Blanco Mesaverde     | Flowing | NM | Rio Arriba | 4  | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003930662 | San Juan 30-5 Unit Com 001N | Basin Mancos         | Flowing | NM | Rio Arriba | 4  | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003924670 | San Juan 30-5 Unit 203A     | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 6  | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003929216 | San Juan 30-5 Unit 206A     | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 18 | 030N | 005W | SWSE | Hilcorp Energy Company |
| 3003927830 | San Juan 30-5 Unit 216A     | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 20 | 030N | 005W | NWNW | Hilcorp Energy Company |
| 3003925087 | San Juan 30-5 Unit 225      | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 29 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003929232 | San Juan 30-5 Unit 239A     | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 15 | 030N | 005W | SWNE | Hilcorp Energy Company |
| 3003929219 | San Juan 30-5 Unit 240A     | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 22 | 030N | 005W | SESE | Hilcorp Energy Company |
| 3003925166 | San Juan 30-5 Unit 242      | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 34 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003927805 | San Juan 30-5 Unit 243A     | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 15 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003925963 | San Juan 30-5 Unit 261      | Basin Fruitland Coal | Shut-In | NM | Rio Arriba | 11 | 030N | 005W | NWNE | Hilcorp Energy Company |

|            |                            |                      |                 |    |            |    |      |      |      |                        |
|------------|----------------------------|----------------------|-----------------|----|------------|----|------|------|------|------------------------|
| 3003921830 | San Juan 30-5 Unit 049     | Basin Dakota         | Shut-In         | NM | Rio Arriba | 9  | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003927858 | San Juan 30-5 Unit 212A    | Basin Fruitland Coal | Shut-In         | NM | Rio Arriba | 31 | 030N | 005W | SWNW | Hilcorp Energy Company |
| 3003927768 | San Juan 30-5 Unit 218A    | Basin Fruitland Coal | Shut-In         | NM | Rio Arriba | 17 | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003927487 | San Juan 30-5 Unit 219A    | Basin Fruitland Coal | Shut-In         | NM | Rio Arriba | 16 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003926640 | San Juan 30-5 Unit 219R    | Basin Fruitland Coal | Shut-In         | NM | Rio Arriba | 16 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003926508 | San Juan 30-5 Unit 267A    | Basin Fruitland Coal | Shut-In         | NM | Rio Arriba | 24 | 030N | 005W | NESW | Hilcorp Energy Company |
| 3003924826 | San Juan 30-5 Unit 213 POW | Basin Fruitland Coal | Monitoring Well | NM | Rio Arriba | 5  | 030N | 005W | NWNE | Hilcorp Energy Company |
| 3003924828 | San Juan 30-5 Unit 216 POW | Basin Fruitland Coal | Monitoring Well | NM | Rio Arriba | 20 | 030N | 005W | SWSW | Hilcorp Energy Company |
| 3003924768 | San Juan 30-5 Unit 219 POW | Basin Fruitland Coal | Monitoring Well | NM | Rio Arriba | 16 | 030N | 005W | NWSW | Hilcorp Energy Company |
| 3003907792 | San Juan 30-5 Unit 027     | Basin Dakota         | Perm Abandoned  | NM | Rio Arriba | 36 | 030N | 005W |      | Hilcorp Energy Company |
| 3003907792 | San Juan 30-5 Unit 027     | Blanco Mesaverde     | Perm Abandoned  | NM | Rio Arriba | 36 | 030N | 005W |      | Hilcorp Energy Company |
| 3003923129 | San Juan 30-5 Unit 085     | Basin Dakota         | Perm Abandoned  | NM | Rio Arriba | 18 | 030N | 005W |      | Hilcorp Energy Company |
| 3003923129 | San Juan 30-5 Unit 085     | Basin Fruitland Coal | Perm Abandoned  | NM | Rio Arriba | 30 | 030N | 005W |      | Hilcorp Energy Company |
| 3003923129 | San Juan 30-5 Unit 085     | Basin Fruitland Sand | Perm Abandoned  | NM | Rio Arriba | 30 | 030N | 005W |      | Hilcorp Energy Company |
| 3003925194 | San Juan 30-5 Unit 232     | Basin Fruitland Coal | Perm Abandoned  | NM | Rio Arriba | 16 | 030N | 005W |      | Hilcorp Energy Company |
| 3003926085 | San Juan 30-5 Unit 232R    | Basin Fruitland Coal | Perm Abandoned  | NM | Rio Arriba | 16 | 030N | 005W |      | Hilcorp Energy Company |








**San Juan 30-5 Unit**  
**Rio Arriba County, NM**

 San Juan 30-5 Unit

 Oil and Gas Well



## Hilcorp San Juan Production




SAN JUAN 30-5 UNIT

MESAVERDE PARTICIPATING AREA

NMNM 078419A



## Hilcorp San Juan Production



SAN JUAN 30-5 UNIT

DAKOTA PARTICIPATING AREA

NMNM 078419B



## Hilcorp San Juan Production



SAN JUAN 30-5 UNIT

PICTURED CLIFFS PARTICIPATING AREA

NMNM 078419C



## Hilcorp San Juan Production



SAN JUAN 30-5 UNIT

FRUITLAND COAL PARTICIPATING AREA

NMNM 078419D