

Submit 3 Copies
To Appropriate
District Office
DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

DISTRICT II
811 South First, Artesia NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-045-24263
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Barbara
8. Well No. 1.
9. Pool name or Wildcat Cha Cha Gallup

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	RECEIVED MAY 14 1999 OIL CON. DIV. DIST. 3
2. Name of Operator Northstar Oil and Gas Corp	
3. Address of Operator P.O. Box 93 Farmington, NM 87499	
4. Well Location Unit letter <u>(P)</u> : <u>760</u> feet from the <u>South</u> line and <u>810</u> feet from the <u>East</u> line Section <u>12</u> Township <u>29N</u> Range <u>15W</u> NMPM San Juan County	
5. Elevation (Show whether DF, RKB, RT, GR, etc.) 5179 G.L.	

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON

TEMPORARILY ABANDON ☐ CHANGE PLANS

PULL OR ALTER CASING ☐

OTHER: _____

SUBSEQUENT REPORT OF:

☐ REMEDIAL WORK

☐ COMMENCE DRILLING OPNS.

☐ CASING TEST AND CEMENT JOB

☐ OTHER: _____

☐ ALTERING CASING ☐

☐ PLUG AND ABANDONMENT ☐

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

1. Check anchors and prepare location
 2. R.U. workover rig. Kill well if necessary. Nipple up wellhead and BOP.
 3. Pull and inspect existing tubing.
 4. R/U with tubing and packer.
 5. Test casing and acidize Gallup perforations.
 6. Pull packer and re-run tubing with seat nipple.
 7. Drop bumper sub and plunger and hang on to test potential Gallup production.
- Operations are expected to begin within 90 days, but depend on negotiations with landowners.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Corbett TITLE President DATE 5/14/1999

Type or print name John C. Corbett Telephone No. (505) 327-5751

(This space for State use)

APPROVED BY ORIGINAL SIGNED BY CHARLIE T. PETERSON

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAY 14 1999

Conditions of approval, if any:

Before the OCC
Case 13920
Northstar Oil & Gas
OCD Ex. No. 7