|  | Mexico  | Form C-103  |  |
|--|---|---|--|
| Office District I  Energy, Minerals and N  | atural Resources  | May 27, 2004  |  |
| 1625 N. Fregch Dr., Hobbs, NM 88240  |   | WELL API NO.<br>30-025-01059  |  |
| District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION   | ON DIVISION   | 5. Indicate Type of Lease   |  |
| District III 1220 South St. F  | rancis Dr.  | STATE FEE   |  |
| 1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM  | 87505   | 6. State Oil & Gas Lease No.  |  |
| 1220 S. St. Francis Dr., Santa Fe, NM<br>87505   |   | B-9473  |  |
| SUNDRY NOTICES AND REPORTS ON WE   |   | 7. Lease Name or Unit Agreement Name  |  |
|  | (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH   |   |  |
| PROPOSALS.)  1. Type of Well: Oil Well  ☐ Gas Well ☐ Other   |   | HOPE STATE  8. Well Number  |  |
|  | 9. OGRID Number   |   |  |
| 2. Name of Operator C. W. TRAINER  | 2. Name of Operator   |   |  |
| 3. Address of Operator   |   | 10. Pool name or Wildcat  |  |
| c/o Oil Reports & Gas Services, Inc., 1008 W. Broadway, Hobbs, I   | NM 88240  | WILDCAT;ABO   |  |
| 4. Well Location   |   | ,   |  |
|  | JTH line and66  |   |  |
|  | ge 33E  | NMPM LEA County   |  |
| 11. Elevation (Show whether 4263 KB  | DR, KKB, KI, GK, etc.,  |   |  |
|  |   |   |  |
| Pit or Below-grade Tank Application or Closure   |   |   |  |
| Pit type Depth to Groundwater Distance from nearest fre  | sh water well Dis   | tance from nearest surface water  |  |
| Pit Liner Thickness: mil Below-Grade Tank: Volume  | bbls; Co  | onstruction Material  |  |
| 12. Check Appropriate Box to Indicate  | e Nature of Notice,   | Report or Other Data  |  |
| NOTICE OF INTENTION TO:  | SUB   | SEQUENT REPORT OF:  |  |
| PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐   | REMEDIAL WOR  |   |  |
| TEMPORARILY ABANDON  | COMMENCE DR   |   |  |
| PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB  |   |   |  |
| PULL OR ALTER CASING   MULTIPLE COMPL  | CASING/CEMEN  | T JOB 🔲   |  |
|  |   | T JOB   |  |
| OTHER:   | OTHER:  |   |  |
|  | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.   | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu  | OTHER:  | d give pertinent dates, including estimated date  |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS  | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB  | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE  | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450'   | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF.  | OTHER:  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450'   | OTHER: all pertinent details, an altiple Completions: At  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF.  | OTHER: all pertinent details, an altiple Completions: At  | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF.  | OTHER: all pertinent details, an altiple Completions: At Approved as to Liability under the second control of | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion plugging of the Well Bore.  |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF.  | OTHER: all pertinent details, an altiple Completions: At Approved as to Liability under the second control of | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF.  | OTHER: all pertinent details, an altiple Completions: At Approved as to Liability under the second control of | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion plugging of the Well Bore.  |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  | Approved as to Liability under to surface restoration   | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion plugging of the Well Bore.  plugging of the Well Bore.  cond is retained until on is completed. |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  | Approved as to Liability under to surface restoration   | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion plugging of the Well Bore.  plugging of the Well Bore.  cond is retained until on is completed. |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideling.   | Approved as to Liability under to surface restoration   | d give pertinent dates, including estimated date tach wellbore diagram of proposed completion plugging of the Well Bore.  plugging of the Well Bore.  cond is retained until on is completed. |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideling.  SIGNATURE A TITLE  | Approved as to Liability under the surface restoration of the surface and the surface and the surface are surface as a general permit AGENT   | plugging of the Well Bore.  pond is retained until on is completed.  DATE 05/20/05  |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideling.  SIGNATURE A TITLE  | Approved as to Liability under the surface restoration of the surface and the surface and the surface are surface as a general permit AGENT   | plugging of the Well Bore.  cond is retained until con is completed.  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan                   |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideling SIGNATURE  Type or print name GAYE HEARD  For State Use Only  E-mail address: oilrep-  | Approved as to Liability under the surface restoration of the surface and the surface and the surface are surface as a general permit AGENT   | plugging of the Well Bore.  pond is retained until on is completed.  DATE 05/20/05  |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideling SIGNATURE  Type or print name GAYE HEARD  F-mail address: oilreptor State Use Only  APPROVED BY:  ### APPROVED BY: ################################### | Approved as to Liability under the surface restoration of the surface and the surface are the | plugging of the Well Bore.  plugging of the Well Bore.  cond is retained until  con is completed.  DATE 05/20/05  OS 67 97  DATE  DATE  DATE  DATE  DATE  DATE                                |  |
| OTHER:  13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompletion.  WELL P&A 02/11/05 AS FOLLOWS:  SET CIBP 50' ABOVE PERFS CUT CSG OFF AT 5000' & SET 50' IN & OUT OF STUB 100' PLUG @ 9-5/8" SHOE 50' @ BASE OF SALT 50' IN & OUT OF STUB @ 450' 50' TO SURF. INSTALL DRY HOLE MARKER  I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideling SIGNATURE  Type or print name GAYE HEARD  For State Use Only  E-mail address: oilrep-  | Approved as to Liability under the surface restoration of the surface and the surface and the surface are surface as a general permit AGENT   | plugging of the Well Bore.  plugging of the Well Bore.  cond is retained until on is completed.  DATE 05/20/05  om Telephone No. 505-393-2727   |  |

| Submit 3 Copies To Appropriate District                | State of New Mexico  | Form C-103   |  |  |
|--|--|--|--|--|
| Office<br>District I                                   | Energy, Minerals and Natural Resources   | May 27, 2004<br>WELL API NO.   |  |  |
| 1625 N. French Dr., Hobbs, NM 88240                    |  |  |  |  |
| District II  | OIL CONSERVATION DIVISION  | 30-025-23611   |  |  |
| 1301 W. Grand Ave., Artesia, NM 88210<br>District III. | 1220 South St. Francis Dr.   | 5. Indicate Type of Lease  |  |  |
| 1000 Rio Brazos Rd., Aztec, NM 87410                   | Santa Fe, NM 87505   | STATE FEE  |  |  |
| District IV 1220 S. St. Francis Dr., Santa Fe, NM      | Salita Fe, INIVI 87303   | 6. State Oil & Gas Lease No.   |  |  |
| 87505  | •  |  |  |  |
|  | ES AND REPORTS ON WELLS  | 7. Lease Name or Unit Agreement Name   |  |  |
|  | ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  | ,  |  |  |
| PROPOSALS.)  | ATION FOR PERMIT* (FORM C-101) FOR SUCH  | Lea DS State   |  |  |
| 1. Type of Well: Oil Well                              | Gas Well Other   | 8. Well Number 1   |  |  |
| 2. Name of Operator                                    |  | 9. OGRID Number 003474   |  |  |
| C. W. Trainer  |  |  |  |  |
| 3. Address of Operator                                 |  | 10. Pool name or Wildcat   |  |  |
| P. O. Box 754, Midland Texas 7970                      | 2  | Lea San Andres   |  |  |
| 4. Well Location                                       |  |  |  |  |
| Unit Letter E : 2086                                   | feet from the North line and 5   | feet from the West line  |  |  |
| Section 36   | Township 19S Range 34E   | NMPM Lea County  |  |  |
|  | 11. Elevation (Show whether DR, RKD, RT, GR, etc.  |  |  |  |
|  |  |  |  |  |
| Pit or Below-grade Tank Application or                 | Closure  | Marineth Biggior State States Branch Court Branch B |  |  |
| Pit typeDepth to Groundwate                            | erDistance from nearest fresh water wellDis  | tance from nearest surface water   |  |  |
| Pit Liner Thickness: mil                               | Below-Grade Tank: Volume bbls; Co  | onstruction Material   |  |  |
| 12 Charle As   | annoneista Day to Indicata Natura of Natica  | Donast as Other Date   |  |  |
| 12. Check Ap   | opropriate Box to Indicate Nature of Notice,   | Report of Other Data   |  |  |
| NOTICE OF INT  | ENTION TO SUB  | SEQUENT REPORT OF:   |  |  |
| ·  | PLUG AND ABANDON REMEDIAL WOR  |  |  |  |
|  | <u> </u>   | ILLING OPNS.□ PANDA 🛱  |  |  |
| · ·  | MULTIPLE COMPL   CASING/CEMEN  |  |  |  |
|  |  |  |  |  |
| OTHER:   | other: and   | Pau Dull Casich  |  |  |
| <ol> <li>Describe proposed or comple</li> </ol>        | ted operations. (Clearly state all pertinent details, an                                     | d give pertinent dates, including estimated date   |  |  |
|  | k). SEE RULE 1103. For Multiple Completions: A   | ttach wellbore diagram of proposed completion  |  |  |
| or recompletion.                                       |  | Approved as to plugging of the Well Bo   |  |  |
| Ran and set a CIBP at 5975'K.B.                        | oduction equipment pulled out of the hole.   | The state of the s |  |  |
| Circulate fresh water to clean out casin               | 06-106   | surface restoration is completed.  |  |  |
| 5.5" casing free at 3160' K.B.                         | 18. 0/25/00  | completed.   |  |  |
|  | ormed that he wanted the hole circulated with mud a  | nd cement on top of the first bridge plug  |  |  |
|  | went in the hole open ended to 5940' K.B.  | nd cement on top of the first bridge plug.   |  |  |
|  | we asked for approval to spot cement from 5900' to   | 5575' K.B., got approval and would   |  |  |
| Have to tag.   |  | , grappe and mount   |  |  |
| Spot 75 sacks of cement, shut down for                 | ornight.   |  |  |  |
| Tagged cement at 5375' K.B.                            |  |  |  |  |
| Went in the hole and shot casing at 41                 | 70' K.B. did not pull shot again at 3160' K.B. came  | free and pulled out of the hole with casing.   |  |  |
|  | waited 3 hours and tagged cement at 3050'.   |  |  |  |
| Cut and pulled out of the hole with 890                |  | P. C.  |  |  |
| Mixed 90 sacks cement and nump in                      | K.B. Waited for 1 hour and tagged at 826' K.B. waited 1.5 hours and tagged plug at 317' K.B. | to the state   |  |  |
| Mixed up 90 sacks of cement pumped                     |  | 6  |  |  |
| Cut off well head and set dry hole mar                 | ker.   | 1 " Carolina   |  |  |
| I hereby certify that the information ab               | ove is true and complete to the best of my knowledge   | e and helief. I further certify that any nit or helow-   |  |  |
| grade tank has been/will be constructed or el          | osed according to NMOCD guideline have to tag, a general per                                 | rmit or an (attached) alternative OCD-approved   |  |  |
| pian   | 11100  | 1) Julius Sarahatila   |  |  |
| SIGNATURE () May DATE STOP                             |  |  |  |  |
| Type or print name & heryl                             | L JOHNS HOLLES STONAS HOLE   | AD/COATelephone No. 452-651  |  |  |
| For State Use Only                                     | L man audices. 4407-110 4011C.   | ELICENTEICHIONE NO. 10° 600 WILL   |  |  |
| APPROVED 9   |  |  |  |  |
| BY: Haufu.W  | WATITLE  | Conditions of  |  |  |
|  | AND STAFF  | MANAGER  |  |  |

to Appropriate District Office

DISTRICT I

**OIL JONSERVATION DIVISION** 

| WELL API NO. |  |
|--------------|--|
| 30-005-00588 |  |

| DISTRICT II Santa Fe, New Mex  | ico 87505                                       |  |
|--|---|--|
| 811 S. First, Artesia, NM 88210  | · · · · · · · · · · · · · · · · · · ·           | 30-005-00588                           |
| DISTRICT III   |   | 5. Indicate Type of Lease              |
| 1000 Rio Brazos Rd, Azlec, NM 87410  |   | STATE FEE X                            |
| DISTRICT IV  |   | 4.0.014.0.1.N                          |
| 2040 South Pacheco, Santa Fe, NM 87505   | ·   | 6. State Oil & Gas Lease No.           |
|  |   |  |
|  |   |  |
| SUNDRY NOTICES AND REPORTS O   | NWELLS  |  |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEEPEN  |   | 7. Lease Name or Unit Agreement Name   |
| DIFFERENT RESERVOIR USE "APPLICATIO  |   | 7. Lease traine of One Agreement raine |
| (FORM C-101) FOR SUCH PROPOS   |   | •                                      |
| I. Type of Well:   | ALS)  | •                                      |
| OIL X GAS  |   | M & W MEDLIN                           |
| WELL WELL OTHER  |   |  |
| 2. Name of Operator  |   | 8. Well No.                            |
| C. W. TRAINER  | ·   | 1                                      |
| 3. Address of Operator   |   | 9. Pool name or wildcat                |
| c/o OIL REPORTS & GAS SERVICES, INC.,1008 W. BROADWA   | AY, HOBBS, NM 88240                             | WILDCAT; SAN ANDRES                    |
| 4. Well Location   |   |  |
| Unit Letter D : 660 Feet From The NORTH  | Line and 660                                    | Feet From The WEST Line                |
| Only Detter D . Ood Peter Tour The TVOTTA  | Encar.  | TOUTH THE THEORY                       |
| Section 8 Township 15S Range 31E   |   | NMPM CHAVES County_                    |
| 10, Elevation (Show whether DF, RKB, RT, CR, ect.  |   |  |
| 4278   |   |  |
| 11. 1 Check Appropriate Box to Indicate Natur  | e of Notice, Report, or Ot                      | her Data                               |
| NOTICE OF INTENTION TO:  | SUPSECIE  | NT REPORT OF:                          |
| NOTICE OF INTENTION TO.  | 30832402  | NI REPORT OF.                          |
| PERFORM REMEDIAL WORK PLUG AND ABANDON   | REMEDIAL WORK                                   | ALTERING CASING                        |
| TEMPORARILY ABANDON CHANGE PLANS   | COMMENCE DRILLING OPNS.                         | PLUG & ABANDONMENT X                   |
| PULL OR ALTER CASING   | CASING TEST & CEMENT JOB                        |  |
| OTHER:   | OTHER:  | ·                                      |
| 13 December 2011 Company Compa |   | A. A. CEP NULE 1103                    |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da  | es, including estimated date of starting any pa | roposea work, Set KULE 1103.           |
|  |   |  |


12-18-02 30 sx @ 3084-2948 12-19-02 17 sx @ 1400 25 sx @ 237 20 sx @ 60-surface 12-21-02 Place dry hole marker

Approved as to Plugging of the Well Bore. Liability under bond is retained until Surface restoration is completed.



| I hereby certify that the information above is true of | and comple  | ete to the best of my kno             | wledge and belief. |               |                |          |
|--|-------------|---------------------------------------|--------------------|---------------|----------------|----------|
| SIGNATURE DAY SHIMA.                                   | *           | TITLE                                 | AGENT              |               | DATE 12-31-02  |          |
| TYPE OR PRINT NAME Gaye Heard                          | <del></del> | · · · · · · · · · · · · · · · · · · · |                    | TELEPHONE NO. | (505) 393-2727 | <u> </u> |
| (THIS SPACE FOR STATE USE)                             |             |                                       |                    |               |                |          |
| APPROVED BY  | TITLE       |                                       |                    |               | DATE           |          |
| CONDITIONS APPROVAL, IF ANY:                           |             | or officers                           | ESENTATOVE ((/STA  | AFF MANAGE    | JAN 0 3 2003   |          |

| •  | :  | . •                        |  |
|--|--|----------------------------|--|
| Submit 3 Copies To Appropriate District Office   | State of New Mexico  |                            | Form C-10<br>Revised June 10, 200  |
| District I<br>1625 N. French Dr., Hobbs, NM 88240  | Energy, Minerals and Natural R   | WELL AP                    |  |
| <u>District II</u><br>1301 W. Grand Ave., Artesia, NM 88210<br><u>District III</u>                           | OIL CONSERVATION DIV<br>1220 South St. Francis I   | 5. Indicate                | Type of Lease  |
| 1000 Rio Brazos Rd., Aztec, NM 87410<br><u>District IV</u><br>1220 S. St. Francis Dr., Santa Fe, NM<br>87505 | Santa Fe, NM 87505   | 517                        | TE FEE   |
| SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOS   | CES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BA ATION FOR PERMIT" (FORM C-101) FOR SUC | CK TO A                    | ame or Unit Agreement Name<br>NるMとU  |
| PROPOSALS.)  1. Type of Well:  Oil Well  Gas Well  | Other  | 8. Well No                 | ımber  |
| 2. Name of Operator  | Trainer  | 9. OGRID                   | Number   |
| 3. Address of Operator   | ox 754 Midland TX  | 79702 Tres                 | ame or Wildcat<br>Papalotes  |
| 4. Well Location   |  |                            |  |
| _  | 2144 feet from the North   |                            |  |
| Section 5  | Township 15 S Range 11. Elevation (Show whether DR, RKB)   |                            | Lea County   |
| 12. Check A  | ppropriate Box to Indicate Nature  | of Notice, Report or       | Other Data   |
| NOTICE OF INPERFORM REMEDIAL WORK  | TENTION TO:  |                            | T REPORT OF:   |
| TEMPORARILY ABANDON  | CHANGE PLANS   | MMENCE DRILLING OF THE     | PLUG AND BABANDONMENT  |
| PULL OR ALTER CASING   |  | SING TEST AND MENT JOB     | OF THE TOTAL |
| OTHER:   | ОТН  | / c. / c.                  |  |
| of starting any proposed wor or recompletion.  | eted operations. (Clearly state all pertine k). SEE RULE 1103. For Multiple Cor                      | mpletions: Attach wellbore | diagram of proposed completion   |
| E Han 20, 2004 1   | Ran 2%"+bg in ho   | le to 742                  | 06   |
| Approved as to Hability under surface restora  | Spotted 65 sack c  | ement plug -               | rom 142 TO 69  |
| 3 + so plu ed as to plu under bon restoration  | Pulled 4 jts tbg.  | 4 circuted                 | hole w. 4.37   |
| <i>□</i> .   | PUH w + bg to 2  | 135' & spotte              | d 50 sack cem  |
| plugging bond is n   | 9. Waited 3 hour   | s 4 tagged                 | top of cement  |
| ging com   |  |                            |  |
| T 70 D   | . Spotted 10 sack c  |                            | 7 surtace.   |
| Se Wel e Wel ed.   | . Setdry hole i  | narker.                    |  |
|  | bove is true and complete to the best of i   | ny knowledge and belief.   | **************************************   |
| SIGNATURE John   | Jones TITLE C  | onsultant                  | DATE Jan 22 20   |
|  | Sould Jr E-mail address:   |                            | Telephone No. 432 687  |
| (This space for State use)   | OC FIELD RE  | PRESENTATIVE II/STAFF      | MANAGARA   |
| Conditions of approval, if and   | Winds TITLE  |                            | PANES () 2004  |



| Office District I Energy, Minera  | of New Mexico als and Natural Resources   | Form C-103<br>May 27, 2004   |
|---|---|--|
| District III 1220 Soil  | RVATION DIVISION uth St. Francis Dr. Fe, NM 87505                                     | WELL API NO. 30-025-35093  5. Indicate Type of Lease STATE FEE  6. State Oil & Gas Lease No.         |
| SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOR PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other  | EEPEN OR PLUG BACK TO A   | 7. Lease Name or Unit Agreement Name  TOWER  8. Well Number  2                                       |
| <ol> <li>Name of Operator</li> <li>W. TRAINER</li> <li>Address of Operator</li> <li>c/o Oil Reports &amp; Gas Services, Inc. 1008 W. Broadway,</li> <li>Well Location</li> </ol>  |   | 9. OGRID Number<br>003474<br>10. Pool name or Wildcat<br>WILDCAT;SAN ANDRES                          |
| Section 23 Townshi  11. Elevation (Show  Pit or Below-grade Tank Application or Closure Pit type STEEL Depth to Groundwater 70' Distance from   | ip 12S Range 33E whether DR, RKB, RT, GR, etc.  | Distance from nearest surface water_>1000'   |
| Pit Liner Thickness: mil Below-Grade Tank:  12. Check Appropriate Box to  |   | Papert or Other Date   |
| NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDO  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPL  OTHER:  13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 1103. or recompletion. | SUE REMEDIAL WOF COMMENCE DR CASING/CEMEN OTHER: arly state all pertinent details, an | SSEQUENT REPORT OF:  RK  |
| SET CIBP @ 4188' W/ 10 SX CMT ON TOP<br>50 SX PLUG AT 2380'-2280'<br>50' IN & OUT @ 895'-795', TAGGED<br>SPOT 100' PLUG 400'-300'<br>60' PLUG FROM SURFACE<br>INSTALL DRY HOLE MARKER<br>P&A 5/27/05  | t iabilit   | ved as to plugging of the Well Bore.  Ty under bond is retained until  The restoration is completed. |
| I hereby certify that the information above is true and comp<br>grade tank has been/will be constructed or closed according to NMOO   |   |  |
| SIGNATURE   | TITLEAGENT  | DATE_5/31/05   |
| APPROVED BY: Loug W. Wink   | ess: oilreportsinc@oilreportsinc.   | com Telephone No. 505-393-2727   |
| Conditions of Approval (if any):  |   |  |