



ConocoPhillips San Juan Business Unit P.O. Box 4289 Farmington, NM 87499-4289

February 25, 2011

Bureau of Land Management Farmington Resource Area 1235 La Plata Highway Farmington, NM 87401

Oil Conservation Division State of New Mexico 1220 S. Saint Francis Drive Santa Fe, NM 87505 Commissioner of Public Lands State of New Mexico P. O. Box 1148 Santa Fe, NM 87501-1148

RE: 2011 Plan of Development Lindrith "B" Unit, I SEC. #713 Rio Arriba County, New Mexico

Ladies and Gentlemen:

The following Participating Areas currently exist in the Lindrith Unit:

, .	FORMATION	EXPANSION	EFFECTIVE DATE
	GALLUP	000	01-JAN-86
	DAKOTA	004	01-NOV-84

The 2010 Plan of Development (or amendments thereto) provided for no wells to be drilled during 2010.

Pursuant to Section 9 of the Lindrith Unit Agreement, ConocoPhillips Company, as Unit Operator, hereby submits no wells for the **2011 Plan of Development**.

The working interest owners are being furnished a copy of this letter, well status listing and enclosed map. ConocoPhillips, as Unit Operator, will drill any offset wells required to prevent drainage of unitized substances and any other wells deemed necessary by the working interest owners or Unit Operator.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (505) 326-9749 if there are any questions regarding this letter.

Sincerely,

Ben Maho

Ben Malone, Land Supervisor, SE

BM/vw: Lindrith Unit, 3.0 (2011) Lindrith Unit Working Interest Owners

LINDRITH UNIT

LINDRITH UNIT 2010 PLAN OF DEVELOPMENT

2011 PLAN OF DEVELOPMENT APPROVALS

Bureau of Land Management

New Mexico Oil Conservation Division

New Mexico Commissioner of Public Lands

Date

Date

Date

LINDRITH UNIT WORKING INTEREST OWNER

CONOCOPHILLIPS COMPANY

LINDRITH B UNIT Well Status as of 01-06-11

•

•

Well Name LINDRITH B UNIT 103 DK LINDRITH B UNIT 108 DK LINDRITH B LINIT 10 DK			-	-	-					MIND FLOO	MMS Prod MMS Lse Agr						
LINDRITH B UNIT 103 DK LINDRITH B UNIT 108 DK LINDRITH B UNIT 10 DK	Rsvr Name	Sec	Twnshp	Twnshp Dir	Rng R	Rng Dir S	ST Prod Stat		Api Well Code	Inteval	Number	Lse ID	Oper ID	Compl Dt	t Int Prod Dt	t 1st Sale Dt	
LINDRITH B UNIT 108 DK 11 INDRITH B LINIT 10 DK	LINDRITH GALLUP DAKOTA,WS	18	24	z	2		NM 11		300392572200S01	S01	8920007130	A706737	012001	<u> </u>	4/17/1998	4/17/1998	M
I INDRITH B UNIT 10 DK	LINDRITH GALLUP DAKOTA,WS	15	24	z	9	M	11 NM		300392679100S01	S01	0820789130	A707094	012001			, ,	Ŵ
	LINDRITH GALLUP DAKOTA,WS	34	24	z	3	M N	NM 11		300392240200S01	s01	0820789150	A706422	012001	9/15/1980	9/15/1980	9/15/1980	M
LINDRITH B UNIT 110 DK	LINDRITH GALLUP DAKOTA,WS	15	24	z	3	M N	11 MN		300392682000S01	S01	892000713X	A707094	012001		2/25/2002	2/25/2002	M
LINDRITH B UNIT 113 DK	LINDRITH GALLUP DAKOTA,WS	10	24	z	3	W I	NM 11		300392676600S01	S01	0820789120	A706425	012001		11/20/2001	11/20/2001	M
LINDRITH B UNIT 11 DK	LINDRITH GALLUP DAKOTA,WS	16	24	N	3	W	11 NM		300392253500S01	S01	892000713A	A706416	012001	1/13/1981	1/13/1981	1/13/1981	M
LINDRITH B UNIT 12 DK	LINDRITH GALLUP DAKOTA,WS	22	24	v	3	W N	NM 11		300392255000S01	S01	0820789130	A706424	012001	3/12/1981	3/12/1981	3/12/1981	M
LINDRITH B UNIT 13 DK	LINDRITH GALLUP DAKOTA,WS	27	24	z	6		11 NM		300392255100S01	S01	892000713A	A706416	012001	4/13/1981	4/13/1981	4/13/1981	W
LINDRITH B UNIT 14 DK	LINDRITH GALLUP DAKOTA,WS	16	24	z	3		NM 11		300392255400S01	S01	892000713A	A706416	012001	4/6/1981	4/6/1981	4/6/1981	M
LINDRITH B UNIT 15 DK	LINDRITH GALLUP DAKOTA,WS	21	24	N	3		NM 11		300392255500S01	S01	892000713A	A706416		2/19/1981	2/19/1981	2/19/1981	M
LINDRITH B UNIT 16 DK	LINDRITH GALLUP DAKOTA,WS	21	24	z	3	M N	NM 41		300392254900S01	S01	892000713A	A706416	012001	1/22/1981	1/22/1981	1/22/1981	M
LINDRITH B UNIT 17 DK	LINDRITH GALLUP DAKOTA,WS	16	24	z	3	M N	11 NM		300392271200S01	S01	892000713A	A706416	012001	7/27/1981	7/27/1981	7/27/1981	IM
LINDRITH B UNIT 18 DK	LINDRITH GALLUP DAKOTA,WS	22	54	z	3		11 MN		300392271300S01	S01	892000713A	A706416	012001	6/30/1981	6/30/1981	6/30/1981	w
LINDRITH B UNIT 19 DK	LINDRITH GALLUP DAKOTA,WS	27	24	z	e	M	NM 41		300392271500S01	\$01	0820789140	A706421	012001	6/11/1981	6/11/1981	6/11/1981	IW
LINDRITH B UNIT 1 DK	LINDRITH GALLUP DAKOTA,WS	28	24	z	т г	3	NM 11		300392213700S01	S01	892000713A	A706416	012001	2/4/1980	2/4/1980	2/20/1980	W
LINDRITH B UNIT 20 DK	LINDRITH GALLUP DAKOTA,WS	26	54	z	3	M	11 NM		300392271400S01	S01	0820789140	A706421	012001	5/11/1981	5/11/1981	5/11/1981	IM
LINDRITH B UNIT 21 DK	LINDRITH GALLUP DAKOTA,WS	15	24	z	m	M	NM NI		300392271100S01	S01	892000713A	A706416	012001	7/16/1981	7/16/1981	7/16/1981	M
LINDRITH B UNIT 22 DK	LINDRITH GALLUP DAKOTA,WS	15	24	z	. ۲	M	NM 11		300392303600S01	\$01	892000713A	A706416	012001	10/19/1982	10/19/1982	10/19/1982	w
LINDRITH B UNIT 23 DK	LINDRITH GALLUP DAKOTA,WS	16	24	z		3	11 NM		300392303700S01	S01	892000713A	A706416	012001	10/25/1982	10/25/1982	10/25/1982	M
LINDRITH B UNIT 25 DK SWD	LINDRITH GALLUP DAKOTA,WS	6	24	z	۳ ۳	3	NM 31	Γ	300392324700S01			A706423	012001	11/29/1983	1/1/1994	11/22/1983	M
LINDRITH B UNIT 26 DK	LINDRITH GALLUP DAKOTA,WS	6	24	z	с,	1	11 II		300392346500S01	S01	892000713A	A706416	012001	10/31/1984	10/31/1984	10/31/1984	M
LINDRITH B UNIT 27 DK	LINDRITH GALLUP DAKOTA,WS	10	24	z	'n	M	NM 41		300392360900S01	501	0820789120	A706425	012001	1/24/1985	1/24/1985	1/24/1985	M
LINDRITH B UNIT 29 DK	LINDRITH GALLUP DAKOTA,WS	16	24	z		Z A	NM 11		300392386800S01	S01	892000713A	A706416	012001	3/21/1986	3/21/1986	3/21/1986	W
LINDRITH B UNIT 2 DK	LINDRITH GALLUP DAKOTA,WS	28	24	z	۳	M	11 NM		300392213800501	S01	892000713A	A706416	012001		1/1/1994	3/17/1980	IM
LINDRITH B UNIT 30 DK	LINDRITH GALLUP DAKOTA WS	16	24	z	3	A W	NM 11		300392385900S01	S01	892000713A	A706416	012001	4/1/1986	4/1/1986	4/1/1986	w
LINDRITH B UNIT 31 DK	LINDRITH GALLUP DAKOTA WS	21	24	z	3	M N	NM 41		300392396800S01	S01	892000713A	A706416	012001	4/21/1986	4/21/1986	4/21/1986	M
LINDRITH B UNIT 32 DK	LINDRITH GALLUP DAKOTA,WS	21	24	z	3	4 M	11 MN		300392392400S01	S01	892000713A	A706416	012001	3/5/1986	3/5/1986	3/5/1986	M
LINDRITH B UNIT 34 GM	GAVILAN::MANCOS	32	25	N	2	M N	NM 11		300392373800S01	S01	892000713B	A706428	012001	1/26/1986	1/26/1986	6/30/1996	M
LINDRITH B UNIT 35 DK	LINDRITH GALLUP DAKOTA,WS	6	24	z	3	M N	NM 41		300392375500S01		:	A706423	012001	12/4/1985	12/4/1985	12/4/1985	MI
LINDRITH B UNIT 37 GM	GAVILAN::MANCOS	4	24	z	2	W N	NM 11		300392381600501	S01	892000713B	A706428	012001	1/23/1986	1/23/1986	9/30/1996	M
LINDRITH B UNIT 40 DK	LINDRITH GALLUP DAKOTA,WS	15.	24	z	n	M	NM 11		300392379700S01	S01	892000713A	A706416		3/13/1986	3/13/1986	3/13/1986	M
LINDRITH B UNIT 41 DK	LINDRITH GALLUP DAKOTA,WS	16	24	z	e	A W	NM 11		300392384000S01	S01	892000713A	A706416	012001	2/24/1986	2/24/1986	2/24/1986.	M
LINDRITH B UNIT 42 DK	LINDRITH GALLUP DAKOTA,WS	15	24	N	3	W N	NM 11	_	300392377800S01	S01	892000713A	A706416	_	12/22/1985	12/22/1985	12/22/1985.	w
LINDRITH B UNIT 44 DK	LINDRITH GALLUP DAKOTA,WS	21	24	N	3	W N	NM 41		300392386000501	S01	892000713A	A706416		4/15/1986	4/15/1986	4/15/1986	M
LINDRITH B UNIT 45 DK	LINDRITH GALLUP DAKOTA,WS	28	24	z	3		NM 41		300392387300S01	S01	892000713A	A706416		5/2/1986	5/2/1986	5/2/1986	M
LINDRITH B UNIT 46 DK	LINDRITH GALLUP DAKOTA,WS	28	24	z	3	M N	11 NM		300392386100S01	S01	892000713A	A706416		5/15/1986	5/15/1986	5/15/1986	M
LINDRITH B UNIT 5 DK	LINDRITH GALLUP DAKOTA,WS	21	24	z	'n	M N	11 NM		300392238400S01	S01	892000713A	A706416	012001	9/4/1980	9/4/1980	9/4/1980	M
LINDRITH B UNIT 6 DK	LINDRITH GALLUP DAKOTA,WS	28	24	z	e	4 M	NM 11		300392242400S01	S01	0820789140	A706421	012001	10/15/1980	10/15/1980	10/15/1980	IM
LINDRITH B UNIT 73 GM	GAVILAN::MANCOS	9	24	z	2	A N	11 NM		300392408900S01	SD1	0820789070	A706417	012001	3/31/1987	3/31/1987	3/31/1987	M
LINDRITH B UNIT 78 DK	LINDRITH GALLUP DAKOTA,WS	9	24	z	2	×	11 MN		300392506600S01	S01	0820789070	A706426	012001	8/11/1991	8/11/1991	8/11/1991	IM
LINDRITH B UNIT 79 DK	LINDRITH GALLUP DAKOTA,WS	2	24	z	2	4 M	11 MN		300392510500S01	S01	0820789080	A706427	012001	11/5/1991	1/6/1992	1/6/1992	W
LINDRITH B UNIT 7 DK	LINDRITH GALLUP DAKOTA,WS	28	24	z	n	M N	11 MN		300392245000S01	S01	892000713A	A706416	012001	12/9/1980	12/9/1980	12/9/1980	M
LINDRITH B UNIT 82 DK	LINDRITH GALLUP DAKOTA,WS	80	24	z	2	N	11 NM		300392515400S01	SO1	0820789080	A706419	012001	3/24/1992	3/24/1992	3/24/1992 .	M
LINDRITH B UNIT 8 DK	LINDRITH GALLUP DAKOTA,WS	27	24	z	m	۷ ۸	11 MN		300392242200S01	S01	892000713A	A706416	012001	10/25/1980	10/25/1980	11/5/1980	M
LINDRITH B UNIT 9 DK	LINDRITH GALLUP DAKOTA,WS	27	24	N	3	A N	11 MN		300392242300S01	S01	0820789140	A706421	012001	11/4/1980	11/4/1980	11/4/1980	M

61 Temp Abandoned
71 Perm Abandoned Well
82 Drilling Development
31 - Active Service Wells

Prod Stat: 11 Flowing Well 21Pumping Well 41 Shut-In PM Pressure Monitoring

	Well Formation PICTURED CLIFFS CHACRA MANCOS	 GALLUP /SD/ SH/ DAKOTA 	ConocoPhilline	Inventory Management San Juan Business Unit Farmington, New Mexico
		(§) 89	- 3-8-8-8-8-8-8 - 8 -8-8	
	000 (000 (000 (000 (000 (000 (000 (000		²³ ★ ³⁰	× =
		025) 86 7 7	200 ¥ 0000 € 10000 € 10000 € 10000 € 10000 € 1000 € 1000 € 1000 € 1000 € 10000	*
34 (<u>3</u> 3 (<u>3</u> 3		4 × 1000 × 14	*	
		N		S C
÷		£ ³ ₩	64 65	
	19	4 018	99 * € 5	27
		05. 0	³⁴ ★ ⁵⁶	and a second
9			66-	
	5	¥39	**************************************	
	X V X	* (8) *		
		42 23 60R 60R	20 30 30 30 30 30 30 30 30 30 3	# # # - - - - - - - - - - - - - - - - -
19 ×	*	²⁰ ★ ¹² ★ ¹² ★ ¹²	³⁸	
		6 (107 (107 (107 (107 (107 (107)(107)(107)(107)(107)(107)(107)(107)		
		31 32 3 3 30 5 46 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(<u>5</u>
	4 4 5 5 5 4 6 6 1 4 6 6 1 4 6 6 1 4 1 4	4.00 - m		