

RICHARDSON PRODUCTION COMPANY

1700 Lincoln, Suite 1700 Denver, Colorado 80203 (303) 830-8000 Fax (303) 830-8009

April 18, 2002

Joan E. Henderson, Trustee Howard E Henderson Living Trust dtd 09/24/97 5809 N. 24th Place Phoenix, AZ 86016

Certified Mail 7000 1670 0006 8579 2213 Return Receipt Requested

RE: Case No. 12798, Order No. R-11760 RPC 17-4 Well (Pictured Cliff formation) SE/4 Section 17, Township 29 North, Range 14 West San Juan County, New Mexico

Dear Mrs. Henderson:

In accordance with paragraph number (6) of Order No. R-11760, enclosed is an Authority for Expenditure outlining the estimated costs to drill the RPC 17-4 well to the Pictured Cliffs formation, with completion in the Pictured Cliffs formation.

According to paragraph number (6) of Order No. R-11760 you have the right to pay the estimated well costs and become a working interest owner in the RPC 17-4 well.

Should you have any questions concerning the enclosure I can be contacted at the letterhead address, by telephone at (303) 830-8000 or by e-mail at <u>rvanblaricom@richardsonoil.com</u>.

Very truly yours,

Beleecea E. Van Blacium

Rebecca E. Van Blaricom Land Manager

/revb Enclosure 02 APR 22

I.: C

 $\dot{\Omega}$

 \bigcirc