

## PROCEDURE:

LOAD WELL WITH TREATED PRODUCED WATER. PULL RODS AND PUMP, TUBING AND PACKER. CLEAN OUT ANY FILL TO T.D. RUN CEMENT LINED TUBING WITH PACKER TO BE SET AT 3870'. HOOK UP FOR INJECTION.

Planting State Company and Com	The section of the se
BEFORD IN A SECTION	
OIL COMMENSALE AND	
Lyon many 3	)
CASS 180. 5062	
Submitted by Coroco	
Hearing Dus 6-6-3	<u> </u>
Companies and the Companies of the Compa	