1	NEW MEXICO OIL CONSERVATION DIVISION
2	STATE LAND OFFICE BUILDING
3	STATE OF NEW MEXICO
4	CASE NO. 10633
5	
6	IN THE MATTER OF:
7	
8	The Application of Conoco Inc., for Unorthodox Oil Well Location,
9	North Dagger Draw-Upper Pennsylvanian Pool, Eddy County, New Mexico.
10	lool, laa, coancy, now memleo.
11	
12	
13	
14	
15	BEFORE:
16	MICHAEL E. STOGNER
17	Hearing Examiner
18	State Land Office Building
19	December 17, 1992
20	DEGE VED
2 1	
2 2	JAN 6 1993
23	REPORTED BY: OIL CONSERVATION DIVISION
24	CARLA DIANE RODRIGUEZ Certified Court Reporter for the State of New Mexico

ORIGINAL

1	APPEARANCES
2	
3	FOR THE NEW MEXICO OIL CONSERVATION DIVISION:
4	ROBERT G. STOVALL, ESQ.
5	General Counsel State Land Office Building
6	Santa Fe, New Mexico 87504
7	
8	FOR THE APPLICANT:
9	K ELLAHIN and KELLAH IN Post Office Box 2265
10	Santa Fe, New Mexico 87504-2265 BY: W. THOMAS KELLAHIN, ESQ.
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
2 2	
23	
2 4	
25	

1	INDEX	
2	Page Number	
3		
4	Appearances 2	
5		
6	WITNESSES FOR THE APPLICANT:	
7		
8	1. <u>BILL HARDIE</u>	
9	Examination by Mr. Kellahin 5	
10	Examination by Mr. Stogner 15	
11		
12	Certificate of Reporter 18	
13	·	
14	EXHIBITS	
15	Reference	
16	Exhibit No. 1	
17	Exhibit No. 2	
18	Exhibit No. 3	
19	Exhibit No. 4	
20	Exhibit No. 5	
21	Exhibit No. 6	
22	Exhibit No. 7	
23		
24		
25		

1 EXAMINER STOGNER: Call this hearing to order, Docket No. 42-92. As far as I know, this 2 is the last hearing for 1992. 3 Please note, today's date is December 17th. I'm Michael E. Stogner, appointed Hearing 5 6 Examiner for today's cases. We're going to go a little out of order 7 and at this time I'll call Case No. 10633. 8 MR. STOVALL: Application of Conoco, 9 Inc., for an unorthodox oil well location, North 10 Dagger Draw-Upper Pennsylvanian Pool, Eddy 11 12 County, New Mexico. EXAMINER STOGNER: Call for 13 14 appearances. MR. KELLAHIN: If the Examiner please, 15 16 I'm Tom Kellahin of the Santa Fe law firm of Kellahin and Kellahin appearing on behalf of the 17 18 Applicant, and I have one witness to be sworn. 19 EXAMINER STOGNER: Any other appearances? Will the witness please stand to be 20 21 sworn at this time. 22 [And the witness was duly sworn.] 23 EXAMINER STOGNER: Mr. Kellahin. 24 MR. KELLAHIN: Thank you, Mr. Examiner. Conoco's application in the North 25

Dagger Draw-Upper Pennsylvanian Pool is for an 1 unorthodox oil well location. It is unorthodox 2 3 insofar as it crowds an interior 40-acre tract within the 160-acre spacing unit. We're required by the rules to present this at a hearing. 5 I have one witness, Mr. Bill Hardie, who is a geologist for Conoco. 7 8 BILL HARDIE 9 Having been first duly sworn upon his oath, was examined and testified as follows: 10 EXAMINATION 11 12 BY MR. KELLAHIN: 13 Q. Mr. Hardie, for the record, would you please state your name and occupation? 14 My name is Bill Hardie. I'm a 15 geologist with Conoco, Inc. 16 On prior occasions, Mr. Hardie, have 17 Q. 18 you testified and been qualified as an expert petroleum geologist before the Division? 19 Yes, I have. 20 Α. 21 Pursuant to your employment as a 22 geologist, have you made a study of the proposed 23 location within Section 18 of this particular 24 area, Township 19 South, Range 25 East?

Yes, I have.

25

Α.

- Q. The proposed well location is a well to be drilled in the North Dagger Draw-Upper Pennsylvanian oil pool?
 - A. That is correct.

MR. KELLAHIN: We tender Mr. Hardie as an expert petroleum geologist.

EXAMINER STOGNER: Mr. Hardie is so qualified.

- Q. Mr. Hardie, let me ask you, sir, to take what is marked as Exhibit No. 1, and orient the Examiner as to the information shown on that display.
- A. This is a base map showing a portion of North Dagger Draw. The solid yellow indicates acreage that Conoco operates. The cross-hatch is acreage that our partners operate but we have an interest in.

Shown is the proposed unorthodox

Barbara Federal No. 16 location. It's in red in
the northwest quarter of Section 18. Also shown
are the operators of the contiguous blocks of
acreage that would be to the west and to the
north. And all those are Yates Petroleum,
although the unorthodox location does not really
encroach upon their acreage.

And then in the blue letters beside each of the surrounding wells, I've also shown the oil cum's for your reference. The proposed location, the Barbara Federal No. 16, is 1980 from the north and 1530 from the west.

- Q. Let me ask you to turn to Exhibit No. 2, which is the Form C-102, and specifically identify for this particular well what its footage location is proposed to be?
- A. Okay. That's the acreage dedication plat, and we propose to drill this well 1980 feet from the north and 1530 feet from the west line of the section. That's approximately, I think, about 300 feet to the west of an actual orthodox location.
- Q. The standard location would be 330 feet off of the interior quarter-quarter section lines?
 - A. That is correct.

- Q. You are 210 feet off the east side of the southeast of the northwest 40-acre tract?
 - A. That is correct.
- Q. Let me ask you now to turn to Exhibit

 No. 3, and identify that exhibit for us?
- A. Exhibit No. 3 is of the same section

we're looking at, Section 18. On it I've placed several of the surface features that inhibit the placement of well locations. I've also shown the actual orthodox location in the cross-hatched areas, and then the green line indicates the northern limit of the reservoir Dagger Draw.

I've prepared this exhibit to show what our options are in placing locations in the northwest quarter of Section 18. As you can see, two of those orthodox locations, the two northern ones, lie outside of the reservoir. They're pretty much out of the question.

So it comes down to the south half of the northwest quarter. We have two choices there. The one in the southwest quarter, we will show in later exhibits, is encountering a thinner portion of the reservoir and is also encountering a portion of the gas cap, so we want to avoid that.

We'll also show that the location in the southeast of the northwest is too close to the Barbara Federal No. 5, and we want to avoid any drainage situations that may have been caused by the Barbara Federal No. 5 as well as any potential formation damage caused by stimulation

techniques that were performed on the Barbara
Federal No. 5.

Also shown on there are Yates' flow lines in the dashed lines, and they also restrict us to some degree as to where we can place the well.

- Q. Let's turn now, Mr. Hardie, to the geologic interpretations you have made that apply to this particular area. What is your first display?
- A. The first one is Exhibit No. 4. Exhibit 4 is actually a combination of two maps, the first of which is a structural map on the top of the Cisco formation, and that's shown by the red contours. Those contours indicate that the formation dips gently to the east, so that if we were to attempt to avoid the gas cap, clearly we would want to stay as far downdip as we possibly can. So this map indicates that we want to keep our proposed Barbara Federal No. 16 as far to the east as possible.

The other portion of the map is a color-filled contour on the dolomite reservoir itself, and that ranges in thickness from zero, at its flanks, to upwards of 350 feet thick at

the core. This map also shows that as we move to the east and to the south, we would encounter thicker portions of the reservoir and, of course, that's what we want to achieve with our unorthodox location.

- Q. Describe for us the significance of the change in the color and the shading on Exhibit
- A. As the dolomite gets thicker, the shades go from lighter blue to darker blue. The darker color is indicating thicker portions of the reservoir.
- Q. Is there a relationship between well productivity and thickness?
- A. Most definitely. The poorer performing wells along this part of the field are inevitably the ones that have thinner pay. Anything we can do to achieve a thicker—to penetrate a thicker portion of the reservoir would help us to more efficiently drain.
- Q. When you look at the two northern drilling windows that are standard drilling windows within the spacing unit, those are located beyond the limit of the dolomite?
 - A. That is correct. They would

undoubtedly be dry holes.

- Q. Then you look at the drilling window that's at a standard location in the southwest portion of the spacing unit, and using Exhibit 4, then, summarize for us why the proposed unorthodox location is preferable to that standard location?
- A. Okay. If we were to drill in the southwest of the northwest quarter, we would encounter a thinner pay zone. The pay would be approximately 50- to 60-feet thick at that location.

Not only that, but it would also be at an updip location, and some of the later exhibits will show that as we move updip we encounter a gas cap, and we want to avoid that. So obviously we want to keep the well as far east as we can.

We don't want to get it too close to the Barbara Federal No. 5, because the 5 has drained approximately 15 MBO and also had some rather unorthodox stimulation techniques applied that we feel may have frac'd either into the gas cap or into the water zone below. So we want to get it far enough away from the Barbara Federal 5 that we can avoid any formation damage that may

have been caused by that.

- Q. Let's turn now to Exhibit No. 5 and have you identify and describe this display?
- A. Not all of the reservoir in North

 Dagger Draw is filled with oil. A portion of it
 is filled with water and a portion of it is
 filled with gas. So this is a color fill contour
 map on the oil-filled portion of the reservoir.

 As the colors get darker green, that indicates
 thicker portions of the oil-filled reservoir.

Also shown on here is a dark green line that outlines the boundaries of the reservoir.

If you'll look along the western flank, you'll notice there's a wide area between the zero line on the oil isopachs and the edge of the fairway. That portion is completely gas-filled, so that is the gas cap over there on the western flank.

Once we encounter the zero contour on our oil-filled portion and begin moving to the east, we encounter more and more oil and less and less gas-filled portion of the reservoir.

This map shows that at our proposed location we would expect to encounter about 110 feet of oil-filled dolomite. If we were to move

the location farther west, that would gradually
get thinner and thinner.

- Q. Describe for me why you wouldn't more farther south and farther east within the spacing unit.
- A. We could have moved farther south as well, but the Barbara Federal No. 11 well, which is currently still producing, has a high production rate and a high estimated ultimate recovery. We feel like it's going to recover those reserves to the north of its location. We don't want to encroach upon the Barbara Federal No. 11.
- Q. Let me have you turn to your cross-section, Exhibit No. 6.
- A. Sure. Exhibit 6 is an east/west cross-section. The location of the cross-section is shown on the maps as well, if you want to refer to those. This is a cross-section using porosity logs across Sections 13 and 18.

On it, the shaded portions represent the dolomite fairway itself. If the shading is red, it indicates that the fairway is gas-filled. If the shading is green, it indicates that the reservoir is oil-filled.

As you can see, as we move to the west, the dolomite fairway gradually thins and then ultimately pinches out between the No. 5 Allison well and the No. 10 Allison well. At the same time it pinches out to the west, it also gains elevation in such a way that we encounter the gas cap.

The gas cap actually starts showing up at some point between the No. 10 Allison and the No. 5 Barbara Federal well. Our proposed Barbara Federal No. 16 shown in red, as you can see, we want to keep it as far east as possible in order to avoid the gas cap, and we want to keep it as far east as possible in order to encounter the thickest portion of the reservoir.

- Q. Were Exhibits 1 through 6 prepared or compiled under your direction and supervision, Mr. Hardie?
 - A. Yes, they were.

Я

- Q. In your opinion, will approval of this application be in the best interests of conservation, the prevention of waste and the protection of correlative rights?
 - A. Yes, it will.
 - Q. In your opinion, is this the optimum

location within this spacing unit, being the 160 acres in the northwest quarter of Section 18, in which to locate this well?

A. It is.

MR. KELLAHIN: That concludes my examination of Mr. Hardie. We move the introduction of his Exhibits 1 through 6.

For the record, Mr. Examiner, Exhibit 7 is our certificate of mailing. While we're not encroaching towards any of the offsets, we did notify Yates Petroleum Corporation, who is the adjoining operator to the west of the spacing unit.

That concludes our presentation.

EXAMINATION

BY EXAMINER STOGNER:

- Q. Mr. Hardie, you suggested that the well
 No. 5 had some unorthodox stimulation
 techniques. Do you want to elaborate a little
 more on that?
- A. No. 5 was drilled in 1976. This was a period of time when we really didn't understand the reservoir. It was drilled by Roger Hanks. It was pretty typical at that time to stimulate the wells with rather large acid jobs. I'm not

exactly sure about the volumes, but I know it's significantly more than we use now.

We feel like these large acid jobs had a tendency to frac into both the gas cap and the underlying water. I think that the high water rate on this well, on the initial potential, kind of confirms that. We wouldn't really expect to find that high of a water cut, typically, being this high in the reservoir.

- Q. When did Conoco take over the No. 5 well?
- A. We took over the No. 5 in 1980 when we purchased the field, and it was plugged prior to us taking it over. Reentering that wellbore is not really an option. It is, I believe, a five-inch casing.

We typically install electric submersible pumps in order to more efficiently drain these wells, and with that small casing, it's difficult to install those kinds of pumps.

EXAMINER STOGNER: Any other questions of this witness?

MR. KELLAHIN: No, sir.

EXAMINER STOGNER: Mr. Hardie may be

25 excused.

1	Anything further in Case 10633?
2	MR. KELLAHIN: No, sir.
3	EXAMINER STOGNER: If not, this case
4	will be taken under advisement.
5	(And the proceedings concluded.)
6	
7	
8	
9	
10	
11	
12	
13	I do hereby certify that the foregoing is
14	a complete restarts of the production of the pro
15	heard by me on / figures/
16	Oil Conservation Division
17	Oil Conservation Division
18	
19	
20	
2 1	
22	
23	
2 4	
25	
2 J	

CERTIFICATE OF REPORTER 1 2 STATE OF NEW MEXICO 3 SS. COUNTY OF SANTA FE 5 I, Carla Diane Rodriguez, Certified 6 Court Reporter and Notary Public, HEREBY CERTIFY 7 that the foregoing transcript of proceedings 8 before the Oil Conservation Division was reported by me; that I caused my notes to be transcribed 10 under my personal supervision; and that the 11 foregoing is a true and accurate record of the 12 13 proceedings. 14 I FURTHER CERTIFY that I am not a relative or employee of any of the parties or 15 attorneys involved in this matter and that I have 16 no personal interest in the final disposition of 17 18 this matter. WITNESS MY HAND AND SEAL December 23, 19 1992. 20 21 22 23

CCR No. 4

24