

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA GOVERNOR 1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

1

June 24, 1985

Case 8 654

OIL CONSULT

BARRETS OF

Mr. Jeff Taylor Oil Conservation Div. P.O. Box 2088 Santa Fe, NM 87501

Re: Carroll & Cornell

Cornell #9 L-12-29N-12W

Dear Jeff:

The referenced well was drilled on federal and between 12/19/46 and 4/27/48 and has never produced. The well was drilled to 4240 and is not cemented from the bottom of the Pictured Cliffs (about 2000') to surface. There are several domestic water wells within a radius of 2 miles which contain gas and are unusable.

I believe this well has a casing failure and is causing or contributing to the problem. Please docket a case calling for the estate of Claude M. Carroll, and all other interested parties to appear and show cause why the Cornell #9, located 1650 feet from the south line, and 330 feet from the west line of section 12-29N-12W, should not be plugged and abandoned in accordance with a Division approved plugging program.

The well had a federal bond, but USGS solicitors determined it was no longer valid.

Yours truly,

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Richard Stamets

John Keller, BLM Farmington

Well File

LEASE FOOD CE CED Est. 2 to 3 barrels distillate (aft. WWO)] PRODUCTIVE DEPTH OR INTERVAL 4 \$ \$ \$ 9 2. 2. 4. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.

REMARKS:

TOPS

SURFACE			DAKOTA S. S.	
OJO ALAMO S. S.	9	7 4	MORRISON FM.	
FARMINGTON S. S.				
PICTURED CLIFFS S. S			1862 1995	
MESAVERDE FM.	-	N excel s		
CLIFF HOUSE			3420	
MENEFEE			35 27	
PT. LOOKOUT			4 2 9.0	
MANCOS SHALE	©	70	4420	
and the state of t				