

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-021-20118
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	West Bravo Dome CDG Unit
8. Well No.	6
9. Pool name or Wildcat	West Bravo Dome
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4442'

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 OIL WELL  GAS WELL  OTHER CO2 Supply

2. Name of Operator  
 OXY USA Inc.

3. Address of Operator  
 P.O. Box 50250 Midland, TX. 79710

4. Well Location  
 Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
 Section 6 Township 18N Range 30E NMPM Harding County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: Yearly Bradenhead Test (SI Well) <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**WBDCDGU #6 - TD-2150' PBD-2100' PERFS-1935-2050'**

YEAR	DATE	TBG PSI	CSG PSI	BLEED DOWN TIME
1990	11/27	485	0	
1991	10/24	555	0	
1992				
1993				
1994				
1995				
1996				
1997				
1998				
1999				
2000				

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *David Stewart* TITLE Production Accountant DATE 11/26/91

TYPE OR PRINT NAME (XXXXXXXXXX) David Stewart TELEPHONE NO. 915-685-56C

(This space for State Use)

APPROVED BY *Ry E Johnson* TITLE DISTRICT SUPERVISOR DATE 12-9-91

AUTHORIZATION FOR MAINTENANCE IN SHUT-IN OR  
 TEMPORARY ABANDONMENT STATUS EXPIRES 10-24-92


WEST BRAVO DOME CARBON DIOXIDE UNIT #6  
1980' FNL & 1980' FEL SEC 6 T18N R30E

ELEVATION: KB: 4452'  
GL: 4442'

8 5/8" SURFACE CASING @ 612'  
CMTD W/ 500 SX CNT. CIRC.

1 - 2 3/8" SN	1.10
1 - 2 3/8" X 5 1/2" GUB UNI VI	6.00
59 - JTS 2 3/8" 4.7# J55 TBG	1873.94
<b>TOTAL</b>	<b>1881.04</b>
<b>KB</b>	<b>9.80</b>
<b>SET AT</b>	<b>1890.84</b>

	SURFACE	PRODUCTION	TUBING
SIZE	8 5/8"	5 1/2"	2 3/8"
WEIGHT	24 #	14 #	4.7 #
GRADE	K-55	K-55	J-55
THREAD	ST&C	ST&C	6rd EUE
DEPTH	612'	2150'	1891'



5 1/2" PACKER @ 1891'

TUBG PERFS (1935'- 2050')

PBTD @ 2100'  
5 1/2" CS6 @ 2150' CMTD W/ 660 SX  
TD @ 2150' CNT CIRC

PREPRD BY: JOE M. FLEMING  
DATE: MAY 15, 1991