

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER- **Carbon Dioxide**

7. Unit Agreement Name

Name of Operator

Texaco Inc.

8. Form or Lease Name

C. T. Click NCT-1

Address of Operator

P. O. Box 728, Hobbs, New Mexico 88240

9. Well No.

Location of Well

UNIT LETTER **G** **1980** FEET FROM THE **North** LINE AND **1980** FEET FROM

10. Field and Pool, or Wildcat

Undesignated

THE **Last** LINE SECTION **34** TOWNSHIP **28-N** RANGE **28-E** N.M.S.M.

15. Elevation (Show whether DF, RT, GR, etc.)

6772' (GR)

12. County

Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

PLUG AND ABANDON

REMEDIAL WORK

ALTERING CASING

TEMPORARILY ABANDON

CHANGE PLANS

COMMENCE DRILLING OPNS.

PLUG AND ABANDONMENT

PULL OR ALTER CASING

OTHER

CASING TEST AND CEMENT JOB

OTHER **Shut In Well**

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth 3183'

9 5/8" OD 32# & 36# K-55 CSG SET @ 397'

7" OD 20# K-55 CSG SET @ 1534'

1. Drill to 3183:

2. Temporarily Abandon Well (Abandoned - Salvage Deferred), 12/2/80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]*

TITLE **Asst. Dist. Supt.**

DATE **12/2/80**

APPROVED BY *[Signature]*

TITLE **SENIOR PRODUCTION GEOLOGIST**

DATE **12/19/80**

CONDITIONS OF APPROVAL, IF ANY: