## Collins, Karen, EMNRD

**From:** Billings, Bradford, EMNRD

Sent: Tuesday, September 22, 2020 4:09 PM

**To:** Bynum, Tom (Contract)

Subject: RE: [EXTERNAL] RE: NDEV1541 - Shinnery 14 Fed 33

Hello, 09/22/2020

Tom Bynum - Devon

Regarding the above indicated incident nDEV1541, the following:

Site is closed in data base as of today. Please keep a copy of this communication as no paper copy will follow. Thank you for your time.

Sincerely,

Bradford Billings EMNRD/OCD

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations

From: Bynum, Tom (Contract) <Tom.Bynum@dvn.com>

Sent: Tuesday, September 22, 2020 1:00 PM

To: Billings, Bradford, EMNRD < Bradford. Billings@state.nm.us>

**Cc:** Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Eads, Cristina, EMNRD <Cristina.Eads@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Smith, Cory, EMNRD <Cory.Smith@state.nm.us>; Marcus, Ramona, EMNRD <Ramona.Marcus@state.nm.us>; Robison, Jason

<Jason.Robison@dvn.com>; Davis, Amanda <Amanda.Davis@dvn.com>; Mathews, Wesley

<Wesley.Mathews@dvn.com>; Carrasco, Lupe <Lupe.Carrasco@dvn.com>; DeHoyos, Kendra

<Kendra.DeHoyos@dvn.com>; Chris Jones <chris@pimaoil.com> Subject: [EXT] RE: [EXTERNAL] RE: NDEV1541 - Shinnery 14 Fed 33

I appreciate you sir!

## Thank you,

TOM BYNUM EHS CONTRACTOR 580-748-1613

<sup>&</sup>quot;Nothing has ever been resolved by continually pointing out the problem."

From: Billings, Bradford, EMNRD < <a href="mailto:Bradford.Billings@state.nm.us">Bradford.Billings@state.nm.us</a>>

Sent: Tuesday, September 22, 2020 12:59 PM

To: Bynum, Tom (Contract) <Tom.Bynum@dvn.com>

**Cc:** Venegas, Victoria, EMNRD < <u>Victoria.Venegas@state.nm.us</u>>; Eads, Cristina, EMNRD < <u>Cristina.Eads@state.nm.us</u>>; Hamlet, Robert, EMNRD < <u>Robert.Hamlet@state.nm.us</u>>; Bratcher, Mike, EMNRD < <u>mike.bratcher@state.nm.us</u>>; Smith, Cory, EMNRD < <u>Cory.Smith@state.nm.us</u>>; Marcus, Ramona, EMNRD < <u>Ramona.Marcus@state.nm.us</u>>; Robison, Jason

<Jason.Robison@dvn.com>; Davis, Amanda <Amanda.Davis@dvn.com>; Mathews, Wesley

<Wesley.Mathews@dvn.com>; Carrasco, Lupe <Lupe.Carrasco@dvn.com>; DeHoyos, Kendra

<Kendra.DeHoyos@dvn.com>; Chris Jones <chris@pimaoil.com>

Subject: [EXTERNAL] RE: NDEV1541 - Shinnery 14 Fed 33

Hello,

I will take care of this one today as well and let you know.

Bradford Billings EMNRD/OCD

From: Bynum, Tom (Contract) < <a href="mailto:Tom.Bynum@dvn.com">Tom.Bynum@dvn.com</a>>

Sent: Tuesday, September 22, 2020 10:26 AM

**To:** Billings, Bradford, EMNRD < <a href="mailto:Bradford.Billings@state.nm.us">Bradford.Billings@state.nm.us</a>>

**Cc:** Venegas, Victoria, EMNRD < <u>Victoria.Venegas@state.nm.us</u>>; Eads, Cristina, EMNRD < <u>Cristina.Eads@state.nm.us</u>>; Hamlet, Robert, EMNRD < <u>Robert.Hamlet@state.nm.us</u>>; Bratcher, Mike, EMNRD < <u>mike.bratcher@state.nm.us</u>>; Smith, Cory, EMNRD < <u>Cory.Smith@state.nm.us</u>>; Marcus, Ramona, EMNRD < <u>Ramona.Marcus@state.nm.us</u>>; Robison, Jason

<<u>Jason.Robison@dvn.com</u>>; Davis, Amanda <<u>Amanda.Davis@dvn.com</u>>; Mathews, Wesley

<<u>Wesley.Mathews@dvn.com</u>>; Carrasco, Lupe <<u>Lupe.Carrasco@dvn.com</u>>; DeHoyos, Kendra

<Kendra.DeHoyos@dvn.com>; Chris Jones <chris@pimaoil.com>

Subject: [EXT] NDEV1541 - Shinnery 14 Fed 33

Good morning Mr. Billings sir,

I was wondering if there might be any other info surrounding this incident from 1990? I have not found where this specific well exists anywhere, and page 2 of this attachment shows the one and only well that comes up when I searched the ULSTR.

I would appreciate any help I could get on this one, have a great day sir!

## Thank you,

TOM BYNUM EHS CONTRACTOR 580-748-1613

"Nothing has ever been resolved by continually pointing out the problem."

Devon - General

Confidentiality Warning: This message and any attachments are only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system. This message was sent by a contractor of Devon

Energy Corporation or one of its affiliate or subsidiaries ("Devon") and does not convey that contractor has the actual, implied, or apparent authority to contract on behalf of Devon. No agreement with Devon shall be of any force or effect unless it is signed by a duly authorized representative of Devon.

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.