

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-007-200
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Vermejo Park 3117	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Coal Methane		8. Well No. 012-I	
2. Name of Operator Pennzoil Exploration & Production Company		9. Pool name or Wildcat Wildcat	
3. Address of Operator P.O. Box 2867, Houston, TX 77252			
4. Well Location Unit Letter <u>I</u> : <u>1883</u> Feet From The <u>South</u> Line and <u>668</u> Feet From The <u>East</u> Line Section <u>01</u> Township <u>31N</u> Range <u>17E</u> NMPM Colfax County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 8111 GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/04/91 Start of work.

1. Remove surface equipment. Pull tubing. Fill with water.
2. Clean out to 1500'. Place 50 sks (220') plug from 72" below to 150' inside casing w/class A @ 15.6 ppg. Fill to surface w/9.0 ppg gel mud.
3. Tagged top of plug @ 1252' (88' inside casing).
4. Place 13 sks (50') surface plug w/class A @ 15.6 ppg.
5. Place well marker, remove junk and debris from location.
6. All work completed 9/09/01.
7. Pipe left in well: 276' of 10 3/4" set @ 276' and 1340' of 7 5/8" set @ 1340'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Williamson TITLE Operations Superintendent DATE 9/11/91
TYPE OR PRINT NAME L. D. Williamson TELEPHONE NO. 376-2817

(This space for State Use)

APPROVED BY Ry E. Johnson DISTRICT SUPERVISOR DATE 9-20-91
CONDITIONS OF APPROVAL, IF ANY