

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-903
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
SANTA FE

5a. Indicate Type of Lease
State ☐ Free ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM O-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER-

Name of Operator
Trans Pecos Resources, Inc.

Address of Operator
800 Gessner, Suite 790, Houston, Texas 77024

Location of Well
UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 4 TOWNSHIP 9N RANGE 23E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Latigo Ranch Blk "C"

9. Well No.
1

10. Field and Pool, or Wildcat
Nikos V.

12. County
Guadalupe

15. Elevation (Show whether DF, RT, GR, etc.)
4994 K.B. 4982 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

PROVISE ABANDON ☐ CHANGE PLANS ☐

ALTER OR ALTER CASING ☐ OTHER ☒ Complete

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐ OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Remove and overhaul wellhead.
2. Swab. Test existing perforated interval (6746' to 6819')
3. Acid foam frac perforated intervals, if necessary.
4. Swab-test and shut-in.

This work to commence about 02-25-83.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Robert G. McKinney, President

DATE 2-15-83

Carl Whaley

TITLE

VISOR

DATE

2/28/83

CTIONS OF APPROVAL, IF ANY: