

C
O
P
Y

Box 1545
Hobbs, New Mexico
June 6, 1947

Mr. Cecil S. Ringle
3433 Purdue Place
Albuquerque, New Mexico

Dear Mr. Ringle:

In reply to your letter of June 5, 1947, our records show that you have a bond for a well to be drilled in Section 34, Township 6N, Range 4 E, in the SW $\frac{1}{4}$ NE $\frac{1}{4}$ NW $\frac{1}{4}$. This application calls for a well to be drilled in the NE $\frac{1}{4}$ NW $\frac{1}{4}$, so you would have to have a bond covering a well to be drilled on this location.

In order for me to approve this drilling permit it would require a Form C-103 showing that you had plugged and abandoned the well described above and the bond transferred to this location before I could approve this Notice of Intention to Drill.

I plan to come up that way about the 11th or 12th of June and will stop and see you then.

Very truly yours,

Oil & Gas Inspector

ROY:cg
cc: Mr. Lake J. Frazier
Box 942
Roswell, New Mexico

Mr. George Graham
Box 871
Santa Fe, New Mexico