

From: [Cliff Brunson](#)
To: [Bratcher, Mike, EMNRD](#)
Subject: OXY-Lost Tank 3 Federal #21 - Remediation Plan
Date: Wednesday, April 08, 2015 7:20:43 PM
Attachments: [Remediation Packet.pdf](#)

Mike,

Please find attached the remediation plan that we discussed this afternoon. Please review and let me know if this meets with your approval. The first page is the site diagram and I have marked the areas of excavation and back dragging. The data summary table, lab data, and initial C-141 follow the diagram.

Give me a call and let me know if you have any questions.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland St.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-Mail: cbrunson@bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.
