

**From:** Patterson, Heather, EMNRD  
**To:** ["Savoie, Tony A."; Bratcher, Mike, EMNRD](#)  
**Subject:** RE: PLU-212 (2RP-2871)  
**Date:** Tuesday, September 29, 2015 10:47:00 AM

---

**RE: BopCo \* PLU #212 \* 30-015-33915 \* 2RP-2871**

Tony,

**This closure request is approved.**

**OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.**

**If you have any questions or concerns, please contact me.**

**Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228**

---

**From:** Savoie, Tony A. [mailto:TASavoie@BassPet.Com]  
**Sent:** Monday, September 28, 2015 8:51 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Subject:** PLU-212 (2RP-2871)

Mike, Heather

This is not one of the sites discussed in March 2015 that had all of the different colors of spill areas. However it was on the north edge of the PLU-213 P&A well pad and reserve pit location.

During the excavation the pit liner was discovered, "not damaged".

I know this was discussed but cannot find the exact date of discussion to install the liner and overlap the edges of the lined pit material.

Thanks

Tony