

**From:** [Audra Burton](#)  
**To:** [Patterson, Heather, EMNRD](#)  
**Cc:** [Billy D](#)  
**Subject:** RE: Rohmer #1 SWD  
**Date:** Wednesday, October 07, 2015 9:15:19 AM  
**Attachments:** .msg  
Scan0004.pdf  
**Importance:** High

---

Here is where the leak went over the berm. Due to power head switch di not kick in. Computer did not kick in. Froze the system. We how ever built a higher berm.

*Audra L. Burton*  
Operations Assistant-New Mexico  
110 S. Halagueno Ste 1  
Carlsbad, NM 88220

Office/ cell #432-448-5323  
Fax# 575-689-8323  
[audra@pyotewatersystems.com](mailto:audra@pyotewatersystems.com)