From:	Patterson, Heather, EMNRD
To:	"Laird, Zackary"; Tucker, Shelly
Cc:	Taylor Jones; Bratcher, Mike, EMNRD
Subject:	RE: WPX E&P Spill Notification
Date:	Wednesday, December 16, 2015 8:24:00 AM

RE: WPX (RKI) * North Brushy Draw Fed 35-6H * 30-015-42293 * 2RP-3278

The OCD concurs with BLM approval of this work plan.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Laird, Zackary [mailto:Zackary.Laird@wpxenergy.com]
Sent: Friday, October 23, 2015 9:50 AM
To: Tucker, Shelly; Patterson, Heather, EMNRD
Cc: Taylor Jones
Subject: RE: WPX E&P Spill Notification

Shelly/Heather,

After further consideration and discussion with EnviroClean, we feel that the previous proposed work plan that contemplated a "dig & haul" clean-up, will likely not achieve the minimal surface damage desired for the clean-up. EnviroClean has proposed an alternative in-place remediation option; this option is described in the attached, updated work plan.

Please let me know if this work plan meets with both of your approval, or if we need to proceed with the dig & haul option. Please call me with questions and/or to discuss.

Thanks in advance!

Zack Laird | Sr. EHS Manager **WPX Energy, Inc.** 210 Park Avenue, Suite 700 | Oklahoma City, OK 73102 <u>405.987.2213</u> (o) | <u>405.742.2696</u> (m) | <u>Zackary.Laird@wpxenergy.com</u> From: Tucker, Shelly [mailto:stucker@blm.gov] Sent: Thursday, October 08, 2015 3:29 PM To: Zackary Laird Cc: Heather.Patterson@state.nm.us; Taylor Jones Subject: Re: WPX E&P Spill Notification

Afternoon... After review of your proposal, BLM has the following stipulations:

1. The other "fingers" will need to be sampled and addressed.

2. Need to attempt to achieve minimal surface damage while removing contaminated material.

3. The area that is stained (nondetect areas) will still need to be tilled or turned under in some way. Trying to prevent in possible future issues with vegetation regrowth and or cosmetic (i.e. a lay person walking around and coming across the stain and raising an issue where there is none).

4. Need to reseed the area with a 50/50 mix of BLM Seed Mix 3 and BLM Seed Mix 4.

5. Samples will also need to be gathered in any pooling areas (even if they do not fall into you "100 foot sample point distance."

Please keep me updated as to status of cleanup.

The BLM approval/acceptance does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J'Tucker

Environmental Protection Specialist Bureau of Land Management

620 E. Greene St Carlsbad, NM 88220

575.234.5905 - Direct

575.361.0084 - Cellular

<u>stucker@blm.gov</u>

?

On Thu, Sep 17, 2015 at 4:19 PM, Zackary Laird <<u>ZLaird@rkixp.com</u>> wrote: Shelly/Heather,

Please see attached OCD form C-141 for a spill occurring at the WPX(RKI) operated N Brushy Draw Federal 35-6H well in Eddy County, NM today (API # 30-015-42293).

Shelly, I was told that Tyke with WPX, contacted you earlier today and that you were able to walk the location with him, is that correct?

Please let me know if you have any questions.

Regards,

Zack Laird | Sr. EHS Manager **WPX Energy, Inc.** 210 Park Avenue, Suite 700 | Oklahoma City, OK 73102 <u>405.987.2213</u> (o) | <u>405.742.2696</u> (m) | <u>ZLaird@rkixp.com</u>

This email is confidential. If you believe it has been sent to you in error, then do not read it, do notify the sender you have received it, and delete it. Email transmissions cannot be warranted to be secure or error-free as information could be intercepted, misdirected, corrupted, lost, incomplete, destroyed or containing viruses. The sender therefore cannot guarantee the integrity or security of this email or any file(s) included herewith. RKI and the sender hereby disclaim any and all liability for injury or damages that may result from the recipient(s) receipt or transmission of this email and any file(s) included herewith or reliance on the contents thereof. Any oilfield equipment, materials or services ordered by or provided to RKI or its affiliates in connection with this message shall be governed by RKI's Terms and Conditions of Purchase (a copy of which may be found at <u>www.rkixp.com</u>) and such Terms and Conditions of Purchase are hereby incorporated and expressly made a part hereof. A paper copy of RKI's Terms and Conditions of Purchase will be provided upon your written request.