RE: Bopco \* PLU CVX JV PC #12H \* 30-015-40126 \* 2RP-3430

Bradley,

This proposed work plan is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]
Sent: Wednesday, December 16, 2015 7:56 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: PLU CVX JV PC 012H

All,

BOPCO EHS was notified of a release that occurred at the PLU PC 16 State 1 (12-3-15). The threads on a 45 elbow failed releasing fluid to the lined containment and a small area outside of containment. A contract gang replaced the failed equipment. The liner was power washed and fluid was recovered, I would like to propose surface removal of saturated soils and proceed with backfilling. Attached you will find the supporting documentation, let me know if you have any questions or concerns. Thank you.

15 barrels oil was released into lined containment. All fluid was recovered

3.5 barrels oil released outside containment and 1.5 barrels oil recovered.

Brad Blevins Remediation Foreman BOPCO, LP 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office-575-887-7329 Cell-1-432-214-3704 <u>bblevins@basspet.com</u>