

From: [Patterson, Heather, EMNRD](#)
To: [Christopher Jones@oxy.com](mailto:Christopher_Jones@oxy.com)
Cc: [Bratcher, Mike, EMNRD](#); [Morales, Tony, EMNRD](#)
Subject: FW: SHUGART 6 COM 001
Date: Tuesday, June 09, 2015 6:19:00 AM
Attachments: 005.jpg
001.jpg
002.jpg
003.jpg
004.jpg

Mr. Jones,

Here are the photos of the leak I called you about yesterday.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

-----Original Message-----

From: Morales, Tony, EMNRD
Sent: Monday, June 08, 2015 3:55 PM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD; Dade, Randy, EMNRD; Morales, Tony, EMNRD
Subject: SHUGART 6 COM 001

MR. BRATCHER

FYI. TANK BATTERY LEAK. LEAK ACTIVE

SUGART 6 COM 001 32.7787417/103.9029735 30-015-31144-00-00. MIDDLE TANK ACTIVE LEAK. LEAK WAS FLOWING AND PONDING WEST OF LOCATION. SPOKE TO TERESA JACKSON, OXY AT ABOUT 1:45PM ABOUT LEAK. SHE STATED SHE WOULD GET SOMEONE TO TAKE CARE OF LEAK.

Your message is ready to be sent with the following file or link attachments:

005.jpg
001.jpg
002.jpg
003.jpg
004.jpg

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.



OXY USA INC.

SHUGART 6 FED. COM. #1

SEC. 6, T18S, R31E

1810' FNL & 880' FEL

EDDY CO., NM NM-68039



LESSER PRAIRIE CHICKEN









3
2
CORROSION
GHS

924075

18-1
62601

2
GHS

2
GHS

112284

6192

1-C

2
GHS

2
GHS

3
2
CORROSION
GHS

924075

62601

2
GHS

112284

6192

1-C