

From: Dakota Neel
To: [Patterson, Heather, EMNRD](#); James.Amos@blm.gov; [Bratcher, Mike, EMNRD](#); stucker@blm.gov
Cc: [Robert McNeill](#)
Subject: (Notification) ADMIRAL FEDERAL COM #002H (30-015-42820)
Date: Thursday, October 20, 2016 1:48:59 PM
Attachments: image003.png

Mr. Bratcher/Ms. Tucker,

COG Operating LLC is reporting a release on the ADMIRAL FEDERAL COM #002H (30-015-42820)

Unit O Section 28 Township 25S Range 29E

The release occurred at approximately 7:00 am on 10-18-2016

Estimated Released: Approx. 355 bbls of Oil

Estimated Recovered: Approx. 350 bbls of Oil

This release was contained within the falcon lined facility. The release was caused by an equalizer valve being in the wrong position. The area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Dakota Neel
HSE Coordinator
COG Operating LLC
Cell: [432-215-2783](tel:432-215-2783)
dneel2@concho.com

[2407 Pecos Ave.](#)
[Artesia , NM 88210](#)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.