

**From:** Patterson, Heather, EMNRD  
**To:** "[Brenda Martin](#)"  
**Subject:** RE: API 30-015-26095  
**Date:** Monday, September 19, 2016 9:03:00 AM

---

Brenda,

As per OCD rules, your C-141 initial is due within 15 days from the date of discovery. You are now past due and I have not received an update on what you discovered at this location. If you sent something earlier, I apologize. My email has been sporadically down, with no indication as to what I may have lost! Please send an update and a C-141 as soon as you can.

Thanks,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

-----Original Message-----

From: Brenda Martin [<mailto:bmartin@beachexp.com>]  
Sent: Tuesday, September 06, 2016 2:54 PM  
To: Patterson, Heather, EMNRD  
Subject: RE: API 30-015-26095  
Importance: High

Heather,

I am checking into what is going on and I will get back with you.

Thank you,

Brenda Martin  
Production  
Beach Exploration, Inc.  
800 North Marienfeld  
Suite 200  
Midland, Texas 79701  
(432) 683-6226 Telephone  
(432) 683-1038 Fax  
e-mail: [bmartin@beachexp.com](mailto:bmartin@beachexp.com)

-----Original Message-----

From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]  
Sent: Tuesday, September 06, 2016 3:17 PM  
To: Brenda Martin  
Cc: Kasuboski, Robert; [agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us); Bratcher, Mike, EMNRD  
Subject: FW: API 30-015-26095

Brenda,

The State Land Office sent us these pics of a release at one of your locations. Looks like in addition to a spill, the open top tank is unnetted. Can you please look into this and let me know what you find.

Thanks,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

-----Original Message-----

From: Kasuboski, Robert [<mailto:rkasuboski@slo.state.nm.us>]  
Sent: Tuesday, September 06, 2016 10:49 AM  
To: Patterson, Heather, EMNRD; Groves, Amber  
Subject: API 30-015-26095

Howdy ,

Found this this am. Looks like injection well in use. Spill on pad and unnetted tank

Thank you,  
Robert

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---