

From: [Patterson, Heather, EMNRD](#)
To: "Blaney, Karolina"
Cc: [Bratcher, Mike, EMNRD](#); [Tucker, Shelly \(stucker@blm.gov\)](mailto:Tucker, Shelly (stucker@blm.gov)); [Crystal EMNRD Weaver \(Crystal.Weaver@state.nm.us\)](mailto:Crystal.Weaver@state.nm.us)
Subject: RE: WPX RDU 11 - C-141
Date: Thursday, December 01, 2016 1:24:00 PM
Attachments: 1.coa 4001.pdf

RE: WPX * RDU #11 * 30-015-24307 * 2RP-4001

Karolina,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4001.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Thursday, November 17, 2016 2:26 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'
Subject: RE: WPX RDU 11 - C-141

Attached is C-141 for the RDU 11 spill.
Thank you and have a great afternoon,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Sunday, November 06, 2016 11:09 AM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: WPX RDU 11 - spill notification

Good morning,

Yesterday, 11/5/16, WPX had a spill at the RDU 11 well pad, API # 30-015-24307; T26S R30E S22. The

cause of this spill is equipment failure. A pump air locked causing tank to overfill. 66 bbls of oil was recovered from a dirt SPCC containment berm; none of the fluids have left the containment. The C-141 report will be submitted within 15 days from the incident.

Please let me know if you have any questions or concerns.

Thank you and have a great Sunday.

Karolina Blaney

Environmental Specialist

WPX Energy

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com