From: Bratcher, Mike, EMNRD

To: Pruett, Maria, EMNRD

Subject: FW: Ghostrider 25/36 W0DM Fed Com #2H Date: Thursday, September 13, 2018 4:56:34 PM

Attachments: image001.png image002.png

2RP-4781 Work Plan - Mewbourne Ghostrider - RXSoil 08092018 (2).pdf

From: Zack Thomas <zthomas@mewbourne.com>

Sent: Thursday, August 30, 2018 9:22 AM

To: Pruett, Maria, EMNRD < Maria. Pruett@state.nm.us>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Griswold, Jim, EMNRD

<Jim.Griswold@state.nm.us>; Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>

Subject: Ghostrider 25/36 W0DM Fed Com #2H

Good Morning Maria & Mike,

Attached is RxSoil's bioremediation work plan for 2RP-4781. We are also considering a standard dig and haul, with a liner in the 4 foot area (red area on leak map). Cost will determine which remediation we want to pursue. Please review plan and let me know if we have characterized the site well enough to perform either type of remediation. Thanks!

Zack Thomas

Environmental Rep. Mewbourne Oil Company PO Box 5270

Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: <u>zthomas@Mewbourne.com</u>

