

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-32888

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement
Name:

Otis 1

RECEIVED

MAY 21 2004

8. Well No.
#2

9. Pool name or Wildcat
Carlsbad; Morrow, East

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Mewbourne Oil Company 14744

3. Address of Operator

PO Box 5270 Hobbs, NM 88241

4. Well Location

Unit Letter K : 1980 feet from the South line and 1400 feet from the West line

Section 1 Township 22S Range 27E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3089'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒ Recomplete Atoka

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Temporary abandon Morrow perforations @ 11582-11771'. Test Atoka Lime @ 11166-11436'.

04/03/04...ND BOP. NU tree. POOH w/tbg and BHA. RIH w/CIBP, CCL & set @ 11532'. Place 50' cement on CIBP. New PBTD @ 11482'.

04/06/04...RIH w/gamma ray & CCL to perforate Atoka @ 11166'-436' (76 holes, 38', 2 SPF, 21.5" Penetration, 0.41" EHD, 23 GC, 120 Phasing). Wireline set pkr @ 11025'.

04/07/04...RIH w/tbg. Latched onto pkr and spaced out. ND BOP. NU tree. Swab and flow test well.

04/09/04...Acidized Atoka @ 11166-436 w/10,000 gals 20% NeFe acid & ball sealers. Swab and flow test. PWOL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Hobbs District Manager DATE 05/19/04

Type or print name NM Young Telephone No. 505-393-5905

(This space for State use)

FOR RECORDS ONLY

APPROVED BY [Signature] TITLE [Signature] DATE MAY 21 2004

Conditions of approval, if any: