

Oil Cons.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Chevron USA, Inc.

3. Address and Telephone No.

15 Smith Rd. Midland, TX 79705

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

U.L. 84 1650 FNL 1650 FEL
Sec 8 TS 22-S R 23-E

5. Lease Designation and Serial No.

NM-045272

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Bolge Flats Unit A COM

Well Name and No.

6

9. API Well No.

30-01510578

10. Field and Pool, or Exploratory Area

Indian Basin Upper Penn

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RIH Tag 5 1/2 CIBP @ 6550 spot 25sx plug fr/6550-6350(Penn)Tag @ 6290
2. Displace hole w/25# Gel p/BB1 9.5# Brine
3. Perf 4 holes @ 4200 unable to sqz spot 30sx plug fr/4250-4000(2000 Internal plug Tag @ 4018 (ok w/BLM)
4. Perf 4 holes @ 2400 sqz perf w/50sx fr/2400-2100(9 5/8 shoe)Tag @ 1954
5. Perf 4 holes @ 1200 sqz perf w/50sx fr/1200-1000(T-salt)Tag @ 910
6. Perf 4 holes @ 275 circ cmt 5 1/2 X 7 X 9 5/8 csg w/100sx fr/275 to surf(13 3/8 shoe) Tag @ surf
7. Install dry hole marker 2-19-03

Approved as to plugging of the well bore,
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Title MANAGER/SUNSET

Date 2-19-03

(This space for Federal or State office use)

(ORIG. SGD.) ALEXIS C. SWOBODA

Title PETROLEUM ENGINEER

Date MAR 13 2003

Approved by
Conditions of approval, if any: