

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88248
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-32176
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator MURCHISON OIL & GAS, INC.		6. State Oil & Gas Lease No. E-9782
3. Address of Operator 1100 MIRA VISTA BLVD. PLANO, TX. 75093-4698		7. Lease Name or Unit Agreement Name: HUGGIE BEAR ST. COM.
4. Well Location Unit Letter <u>H</u> : <u>1420</u> feet from the <u>NORTH</u> line and <u>990</u> feet from the <u>EAST</u> line Section <u>2</u> Township <u>17S</u> Range <u>28E</u> NMPM County <u>EDDY</u>		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3383' RKB 3405'		9. Pool name or Wildcat CROW FLATS MORROW

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Spud well 0600 4/1/03 and drill a 17-1/2" hole to 215'. Ran 13-3/8" casing as follows:

Shoe	1'
1 Jt 13-3/8" 68 #/FT J-55 Butt	30'
Insert Float	
6 Jts 13-3/8" 68 #/FT J-55 Butt	187'
	218'

Casing set @ 210'. Cement w/ 250 SXS CL "C" + 2% CACL + 1/4 #/SX Cellofiake. Circulate 50 SXS to reserve pit. Plug down @ 1700 HR 4/1/03. Floats held. WOC 4 Hr. Cut off conductor and weld on head. Test to 500 PSI. Nipple up BOP. Test BOP to 500 PSI. Pick up BHA and TIH. WOC total 18 Hr. Drill cement & plug. Test casing to 500 PSI. Resume drilling 12-1/4" hole.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael S. Daugherty TITLE V P OPERATIONS DATE 4/4/03

Type or print name MICHAEL S. DAUGHERTY Telephone No. (972) 931-0700

(This space for State use)

APPROVED BY William W. Burns TITLE District Supervisor DATE APR 9 2003

Conditions of approval, if any: