

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-01615

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-5084

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Red Lake Sand Unit

1. Type of Well:

Oil
Well ☒

Gas
Well ☐

Other

RECEIVED

2. Name of Operator

Mack Energy Corporation

FFR 13 2004

8. Well No.

9

3. Address of Operator

P.O. Box 960, Artesia, NM 88211

OCD-ARTESIA

9. Pool name or Wildcat

Red Lake; Queen-Grayburg-SA

4. Well Location

Unit Letter A : 330 Feet From The North Line and 330 Feet From The East Line

Section 30 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RCB, RT, CR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-26-04 Spot 25 sx cmt. @ 1708'.

1-27-04 Tag plug @ 1530'.

1-27-04 Circ. hole w/ mud.

1-27-04 Perf. 4 holes @ 505' set pkr. @ 125', sqz. 35 sx cmt. tag plug @ 380'.

1-27-04 Perf. 4 holes @ 350' set pkr. @ 62', sqz. 35 sx cmt. Displaced cmt. to 250'.

1-27-04 Perf. 4 holes @ 60', pump 20 sx cmt. down 7" to surface out of 8-5/8" csg.
Leave 7" full of cmt.

1-28-04 Tag plug @ 6'.

1-18-04 RDMO. Cut off wellhead, install dry hole marker, & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. Massey TITLE Agent DATE 2-09-04

TITLE OR PRINT NAME Roger Massey TELEPHONE NO. 432-530-0907

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE OCT 21 2004



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenberg

Director

Oil Conservation Division

16 February 2004

Mack Energy Corp.

P. O. Box 960

Artesia, New Mexico 88221-0960

RECEIVED

OCT 15 2004

OCD-ARTESIA

Form C-103 Report of Plugging for your Red Lake Sand Unit #9 A-30-17-28 API 30-015-01615
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to
indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in
concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name,
well number and location including quarter/quarter section or unit letter, section, township, range and API
well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been
cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☐ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been
leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for
plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and
returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and
approval.

Perry W. Shell
Name

Protection Clerk
Title

Van Barton
Field Rep. II