

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	3001521071
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-4655
7. Lease Name or Unit Agreement Name	Bandit State
8. Well Number	#1 SWD
9. OGRID Number	18917
10. Pool name or Wildcat	Carlsbad Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Saltwater Disposal ☐

2. Name of Operator

Read & Stevens, Inc.

3. Address of Operator

PO Box 1518, Roswell, NM 88202

4. Well Location

Unit Letter _____ : _____ 1980 _____ feet from the _____ North _____ line and _____ 2021 _____ feet from the _____ West _____ line

Section 10 Township 23S Range 26E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3331' KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mll Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: Casing Mechanical Integrity Test ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Re-enter well by drilling out plugs to 3800'. Set CIBP w/10' cement on top at 3790'. Perforate 3430' - 60', 3480' - 3510', 3545' - 75'. Total of 340 holes. Acidize w/3000 gallons 15% NEFe HCl. Fracture stimulate w/121,000# 12/20 brown sand. Set packer at 3346'. Run 108 joints 2 3/8" fiberglass tubing for injection string. Flange wellhead. RU pump truck w/1000# pressure spring and one hour chart. Pressure casing/tubing annulus to 500# and hold for 30 minutes. No leakage. Release pressure and open well for disposal. NMOCD representative Gerry Guye present and approved.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE William V. Pate TITLE Superintendent DATE October 7, 2004

Type or print name
For State Use Only

E-mail address: _____ Telephone No. _____

APPROVED BY: [Signature] TITLE Wild Sp ID DATE OCT 21 2004

Conditions of Approval (if any): _____

