

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

OCT 20 2004

OCU-ARTESIA

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other
2. Name of Operator
MARBOB ENERGY CORPORATION
- 3a. Address
PO BOX 227, ARTESIA, NM 88211-0227
- 3b. Phone No. (include area code)
(505) 748-3303
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

5. Lease Serial No.
NMNM0557371
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No.
AAO FEDERAL #5
9. API Well No.
30-015-32959
10. Field and Pool, or Exploratory Area
RED LAKE; QUEEN GRBG SA
11. County or Parish, State

1650 FNL 875 FWL, SEC. 1-T18S-R27E, UNIT E

EDDY CO., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|---|---|---|--|---|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input checked="" type="checkbox"/> Recomplete | <input type="checkbox"/> Other |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| | <input type="checkbox"/> Convert to Injection | <input checked="" type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

ADDED PAY IN THE SAN ANDRES AS FOLLOWS:

- 10/7/04 - SET CIBP @ 3300'. PERF THE UPPER SAN ANDRES @ 2131' - 2789' (24 SHOTS).
ACIDIZED W/ 4000 GAL NEFE 15% HCL ACID. SWAB TEST.
- 10/8/04 - FRAC THE UPPER SAN ANDRES @2131' - 2789' W/ 157,878 GAL CLEAN GEL &
268,000# PROPPANT. INJ RATE 75 BPM. AIP 2049#.
- 10/12/04 - PUT WELL ON PUMP.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

DIANA J. CANNON

Title PRODUCTION ANALYST

Signature

Date OCTOBER 19, 2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)