Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-32666	CT
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE	
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				aus Ecuse 110.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			9	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUGE PROPOSALS.)  1. Type of Well:			Gem Dandy (	BCG St Com
1. Type of Well:	(23° )	· 6/	,	
Oil Well Gas Well X Other / A State of the Control				
2. Name of Operator			8. Well No.	
Yates Petroleum Corporation			1	
3. Address of Operator			9. Pool name or Wildcat	
105 S. 4 <sup>th</sup> Street Artesia, NM 88210 \& C <sup>CV</sup>			Crow Flats Morrow	
3. Address of Operator 105 S. 4th Street Artesia, NM 88210				
4. Well Location				
This I show I all 1990 Cart Cart I South to 1 4/0 and 1 14/1				
Only Letter <u>L. 1760</u> feet from the <u>SOUIN</u> line and <u>660</u> feet from the <u>West</u> line				
Section 35 Township 16S Range 27E NMPM Eddy County				
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3418' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN			SÉQUENT REI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		ALTERING
		REWEDIAL WOR		CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. 🗌	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	ND	
	COMPLETION	CEMENT JOB		
OTHER:		OTHER: Perfora	te and stimulate	X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompilation.				
4/21/03 – Perforate Morrow 89	78'-9002' (145), 9046'-9050' (	25) for a total of	170 holes.	
4/22/03 – Acidize 9046'-9050' with 750 bbls 7-1/2% MSA acid with 37 ball sealers. Acidize 8978'-9002' with 1000g				
7-1/2% MSA acid with 218 ball sealers. Set packer at 8902'. Set RBP at 9095'.				
		•		
				•
11 1				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print name Ting Huerto	<b>1</b>		Telenhone No.	. 505-748-1471
(This space for State 156)				. 500 / 70 17/1
(14) die le le Ditité Sulevison MANO				
APPROVED BY	TITLE_	www.		_DATE   TAY 0 9 2003

APPPROVED BY Sear & Sum Conditions of approval, if any: