

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop

Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

16 May 2003

Dominion Exploration and Production 14000 Quail springs Parkway

Suite 600

Oklahoma City, Oklahoma 73134-2600

Form C-103 Report of Plugging for your Saragossa "19" State Com # 1 C-19-23-26 API 30-015-32144 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

indicate that the work has been accomplished and the location is r	ready for final inspection.
1. All pits have been filled and leveled.	
☐ 2. Rat hole and cellar have been filled and leveled.	
3. A steel marker 4" in diameter and approximately 4' above concrete to mark the exact location of the plugged well. (Marker well number and location including quarter/quarter section or unit well ID number permanently welded, stamped or otherwise engra	must have operator name, lease name, t letter, section township range and API
4. The location has been leveled as nearly as possible to original cleared of all junk and equipment.	inal top ground contour and has been
5. The dead men and tie downs have been cut and removed.	 A series of the control of the control
☐ 6. If a one well lease or last remaining well on lease, the batter leveled and cleared of all junk & equipment.	ery and burn pit locations have been
7. All environmental concerns have been addressed as per OC	CD guidelines.
The above are minimum requirements and no plugging bond will plugged and abandoned wells have been inspected and Form C-10	be cancelled until all locations for 3 approved.
When all of the work outlined above has been done, please notify returning this letter to us so that our representative will not have to	this office by completing, signing and make more than one trip to the location.
I certify that the above work has been done and the above-mention approval.	ned lease is ready for OCD inspection and
·	LSC
Name	Van Barton Field Rep. II