Submit 3 Copies To Appropriate District Office	State of New M	exico		Form C-103
District I	Energy, Minerals and Nat	ural Resources	WELL ADINO	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		* D. W. MOTO. 1	WELL API NO. 30-015-:	26561
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Le	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE	FEE X
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8	5/303	6. State Oil & Gas Lea	ase No.
87505				
SUNDRY NOT: (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)		LUG BACK TO A	7. Lease Name or Unit SARA AH	
	Gas Well Other	RECEIVED	8. Well Number #5	j
Name of Operator Yates Petroleum Corporati	on	JAN 1 9 2005	9. OGRID Number 0255	375
3. Address of Operator		DUMPTEDIA	10. Pool name or Wild	lcat
105 S. 4 th Street, Artesia,	NM 88210		DAGGER DRAW	UPPER PENN
4. Well Location Unit Letter N:	660 feet from the Sour	th line and 1	1,980 feet from the	West line
Section 11	Township 20S R	ange 24E	NMPM Eddy	County
	11. Elevation (Show whether Di			Committee of the Commit
Pit or Below-grade Tank Application	ar Cleanre 🗆			A Maria
		water well > 1 000? D	istanas Gram nagrast surface	water N/A
Pit type <u>Steel</u> Depth to Groundwat Pit Liner Thickness: mil	Below-Grade Tank: Volume		nstruction Material	water
12. Check A	Appropriate Box to Indicate 1	nature of Notice,	Report or Other Data	a
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPOR	RT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	_	ERING CASING
TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRI		ND A
	MOLITEL COME	CASHAGICEMEN	1300 🗆	
TOLE ON NEVER OF COMO				
OTHER:	_	OTHER: TEMPO	RARILY ABANDON	X
OTHER: 13. Describe proposed or comp	oleted operations. (Clearly state all	OTHER: TEMPO	d give pertinent dates, inc	X cluding estimated date
OTHER: 13. Describe proposed or comp	_	OTHER: TEMPO	d give pertinent dates, inc	X cluding estimated date f proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 1/2/05 – Notified BLM. Mov	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multi	OTHER: TEMPO pertinent details, and ple Completions: At	d give pertinent dates, ind tach wellbore diagram of	f proposed completion
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 1/2/05 – Notified BLM. Mov CWI.	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multi	OTHER: TEMPO pertinent details, and ple Completions: At	d give pertinent dates, ind tach wellbore diagram of DH w/ 287 rods. Pun	f proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 1/2/05 – Notified BLM. Mov CWI. 1/3/05 – NU BOP. Released	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multi	OTHER: TEMPO pertinent details, and ple Completions: At	d give pertinent dates, ind tach wellbore diagram of DH w/ 287 rods. Pun	f proposed completion
OTHER: 13. Describe proposed or composed or composed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD.	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg.	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC	d give pertinent dates, ind tach wellbore diagram of the W/ 287 rods. Pun tbg. RIH & set CIBI	f proposed completion nped was parted. P @ 7,590' using
OTHER: 13. Describe proposed or composed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released '15' KB. SD. 1/4/05 - RIH & cap CIBP w/	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg.	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4"	d give pertinent dates, ind tach wellbore diagram of the W/ 287 rods. Pun tbg. RIH & set CIBI	f proposed completion nped was parted. P @ 7,590' using
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 1/2/05 – Notified BLM. Mov CWI. 1/3/05 – NU BOP. Released 15' KB. SD. 1/4/05 – RIH & cap CIBP w/ Tested casing to 800# for 30 r	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH winnutes. BLM witnessed. SI	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" of tbg & circulated D.	d give pertinent dates, ind tach wellbore diagram of the W/287 rods. Pun tbg. RIH & set CIBI d 290 bbls 2% KCL &	f proposed completion nped was parted. P @ 7,590' using & inhibitor.
OTHER: 13. Describe proposed or composed or starting any proposed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to	pleted operations. (Clearly state all bork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface w	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. // KCL & inhibite	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion nped was parted. P @ 7,590' using winhibitor. The head. Well is
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 1/2/05 – Notified BLM. Mov CWI. 1/3/05 – NU BOP. Released 15' KB. SD. 1/4/05 – RIH & cap CIBP w/ Tested casing to 800# for 30 r	pleted operations. (Clearly state all bork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface w	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. // KCL & inhibite	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion nped was parted. P @ 7,590' using winhibitor. The head. Well is
OTHER: 13. Describe proposed or composed or starting any proposed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to	Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface wall is TEMPORARILY AB	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. // KCL & inhibite	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion nped was parted. P @ 7,590' using winhibitor. The head. Well is
OTHER: 13. Describe proposed or composed was or recompletion. 1/2/05 – Notified BLM. Mov CWI. 1/3/05 – NU BOP. Released 15' KB. SD. 1/4/05 – RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 – POOH laying down to temporarily abandoned. WEI	Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface wall is TEMPORARILY AB	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. v/ KCL & inhibite SANDONED ON	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion inped was parted. P @ 7,590' using with the inhibitor. head. Well is EPORT.
OTHER: 13. Describe proposed or composed was or recompletion. 1/2/05 – Notified BLM. Mov CWI. 1/3/05 – NU BOP. Released 15' KB. SD. 1/4/05 – RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 – POOH laying down to temporarily abandoned. WEI	Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface wall is TEMPORARILY AB	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. v/ KCL & inhibite SANDONED ON	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion inped was parted. P @ 7,590' using with the inhibitor. head. Well is EPORT.
OTHER: 13. Describe proposed or composed was or recompletion. 1/2/05 – Notified BLM. Mov CWI. 1/3/05 – NU BOP. Released 15' KB. SD. 1/4/05 – RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 – POOH laying down to temporarily abandoned. WEI	Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface wall is TEMPORARILY AB	OTHER: TEMPO pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. v/ KCL & inhibite SANDONED ON	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion inped was parted. P @ 7,590' using with the inhibitor. head. Well is EPORT.
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to temporarily abandoned. WEI Chart attached. Witnessed I hereby certify that the information	pleted operations. (Clearly state all bork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH with minutes. BLM with essed. SI bg. Loaded hole to surface was LIS TEMPORARILY ABOVE by BL M inspector.	other: tempo pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" // tbg & circulated D. // KCL & inhibite BANDONED ON	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion in ped was parted. P @ 7,590' using with inhibitor. head. Well is a port. CPORT.
OTHER: 13. Describe proposed or composed was or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to temporarily abandoned. WEI Chart attached. Witnessed I hereby certify that the information grade tank has been/will be constructed or	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH we minutes. BLM witnessed. SI bg. Loaded hole to surface we LL IS TEMPORARILY ABOUT DESCRIPTION.	other: tempo pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" of tbg & circulated D. w/ KCL & inhibite BANDONED ON	d give pertinent dates, ind tach wellbore diagram of the pertinent dates, indicated wellbore diagram of the pertinent dates, indicated dates,	f proposed completion inped was parted. P @ 7,590' using with a simple inhibitor. The head. Well is a second in the input of the inpu
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to temporarily abandoned. WEI Chart attached. Witnessed I hereby certify that the information	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH we minutes. BLM witnessed. SI bg. Loaded hole to surface we LL IS TEMPORARILY ABOUT DESCRIPTION.	other: tempo pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" of tbg & circulated D. w/ KCL & inhibite BANDONED ON	d give pertinent dates, ind tach wellbore diagram of the diagram o	f proposed completion inped was parted. P @ 7,590' using with a simple inhibitor. The head. Well is a second in the input of the inpu
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to temporarily abandoned. WEI Chart attached. Witnessed I hereby certify that the information grade tank has been will be constructed or SIGNATURE Type or print name Su'Ann R	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface was LIS TEMPORARILY ABOVE is true and complete to the closed according to NMOCD guidelines.	other: tempo pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" of tbg & circulated D. w/ KCL & inhibite BANDONED ON	d give pertinent dates, ind tach wellbore diagram of the pertinent dates, indicated wellbore diagram of the pertinent dates, indicated dates,	f proposed completion in ped was parted. P@ 7,590' using with a simple to the answer of the answer
OTHER: 13. Describe proposed or composed was or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to temporarily abandoned. WEI Chart attached. Witnessed I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface was LIS TEMPORARILY ABOVE is true and complete to the closed according to NMOCD guidelines.	other: tempo pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" of tbg & circulated D. w/ KCL & inhibite BANDONED ON	d give pertinent dates, ind tach wellbore diagram of the pertinent dates, indicated wellbore diagram of the pertinent dates, indicated and the pertinent dates. Pertinent dates and the pertinent dates and the pertinent dates and the pertinent dates. I description dates are pertinent dates, indicated and the pertinent dates. Pertinent dates are pertinent dates are pertinent dates are pertinent dates. Pertinent dates are pertinent dates are pertinent dates. Pertinent dates are pertinent dat	f proposed completion inped was parted. P@ 7,590' using with inhibitor. head. Well is CPORT. fify that any pit or below-ocd-approved plan
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 1/2/05 - Notified BLM. Mov CWI. 1/3/05 - NU BOP. Released 15' KB. SD. 1/4/05 - RIH & cap CIBP w/ Tested casing to 800# for 30 r 1/5/05 - POOH laying down to temporarily abandoned. WEI Chart attached. Witnessed I hereby certify that the information grade tank has been will be constructed or SIGNATURE Type or print name Su'Ann R	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple in & RU. NU BOP. Move TAC. POOH w/ 2-7/8" tbg. 35' cement (5 sacks). RIH wininutes. BLM witnessed. SI bg. Loaded hole to surface was LIS TEMPORARILY ABOVE is true and complete to the closed according to NMOCD guidelines.	other: tempo pertinent details, and ple Completions: At in steel pit. POC LD 10 jts 1-3/4" of tbg & circulated D. w/ KCL & inhibite BANDONED ON	d give pertinent dates, ind tach wellbore diagram of the pertinent dates, indicated wellbore diagram of the pertinent dates, indicated and the pertinent dates. Pertinent dates and the pertinent dates and the pertinent dates and the pertinent dates. I description dates are pertinent dates, indicated and the pertinent dates. Pertinent dates are pertinent dates are pertinent dates are pertinent dates. Pertinent dates are pertinent dates are pertinent dates. Pertinent dates are pertinent dat	f proposed completion inped was parted. P@ 7,590' using with inhibitor. head. Well is CPORT. fify that any pit or below-ocd-approved plan

