

Arrant, Bryan

From: Kem McCready [kemmm@naguss.com]
Sent: Wednesday, February 09, 2005 10:05 AM
To: barrant@state.nm.us
Subject: FW: Nadel Gussman - Josey Fed #1

Bryant, please see the following note on the Josey SFT from Halliburton. As you can see we did not run an SFT on the Josey.

Kem E. McCready

-----Original Message-----

From: Kevan Fuchs [mailto:Kevan.Fuchs@Halliburton.com]
Sent: Wednesday, February 09, 2005 10:52 AM
To: kemmm@naguss.com
Cc: James Haest
Subject: Nadel Gussman - Josey Fed #1

Kem, we did not run SFT on this well. The ticket shows the tool was on stand-by but I do not think the tool was run possibly do to hole conditions. If they did run it they forgot to charge you for it?

Your welcome James,

Kevan Fuchs

Midland – AFE-Applied Formation Evaluation

Halliburton Energy Services

4000 N. Big Spring Suite 200

Midland, TX. 79705

Office 432-683-0274

Cell 432-557-2156

Fax 432-683-0212

kevan.fuchs@halliburton.com

This email has been scanned by the MessageLabs Email Security System.
For more information please visit <http://www.messagelabs.com/email>

2/9/2005