

N.M. Oil Cons. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

RECEIVED

MAR 01 2005

Form 3160-5
(September 2001)

OC-D-ARTESIA

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

5. Lease Serial No.	NMNM12110
6. If Indian, Allottee or Tribe Name	
7. If Unit or CA/Agreement, Name and/or No.	NMNM110992
8. Well Name and No.	OSO PEDORRO FEDERAL COM #1
9. API Well No.	30-015-31374
10. Field and Pool, or Exploratory Area	DOG CANYON; STRAWN
11. County or Parish, State	EDDY CO., NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator MARBOB ENERGY CORPORATION
3a. Address PO BOX 227, ARTESIA, NM 88211-0227	3b. Phone No. (include area code) (505) 748-3303
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660 FNL 1650 FEL, SEC. 7-T17S-R28E, UNIT B	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal
			<input type="checkbox"/> Water Shut-Off
			<input type="checkbox"/> Well Integrity
			<input type="checkbox"/> Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

PLUGGED & ABANDONED AS FOLLOWS:

NOFIFIED BLM 24 HRS BEFORE STARTING.

1/28/05 - POOH W/ TBG. RIH & SET CIBP @ 9080'

1/31/05 - RIH W/ TBG. LOAD & CIRC HOLE W/ MUD LAIDEN FLUID. SPOT 25 SX CLASS C CMT ON TOP OF CIBP. POOH W/ TBG.

2/1/05 - RIH W/ CUTTER ON W/L. CUT CSG @ 7885'. WORK 4 1/2" CSG. SDFN.

2/2/05 - RIH W/ JET CUTTER. CUT CSG @ 7800'. POOH W/ 86 JTS 4 1/2" CSG.

2/3/05 - POOH W/ 92 JTS 4 1/2" CSG. TTL 178 JTS. NU BOP. RIH W/ TBG TO 6936'. SDFN.

2/4/05 - RIH W/ TBG TO 7850'. CIRC HOLE W/ MUD LAIDEN FLUID. SPOT 30 SX CLASS C CMT @ 7850'. POOH W/ 50 JTS TBG. SDFN.

2/7/05 - RIH W/ TBG. TAG PLUG @ 7661'. POOH W/ TBG. DIG OUT CELLAR. ND BOP & 7" WELL HEAD. SDFN.

(CONTINUED ON PAGE 2)

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

DIANA J. CANNON

Title
PRODUCTION ANALYST

Signature

Date

FEBRUARY 24, 2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

APPROVED

FEB 25 2005

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

LES BABYAK
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

FORM 3160-5
SUNDRY NOTICES & REPORTS ON WELLS

OSO PEDORRO FEDERAL COM #1
30-015-31374
660 FNL 1650 FEL, SEC. 7-T17S-R28E, UNIT B
EDDY CO., NM

SUBSEQUENT REPORT
PLUG & ABANDON

PAGE 2

2/8/05 - RU CSG JACKS. FREE POINT 7" CSG. FREE @ 8000'. CHGD OUT TBG LINE ON RIG. SDFN.
2/9/05 - RIH W/ JET CUTTER ON W/L. CUT CSG @ 7400'. LD 4 JTS. RD CSG JACKS. SDFN.
2/10/05 - POOH W/ 116 JTS 7" CSG. SDFN.
2/11/05 - POOH W/ 81 JTS 7" CSG (TTL 197 JTS + LANDING JT). NU BOP & 7" CSG HD. RIH W/
TBG TO 7445'. CWI. SDFN.
2/14/05 - SPOT 50 SX CLASS C CMT @ 7" CSG STUB. POOH W/ 60 JTS TBG. WOC. RIH & TAGGED
PLUG @ 7280'. LOAD HOLE W/ MUD LAIDEN FLUID. POOH TO 3220'. CWI. SDFN.
2/15/05 - SPOT 50 SX CLASS C CMT @ 3220' TO 3035'. POOH TO 1559'. WOC 4 HRS. TAGGED
PLUG @ 1442'. POOH TO 477'. SPOT 50 SX CLASS C CMT. POOH W/ TBG. WOC. SDFN.
2/16/05 - RIH & TAGGED PLUG @ 318'. POOH. LD TBG. RIH W/ 60' TBG. CIRC HOLE W/ 20 SX
CLASS C CMT TO SURFACE. CUT OFF WELL HEAD. INSTALL DRY HOLE MARKER. CUT
OFF ANCHORS. RD.