Form 3160-5 (April 2004)

## N.M. Oil Cons. DIV-Dist. 2

UNITED STATES 1301 W. Grand Avenue DEPARTMENT OF THE INTERPESIA, NM 882 10 BUREAU OF LAND MANAGEMENT

DOKLA	5. Lease Senal No.				
SUNDRY NOTIC	NN	M-8431			
Do not use this form abandoned well. Use	6 If Indian, Allotte	e or Tribe Name			
SUBMIT IN TRIPLICA	7. If Unit or CA/Agreement, Name and/or No.				
Oil Well 🗆 4 Gas We	8. Well Name and No.				
2. Name of Operator Armstrong Energy	Ross Federal #5  9. API Well No. 30-005-63621				
3a. Address					
P.O. Box 1973, Roswell, NM 88202-1973 575-625-2:			22	10 Field and Pool, or Exploratory Area Foor Ranch; Wolfcamp	
4. Location of Well (Footage, Sec., T, R, M., o	11. County or Parish, State				
660' FSL & 660' FEL, Sec 7, T1	Chaves, NM				
<del></del>	UL P	INDICATE N	IATURE OF NOTICE. R	EPORT OR OTH	ER DATA
TYPE OF SUBMISSION	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, SUBMISSION TYPE OF ACTION				
4 Notice of Intent Al Subsequent Report Co	cidize  Iter Casing asing Repair nange Plans Convert to Injection	Deepen Fracture Trea New Constru Plug and Aba Plug Back	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Tion Recomplete Other		
testing has been completed. Final Abando determined that the site is ready for final in Request T.A. status for the Ross Fe	nspection.)				
Open valve on 8-5/8" x 5-1/2" Annu			131.7	to witness te	
TOC @ 3995', CBL Perforations: 5030'-5034', CIBP @ Packer @ 4931'	) 5230' w/ 35' cement				,
ccepted for record	CD (I		APPROVED FOR 3 MONTH PERIOD		
8/17/11	AUG 9	2011	Ending	OCT 27 2011	
	NMOCD A	RTESIA			
14. I hereby certify that the foregoing is t Name (Printed/Typed)					
Bruce A. Stubbs		-	Γitle Vice President - Oper	rations	
Signature / Substitute			Date 7-18-11		
THIS	SPACE FOR	FEDERAL	OR STATE OFFICE	USE	
Approved by /S/ DAVID Conditions of approval, if any, are attached. certify that the applicant holds legal or equita		does not warrant		ENGINEER Date	JUL 27 2011
which would entitle the applicant to conduct	operations thereon.	***************************************	Office	to make to any divi-	etmant are account of the I last
Title 18 U.S.C Section 1001 and Title 43 U.S.C States any false, fictitious or fraudulent states	Section 1212, make it a nents or representations	as to any matter	cison knowingly and willfully within its jurisdiction.	to make to any depai	unent or agency of the Unit

(Instructions on page 2)

QUEEN 380' PENROSE 450' GRAYBURG 621' SAN ANDRES 883'	12 1/4" HOLE 8 5/8"-24 #/FT., J-5 300 SX. CLASS "C"			
GLORIETTA 2002'		RMSTRONG ENERGY CORP.  ROSS FEDERAL #5 SEC. 7-T10S-R26E 660' FSL & 660' FEL CHAVES COUNTY, NM  SPUD DATE: 11-4-03 API No.: 30-005-63621		
	7 7/8" HOLE			
TUBB 3499'				
ABO 4244'	TOC @ 3995'			
	ABO 4609-25', 16%	POROSITY		
WOLFCAMP 4924'	5030-5034'	5230' CIBP W/ 35' CEMENT		
PENN 5480' STRAWN 5617' GRANITE WASH 5658	5 1/2"=15.5 #/FT., 310 SX CLASS "C"	J-55, 8 RD, LT&C @ 5740'		

## BUREAU OF LAND MANAGEMENT

Roswell Field Office
2909 West Second Street
Roswell, New Mexico 88201
575-627-0272

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, call (575) 627-0205 or after office hours call (575) 420-2832.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)