Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

Rec'd 05/	18/2020 - NMOCD
	FORM APPROVED
	OMB NO. 1004-0137
	Expires: January 31, 201
	5 Lance Carial No.

	DEVITOR LAND MANA				Expires: Ja	nuary 31, 2018	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No. NMNM112931		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or	Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No NMNM137594		
Type of Well Oil Well					8. Well Name and No. BIG SINKS 1 W1AP FED COM 3H		
Name of Operator					9. API Well No. 30-015-46974-00-X1		
3a. Address P O BOX 5270 HOBBS, NM 88241	, 0	3b. Phone No. (include area code) Ph: 575-393-5905			10. Field and Pool or Exploratory Area JENNINGS-BONE SPRING, WES		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	11. County or Parish, State			State	
Sec 1 T26S R31E NWNE 205FNL 1600FEL 32.078968 N Lat, 103.728226 W Lon					EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
➤ Notice of Intent	☐ Acidize	☐ Dee	epen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
_	Alter Casing	□ Нус	draulic Fracturing	☐ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ Nev	w Construction	☐ Recomp	olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plu	g and Abandon	☐ Tempor	arily Abandon		
	☐ Convert to Injection	☐ Plu	g Back	☐ Water D	Disposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit Change casing from 7" to 7 5/program. See attachments for casing te	ally or recomplete horizontally, it will be performed or provide operations. If the operation resondonment Notices must be filed in all inspection. 8" 39# P110 FJ & cement	give subsurface the Bond No. o sults in a multip ed only after all t design as de	locations and measur n file with BLM/BIA le completion or reco- requirements, includi	red and true ve Required sub mpletion in a r ng reclamation	ertical depths of all pertine osequent reports must be for new interval, a Form 3160	ent markers and zones. filed within 30 days 0-4 must be filed once	
Please contact Levi Jackson v	vith any questions.	ig program.	Acce	pted 05/18	8/2020 - KMS NN	MOCD	
14. I hereby certify that the foregoing is	Electronic Submission #5	RNE OIL COM	PANY. sent to the	Carlsbad	-		
Name(Printed/Typed) LEVI JAC	KSON		Title ENGINE	ER			
Signature (Electronic S	Submission)		Date 05/14/20)20			
	THIS SPACE FO	R FEDERA	AL OR STATE (OFFICE U	SE		
Approved_By_OLABODE_AJIBOLA			TitlePETROLE	JM ENGINE	EER	Date 05/17/2	
which would entitle the applicant to condu	act operations thereon.	subject tease	Office Carlsbad				
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any pe	erson knowingly and	willfully to ma	ike to any department or a	igency of the United	

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Revisions to Operator-Submitted EC Data for Sundry Notice #515419

Operator Submitted

BLM Revised (AFMSS)

Sundry Type: **CSG-ALTER**

NOI

CSG-ALTER NOI NMNM112931

NMNM112931 Lease:

NMNM137594 (NMNM137594)

Agreement:

Operator:

MEWBOURNE OIL COMPANY PO BOX 5270 HOBBS, NM 88241 Ph: 575-393-5905

MEWBOURNE OIL COMPANY P O BOX 5270 HOBBS, NM 88241 Ph: 575.393.5905

JACKIE LATHAN

Admin Contact:

JACKIE LATHAN AUTHORIZED REPRESENTATIVE E-Mail: jlathan@mewbourne.com

REGULATORY E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905

Tech Contact:

LEVI JACKSON ENGINEER

Ph: 575-393-5905

Ph: 575-393-5905

LEVI JACKSON ENGINEER

E-Mail: ljackson@mewbourne.com

E-Mail: Ijackson@mewbourne.com

Ph: 575-393-5905

Location:

State: NM County: EDDY NM EDDY

JENNINGS-BONE SPRING, WEST Field/Pool: PURPLE SAGE, WOLFCAMP

Well/Facility:

BIG SINKS 1 W1AP FED COM 3H Sec 1 T26S R31E Mer NMP NWNE 205FNL 1600FEL

BIG SINKS 1 W1AP FED COM 3H Sec 1 T26S R31E NWNE 205FNL 1600FEL 32.078968 N Lat, 103.728226 W Lon

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: | Mewbourne Oil Company

LEASE NO.: | NMNM112931

WELL NAME & NO.: | BIG SINKS 1 W1AP FED COM #3H

SURFACE HOLE FOOTAGE: 205'/N & 1600'/E **BOTTOM HOLE FOOTAGE** 330'/S & 1000'/E

LOCATION: Section 1, T.26 S., R.31 E., NMP

COUNTY: Eddy County, New Mexico

COA

H2S	○ Yes	© No	
Potash	None	C Secretary	○ R-111-P
Cave/Karst Potential	C Low	Medium	O High
Cave/Karst Potential	Critical		
Variance	○ None	Flex Hose	○ Other
Wellhead	Conventional	Multibowl	○ Both
Other	☐ 4 String Area	Capitan Reef	□WIPP
Other	Fluid Filled	☐ Cement Squeeze	☐ Pilot Hole
Special Requirements	☐ Water Disposal	▼ COM	□ Unit

All Previous COAs Still Apply.

A. CASING

Casing Design:

- 1. The 13-3/8 inch surface casing shall be set at approximately 1225 feet (a minimum of 70 feet (Eddy County) into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job will be a minimum of **8** hours or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours

- after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The 9-5/8 inch intermediate casing shall be set at approximately 4250 feet. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
 - Cement to surface. If cement does not circulate see B.1.a, c-d above.
 Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.
 Excess cement calculates to 17%, additional cement might be required.
 - ❖ In Medium Cave/Karst Areas if cement does not circulate to surface on the first two casing strings, the cement on the 3rd casing string must come to surface.
- 3. The minimum required fill of cement behind the 7-5/8 inch production casing is:

Option 1 (Single Stage):

Cement should tie-back at least 200 feet into previous casing string.
 Operator shall provide method of verification.
 Excess cement calculates to 1%, additional cement might be required.

Option 2:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

- b. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.
- c. Second stage above DV tool:
 - Cement should tie-back at least **200 feet** into previous casing string. Operator shall provide method of verification.
- 4. The minimum required fill of cement behind the 4-1/2 inch production liner is:

• Cement should tie-back 100 feet into the previous casing. Operator shall provide method of verification.

B. PRESSURE CONTROL

1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).'

2.

Option 1:

- a. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 10,000 (10M) psi. Variance is approved to use a 5000 (5M) Annular which shall be tested to 5000 (5M) psi.
- b. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the intermediate casing shoe shall be 10,000 (10M) psi. Variance is approved to use a 5000 (5M) Annular which shall be tested to 5000 (5M) psi.

Option 2:

- 1. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 10,000 (10M) psi. Variance is approved to use a 5000 (5M) Annular which shall be tested to 5000 (5M) psi.
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
 - e. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.

C. SPECIAL REQUIREMENT (S)

Communitization Agreement

- The operator will submit a Communitization Agreement to the Carlsbad Field Office, 620 E Greene St. Carlsbad, New Mexico 88220, at least 90 days before the anticipated date of first production from a well subject to a spacing order issued by the New Mexico Oil Conservation Division. The Communitization Agreement will include the signatures of all working interest owners in all Federal and Indian leases subject to the Communitization Agreement (i.e., operating rights owners and lessees of record), or certification that the operator has obtained the written signatures of all such owners and will make those signatures available to the BLM immediately upon request.
- If the operator does not comply with this condition of approval, the BLM may take enforcement actions that include, but are not limited to, those specified in 43 CFR 3163.1.
- In addition, the well sign shall include the surface and bottom hole lease numbers. When the Communitization Agreement number is known, it shall also be on the sign.

OTA05172020