Submit 1 Copy To Appropriate District		۰ <i>۲</i>	OCD – R	REC'D 9/15/2020	E G 102			
Office	State of New Mexico Energy, Minerals and Natural Resources				Form C-103 Revised July 18, 2013			
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals ar	ia Natural	WELL API NO					
<u>District II</u> - (575) 748-1283	OIL CONSERVATION DIVISION			30-01533453				
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.			5. Indicate Ty				
1000 Rio Brazos Rd., Aztec, NM 87410					STATE r FEE 6. State Oil & Gas Lease No.			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	District IV - (505) 476-3460 Santa Fe, NM 87505 220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505				Gas Lease no.			
87505 SUNDRY NOT	308713	e or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PROPO		e or Unit Agreement Name						
DIFFERENT RESERVOIR. USE "APPLI	DAD STATE							
PROPOSALS.) 1. Type of Well: Oil Well	8. Well Number 39							
2. Name of Operator	9. OGRID Number							
Apache Corporation	873							
3. Address of Operator	10. Pool name or Wildcat ARTESIA GLORIETA-YESO							
303 Veterans Airpark Lane, Suite 1				ARTESIA GLU	RIETA-TESU			
4. Well Location Unit Letter_C:	990feet from the		$_$ line and $\underline{179}$	92 foot	from the <u>W</u> line			
Section 35	Township 17S	Range		NMPM	County EDDY			
Section 35	11. Elevation (Show whet							
	3684		<i>D</i> , 111, 011, <i>C</i>	•/				
12. Check	Appropriate Box to Indi	cate Natur	re of Notice,	, Report or Oth	er Data			
		1	CLIE					
	NTENTION TO: PLUG AND ABANDON		SUE EMEDIAL WOF					
TEMPORARILY ABANDON	CHANGE PLANS							
PULL OR ALTER CASING	MULTIPLE COMPL		SING/CEMEN					
		_						
CLOSED-LOOP SYSTEM		_			_			
OTHER:		1	THER:	1				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
proposed completion or rec		FINIMAC. I	or multiple CC	mpletions. Attac	ii wendore diagram or			
APACHE REQUEST APPROVAL TO	•							
SET CIBP @3800+35'OF CEMENT (OVER PERFS 3824-4155							
WBD AND PROCEDURES INCLUDE	D							
		_						
Spud Date: 7/13/2004	Rig Rel	lease Date:						
			L					
Therefore earlier that the information	ah arra in turn and a complete	4 a 4 b a 1 a a 4 a	£ 1	a and hall of				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
n··· i nu								
SIGNATURE alicia fulto	nTITLE	Sr. Staff Re	eg Analyst		DATE 6/9/2020			
		11 2	icia fulton@anac	checorp com	DUONE (422) 919 1099			
Type or print name Alicia Fulton For State Use Only	E-mail	address:	icia.fulton@apac		PHONE: (432) 818-1088			
	\wedge //	<u>^</u>	unline n	^				
APPROVED BY:	Smoleh TITLE	Con	ipliance off		DATE 9-29-2020			
Conditions of Approval (if any):								



Well name:	DAD St	ate 39						
API Number:	30-015-33453							
County, State:	Eddy, NIV	1						
Legals:	SEC-35	TWP-17S	RGE-28E					
Depths:	4370	MD	4355	PBTD				
Producing Interval	3824' - 41	55' (Yeso)						
CSG	OD	Wt/Ft	Cap (bbl/ft)	Тор	Set @			
Surface	8.625"	24.0#	0.0636	0'	501			
Production	5.500"	17#	0.0232	0'	4370			
Engineer:	David Cummings		432-818-1845 (o)		davidr.cummings@apachecorp.com			
Assistant Foreman:	David Peo	David Pedroza 575-910-3283		3 (c)	<pre>david.pedroza@apachecorp.com</pre>			
Production Foreman	Javier Be	rdoza	575-441-5755 (c)		javier.berdoza@apachecorp.com			

What's New:

1) Set CIBP, cap w/ cement, and test casing integrity

2) **TA well**

WELL HISTORY

The well is currently SI. Last tested at 2 BOPD x 10 BWPD x 4 MCFD, with last production reported on 4/2019.

WORKOVER SUMMARY:

TA well. This well was producing from the Yeso formation. It is recommended that this well be TA'd for evaluation of uphole potential requiring geological and engineering review. Without further analysis, valuable resources may be forfeited by prematurely plugging the well.

PROCEDURE:

- 1. MIRU wireline, RIH w/ gauge ring, POOH, RIH w/ CIBP, set @ 3,800 (top of perfs 3,824'), POOH.
- 2. RIH w/ dump bailer and spot 4-5 sxs of cement (35') on top of CIBP, POOH.
- 3. RIH and tag TOC. Record depth of TOC. RDMO WL.
- 4. Circulate hole w/ packer fluid.
- 5. Test casing to 500 psi for 30 minutes (Please contact NMOCD 24 hours in advance). Note: If casing does not test, TA operations will be postponed and the well evaluated for P&A.
- 6. TA well



