

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 87240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-21777
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Nash Unit
8. Well Number 004 SWD
9. OGRID Number 005380
10. Pool name or Wildcat SWD; DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD	7. Lease Name or Unit Agreement Name: Nash Unit
2. Name of Operator XTO Energy, Inc.	8. Well Number 004 SWD
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701	9. OGRID Number 005380
4. Well Location Unit Letter A : 990 feet from the North line and 330 feet from the West line Section 13 Township 23S Range 29E NMPM County Eddy	10. Pool name or Wildcat SWD; DELAWARE
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☐
CASING/CEMENT JOB ☐


OTHER: **Re-set packer & ran chart** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/15/11-12/19/11: MIRU PU. ND WH. NU BOP. Release packer. POOH w/2 7/8" IPC tbq. and packer.
RIH w/5-1/2" packer.
Set packer at 3159'. ND BOP. NU WH.
Press TCA to 350 psig for 30 min on chart recorder. Acid w/2000g 15% HCL Acid RWTT.

Spud Date:

Rig Release Date:



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Ann Perales* TITLE Regulatory Analyst DATE 01/06/2012

Type or print name Ann Perales E-mail address: ann_perales@xtoenergy.com PHONE 432.620.4336

For State Use Only

APPROVED BY *Dr. R. Spewer* TITLE Dr. R. Spewer DATE 01/24/12

Conditions of Approval (if any):

