Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
Energy, Minerals and Natural Resources	May 27, 2004
1625 N French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-38323
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 R10 Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM	o. State Off & Gas Lease No.
87505	7 1 2 1 2 1 2 1 2 1 2 1 2 1 2 2 2 2 2 2
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Mayaro 22 State
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well	003
2. Name of Operator	9. OGRID Number
Cimarex Energy Co. of Colorado	162683
3. Address of Operator	10. Pool name or Wildcat
600 N. Marienfeld, Ste. 600; Midland, TX 79701	Empire; Glorieta-Yeso
4. Well Location	Limpire, diorieta-reso
	feet from the East line
Section 22 Township 175 Range 28E NMPM	County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3584 GR	
Pit or Below-grade Tank Application or Closure	778 N. H.
Pit type Depth to Groundwater Distance from nearest fresh water well	Distance from nearest surface water
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON	RILLING OPNS P AND A
TEMPORARILY ABANDON	RILLING OPNS P AND A
TEMPORARILY ABANDON	RILLING OPNS P AND A NT JOB Drilling & Completion
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g	RILLING OPNS P AND A Drilling & Completion ve pertinent dates, including estimated date of
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTO OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and good starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we have a starting any proposed work.	RILLING OPNS P AND A Drilling & Completion ve pertinent dates, including estimated date of
TEMPORARILY ABANDON	RILLING OPNS P AND A Drilling & Completion ve pertinent dates, including estimated date of
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and government and proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 15. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 16. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 17. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 18. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 18. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 19. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 19. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion.	RILLING OPNS P AND A Drilling & Completion Sive pertinent dates, including estimated date of wellbore diagram of proposed completion or
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gostarting any proposed work). SEE RULE 1103. For Multiple Completions: Attach was recompletion. 15. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach was recompletion. 16. Drilling: 10-24-11 Spud well @12:00 pm. TD 14-3/4" hole @ 378'. RIH w/ 9-5/8", 36#, J55 STC csg & set @ 378'.	RILLING OPNS P AND A Drilling & Completion Sive pertinent dates, including estimated date of wellbore diagram of proposed completion or
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and government and proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 15. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 16. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 17. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 18. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 19. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion.	RILLING OPNS P AND A Drilling & Completion Sive pertinent dates, including estimated date of wellbore diagram of proposed completion or Cmt w/ Lead: 200 sx Class C; tail: 200 sx Class C. Circ
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gostarting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. Drilling: 10-24-11 Spud well @12:00 pm. TD 14-3/4" hole @ 378'. RIH w/ 9-5/8", 36#, J55 STC csg & set @ 378'. 94 sx to pit. 10-27-11 TD 7-7/8" hole @ 4902'. Logging. 10-28-11 RIH w/ 5-1/2", L80, LTC csg & set @ 4902'. Cmt w/ Lead: 300 sx Class C 50/50; Tail w/ 400 sx Class.	RILLING OPNS P AND A Drilling & Completion Sive pertinent dates, including estimated date of wellbore diagram of proposed completion or Cmt w/ Lead: 200 sx Class C; tail: 200 sx Class C. Circ
TEMPORARILY ABANDON	RILLING OPNS P AND A Drilling & Completion Sive pertinent dates, including estimated date of wellbore diagram of proposed completion or Cmt w/ Lead: 200 sx Class C; tail: 200 sx Class C. Circ
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gostarting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. Drilling: 10-24-11 Spud well @12:00 pm. TD 14-3/4" hole @ 378'. RIH w/ 9-5/8", 36#, J55 STC csg & set @ 378'. 94 sx to pit. 10-27-11 TD 7-7/8" hole @ 4902'. Logging. 10-28-11 RIH w/ 5-1/2", L80, LTC csg & set @ 4902'. Cmt w/ Lead: 300 sx Class C 50/50; Tail w/ 400 sx Class.	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gong starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. Drilling: 10-24-11 Spud well @12:00 pm. TD 14-3/4" hole @ 378'. RIH w/ 9-5/8", 36#, J55 STC csg & set @ 378'. 94 sx to pit. 10-27-11 TD 7-7/8" hole @ 4902'. Logging. 10-28-11 RIH w/ 5-1/2", L80, LTC csg & set @ 4902'. Cmt w/ Lead: 300 sx Class C 50/50; Tail w/ 400 sx Class. Completion: 11-6-11MIRU. Perf Blinebry @ 3970-4535' w/ 1 SPF, 28 holes. WO frac. 11-18-11 Frac Blinebry w/ 1,107,211 slickwater & 398,875# sd. RIH w/ CBP & set @ 3945'. Perf Paddock slickwater & 540,044# sd.	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Pand Pand Pand Pand Pand Pand Pand Pand
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Part wellbore diagram of proposed completion or Cmt w/ Lead: 200 sx Class C; tail: 200 sx Class C. Circ Pass C Starbond. Circ 102 sx to pit. Release @ 3522-3913' w/ 4 SPF, 52 holes. Frac w/ 1,190,385
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMESTOTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. Drilling:	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Part wellbore diagram of proposed completion or Cmt w/ Lead: 200 sx Class C; tail: 200 sx Class C. Circ Pass C Starbond. Circ 102 sx to pit. Release @ 3522-3913' w/ 4 SPF, 52 holes. Frac w/ 1,190,385
TEMPORARILY ABANDON	RILLING OPNS P AND A
TEMPORARILY ABANDON	RILLING OPNS PAND A Drilling & Completion Drilling & Completion Drilling & Completion Drilling & Completion or Part wellbore diagram of proposed completion or Cmt w/ Lead: 200 sx Class C; tail: 200 sx Class C. Circ Pass C Starbond. Circ 102 sx to pit. Release @ 3522-3913' w/ 4 SPF, 52 holes. Frac w/ 1,190,385
TEMPORARILY ABANDON	RILLING OPNS