Hnergy Miners	of New Mexico als and Natural Resources	Form C-103 June 19, 2008		
1625 N. French Dr., Hobbs, NM 88240 WELL API NO.		WELL API NO.		
District II 1301 W. Grand Avc., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-015-39010 5. Indicate Type of Lease		
District III 1000 Rep Brozos Rd Aztec NM 87410 1220 South St. Francis Dr.		STATE FEE		
District IV Santa	Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505		B0-9603-0024		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (F PROPOSALS.)		Empire Abo Unit		
1. Type of Well: ☑ Oil Well ☐ Gas Well ☐ Other:	DECEIVED	8. Well Number 418		
2. Name of Operator	UECTIAFD	9. OGRID Number		
Apache Corporation 3. Address of Operator	MAR 1 2 2012	873 10. Pool name or Wildcat		
303 Veterans Airpark Lane, Suite 3000 Midland, TX 7970)ā	Empire; Abo (22040)		
4. Well Location NMOCD ARTESIA				
Unit Letter B: 1110 feet from the North line and 1625 feet from the East line				
Section 16 Township	18S Range 27E	NMPM County Eddy		
	whether DR, RKB, RT, GR, etc.,)		
3458' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐				
TEMPORARILY ABANDON				
PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE	☐ CASING/CEMEN	T JOB 📋		
DOWNTIOLE COMMINGEE				
OTHER: OTHER: COMPLETION 🗵				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
of starting any proposed work) SEE RULE 1103	y cor willinger ombiellons. At	or recompletion.		
	s. For Multiple Completions: Al	nach wendore diagram of proposed completion		
	or rot within the Completions: At	nach wendore diagram of proposed completion		
or recompletion. Apache completed this well, as follows:		nach wendore diagram of proposed completion		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg.	9'; CO to PBTD @ 6072'.			
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591	9'; CO to PBTD @ 6072'.			
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg.	9'; CO to PBTD @ 6072'.			
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super ipool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15%		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid.		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'.) holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid.		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super spool. equip; SN @ 5996'. ig Release Date: 12/02/2011 plete to the best of my knowledg	holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid.		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP Spud Date: 11/19/2011 Ri	P'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'. ig Release Date: 12/02/2011 plete to the best of my knowledg	holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid. e and belief. DATE 03/06/2012		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP Spud Date: 11/19/2011 R: Type or print name Reesa Holland E	9'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super spool. equip; SN @ 5996'. ig Release Date: 12/02/2011 plete to the best of my knowledg	holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid. e and belief. DATE 03/06/2012		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP Spud Date: 11/19/2011 R: Type or print name Reesa Holland E For State Use Only	P'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'. ig Release Date: 12/02/2011 plete to the best of my knowledg TTLE Sr. Staff Engr Tech E-mail address: Reesa.Holland@apar	holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid. e and belief. DATE 03/06/2012		
or recompletion. Apache completed this well, as follows: 12/14/2011 MIRUSU Tag up on & DO DV tool @ 2979 12/28/2011 MIRUSU POOH w/tbg. 12/29/2011 Log - TOC @ 200'. Perf Upper Abo @ 591 NEFE acid. 12/30/2011 Swab POOH & LD tbg & pkr. 01/11/2012 Frac Abo w/60,000 gal 15# gel &12,500# 1 01/16/2012 ND & NU wellhead. ND frac valve & frac s 01/17/2012 CO sand to PBTD @ 6072' & RIH w/prod e 01/18/2012 RIH w/pump & rods. 01/20/2012 Set 640 Pumping Unit; install electric; POP Spud Date: 11/19/2011 R: Type or print name Reesa Holland E For State Use Only	P'; CO to PBTD @ 6072'. 12-18', 38-46', 90-96' w/4 SPF, 80 100 Mesh & 55,000# 40/70 Super pool. equip; SN @ 5996'. ig Release Date: 12/02/2011 plete to the best of my knowledg	holes. Acidize Upper Abo w/2374 gal 15% LC sand, flush w/5681 gal gel fluid. e and belief. DATE 03/06/2012		