Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N French Dr., Hobbs, NM 88240	•		WELL API NO.
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-60161
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE V FEE
1220 S. St. Francis Dr., Santa Fe, NM	2		6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)			Double L Queen Unit
1. Type of Well:			
Oil Well Gas Well X Other			
2. Name of Operator	RECEIVED		8. Well No.
Tipton Oil & Gas Acquisitions, In	IC.	+ VED	003
3. Address of Operator	IAN 2	1 2005	9. Pool name or Wildcat
P.O. Box 1234 Lovington NM 8	38260 OCLEAN		Double L Queen; Assoc.
4. Well Location			200002 20000
Unit Letter C	: feet from the	line and	feet from theline
Section 25 Township 14S Range 29E NMPM Chaves, County			
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	J PLUG AND ABANDON LJ	REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. PLUG AND
PULL OR ALTER CASING] MULTIPLE	CASING TEST A	ABANDONMENT
PULL OR ALTER CASING L	MULTIPLE COMPLETION	CEMENT JOB	ND
	COM EL TON	OEMENT GOD	
OTHER: CONVERT INJECTO	OR TO PRODUCER	OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation.			
Release tbg. from permanent packer. POOH with tbg. GIH with work string and bailer. Knock packer to bottom of hole.			
POOH with work string and bailer. Run new rods, pump, and tbg. Set pumping unit and commence production.			
NOT TO CONVERT - WOLK NOT DONE & PLUMSE FUX TYPE TO "I!" THX -			
A CONTRACTOR OF THE PARTY OF TH			
PLUASE FUX TYPE TO I.			
THX-			
PriHARDI			
ReithAco 12/20/11			
* INSPECTION VERLEID			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Deliver Miles TITLE Agent for Clay Tipton, Principal DATE 1/20/05			
Type or print name Clay Tipton, Principal Telephone No. 505-631-4121			
(This space for State use)			
APPPROVED BY TITLE Suid So D DEEB. 1 2005			
Conditions of approval, if any:			