Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103 Revised August 1, 2011
District I – (575) 393-6161			Resources	WELL API NO.
District II – (575) 748-1283	1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-015-03161
811 S. First St., Artesia, NM 88210	t St., Artesia, NM 88210 OIL CONSERVATION DIVISION		į	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	trict III - (505) 334-6178 1220 South St. Francis Dr.			STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 8/303			6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-7596	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				PODINGON GTATE
PROPOSALS.)				ROBINSON STATE 8. Well Number 5
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator				9. OGRID Number 274841
Alamo Permian Resources. LLC 3. Address of Operator				10. Pool name or Wildcat
415 W. Wall Street, Suite 500, Midland, TX 79701			GRAYBURG JACKSON;SR-Q-G-SA	
4. Well Location				
Unit Letter D: 330 feet from the N line and 330 feet from the W line				
Section 27 Township 17S Range 29E NMPM County EDDY				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12 Charle Appropriate Pay to Indicate Nature of Notice Penart or Other Data				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
				SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				_
TEMPORARILY ABANDON			COMMENCE DRIL	
PULL OR ALTER CASING	MULTIPLE COMPL [CASING/CEMENT	JOB 🗆
DOWNHOLE COMMINGLE				
OTHER:			OTHER: RETU ⊠	JRN TO PRODUCTION
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
2-21-12				
MIRU PU. Open well up and pulled rods and pump. ND WH NU BOP. TIH with 2 3/8" tubing to tag bottom and POOH with tubing (1st				
joint had a HIT). Secure well and SDFN.				
2 22 12				
2-22-12 Open well up and TIH with 4 3/4" bit and 5 1/2" casing scrapper. POOH with bit and scrapper and TIH with bailer to clean out 60 ft. of fill.				
Hydro test tubing in the hole, Secure well and SDFN.				
2-23-12 2-23-12				
ND BOP and NU WH. TIH with new pump and rods, HWO, RD pulling unit and clean location.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE TITLE Regulatory Affairs Coordinator DATE 03/06/2012				
Type or print name				
ADDROVED BY SKI WILL THE DISTRICT BATE OSLISTONS				
APPROVED BY: OF TITLE OF TOPOWOR DATE 03/15/20 ID Conditions of Approval (if any):				
Conditions of Approval (If any):				