l l	
Submit One Copy To Appropriate District 2012 State of New Mexico	Form C-103
trict I Energy, Minerals and Natural R	esources March 18, 2009
.25 N. French Dr., Hobby CO ARTESIA	WELL API NO. 30-015-23960
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIV	5 Indicate Type of Lease
District III 1220 South St. Francis I 1000 Rio Brazos Rd, Aztec, NM 87410	Or. STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BA DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUG	THE TREE THE TREE THE TREE THE TREE THE TREE TRE
PROPOSALS.)	8. Well Number 55
1. Type of Well: Oil Well Gas Well X Other PA 2. Name of Operator	9. OGRID Number
Yates Petroleum Corporation	025575
3. Address of Operator	10. Pool name or Wildcat
105 S. 4 th Street, Artesia, NM 88210	Dagger Draw; Upper Penn, North
4. Well Location	
Unit Letter <u>C</u> : 660 feet from the <u>North</u> line and <u>1980</u> feet from the <u>North</u> line and the <u>North line and the line and</u>	
Section 19 Township 19S Range 25E NMPM Eddy	County
11. Elevation (Show whether DR, RKB 3588' GR	, RT, GR, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report	t or Other Data
	tor other bata
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	MEDIAL WORK ☐ ALTERING CASING ☐ 1 MMENCE DRILLING OPNS.☐ P AND A ☐
	SING/CEMENT JOB
SEE SITTLE COMME	Sincipal Market Good
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
A steel marker at least 4" in diameter and at least 4' above ground level.	has been set in concrete. It shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N	UMBER, QUARTER/QUARTER LOCATION OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. AH IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment.	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR ntour and has been cleared of all junk, trash, flow lines and
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR L. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location.	UMBER, QUARTER/QUARTER LOCATION OR AFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases have	UMBER, QUARTER/QUARTER LOCATION OR AFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location.	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed have been removed. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15.	UMBER, QUARTER/QUARTER LOCATION OR NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines.	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have seen removed. All fluids have been removed from non-
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines.	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have seen removed. All fluids have been removed from non-
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15.	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR E. Intour and has been cleared of all junk, trash, flow lines and set below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have seen removed. All fluids have been removed from non-
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines. Metal battery or location will complete reclamation to When all work has been completed, return this form to the appropriate District	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have as 1.35.10 NMAC. All fluids have been removed from non-unitary last active well at battery is plugged, at office to schedule an inspection.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines. The battery or location will complete reclamation to When all work has been completed, return this form to the appropriate District	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed have been removed. (Poured onsite concrete bases do not have as active well at battery is plugged, at office to schedule an inspection. DATE 3/2012
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines. The battery or location will complete reclamation to When all work has been completed, return this form to the appropriate District	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed have been removed. (Poured onsite concrete bases do not have as active well at battery is plugged, at office to schedule an inspection. DATE 3/2012
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines. The battery or location will complete reclamation to When all work has been completed, return this form to the appropriate District	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed have been removed. (Poured onsite concrete bases do not have as active well at battery is plugged, at office to schedule an inspection. DATE 3/2012
OPERATOR NAME, LEASE NAME, WELL NUMBER, API N UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All IN PERMANENTLY STAMPED ON THE MARKER'S SURFACE The location has been leveled as nearly as possible to original ground co other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two fe If this is a one-well lease or last remaining well on lease, the battery and OCD rules and the terms of the Operator's pit permit and closure plan. All fl from lease and well location. All metal bolts and other materials have been removed. Portable bases ha to be removed.) All other environmental concerns have been addressed as per OCD rules Pipelines and flow lines have been abandoned in accordance with 19.15. retrieved flow lines and pipelines. The battery or location will complete reclamation to When all work has been completed, return this form to the appropriate District	umber, Quarter/Quarter Location or NFORMATION HAS BEEN WELDED OR intour and has been cleared of all junk, trash, flow lines and beet below ground level. pit location(s) have been remediated in compliance with ow lines, production equipment and junk have been removed are been removed. (Poured onsite concrete bases do not have as 1.35.10 NMAC. All fluids have been removed from non-unitary last active well at battery is plugged, at office to schedule an inspection.